

Date Inspection Started: 03 09 25
 Date Inspection Completed: 11 09 25
 Inspection Expiry Date: 30 09 26

Station Number: A153102 Station Name: VIRDEN TRUCK AND
 Mechanic Number: 11016216 Mechanic Signature: [Signature]
 City: (204) 748-6887 Station Phone Number

Vehicle Owner: BOYES CONTRACTING
 Address: BOX 63 City: HARTNEY MB Postal Code: ROM 0X0 Phone:

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: C6U582 Prov: MB NSC #: MB 1203540 Odometer Reading: 779,692 Odom. Type: km mi

Vehicle Identification Number: 3W4KD1D49XG7F9311929 Make: KW Model: T800 Year: 07 Unit #: 7
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)
 4C FRONT SUSPENSION BUSHING LOOSE

Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
 19E SPEED SENSOR OUT OF ADJUSTMENT.
 14A BRAKE CHAMBER INTERNAL LEAK

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)
 13B WINDSHIELD CRACK

Section 9 - Tire & Wheel: Defects (if any)

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke		
	L	R	L	R	L	R	
1	.75	.76	16.51	16.52	1	1	
2	.65	.60	16.53	16.54	1.25	1.25	
3	.65	.73	16.53	16.51	1.25	1.25	
4							
5							
Final Measurement						INCHES	

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	15	15			100	100		
2	19	19			100	100		
3	12	12			100	100		
4								
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-585-0920

DEC 11 2007

Manitoba
A976936