04080362

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

NO6-6

Vehicle Safety
Box 45064 Regent Postal Outl
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL NOT TO BE REMOVED WITHOUT PERMIT

Manitoba C071921

	DAY	MO.	YR.
Date Inspection Started	31	03	26
Date Inspection Completed	02	04	26
Inspection Expiry Date	30	04	27

Station Number: A1231 — Station Name: MARION Trucking LTD WPG — City

Mechanic Number: M5054 — Mechanic Signature — Station Phone Number: 204-237-3171

Vehicle Owner: MARION Trucking LTD

Address: 578 McTavish St WPG — City: MB — Province: R2J0E6 — Postal Code: 237-3171 — Phone

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: NOT — Prov. — NSC # — Odometer Reading: 678330 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 5KKHALCV76PV42851 — Make: Western Star — Model: 4900 — Year: 06 — Unit #

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

X Truck — GVWR 24,216 KGS — ___ Truck Tractor — ___ Trailer — ___ Semi-Trailer — ___ Bus — ___ School Bus — ___ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) — Defects (if any) / Circle Brake Type: #5 Axle #1 RS Axles #2 BS Axles #3 BS Wheel seal Damp.
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) #13 3 ID Lite on Rear Missing @ 6700 Chassis. When Safty.
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) #13 C RS windshield cracked.
X	X	**Section 9 - Tire & Wheel:** Defects (if any) #4A CORRECTED TIRES PSI.
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining MM L	Lining MM R	Drum/Rotor L	Drum/Rotor R	Stroke CM L	Stroke CM R
1	18	17	16.546	16.550	3½	3½
2	11	21	16.532	16.530	4	4
3	21	14	16.535	16.506	4	4
4						
5						
	Final Measurement					

Axle	Tread Depth MM Initial L		Initial R		Corrected L		Corrected R		Air Pressure PSI Initial L		Initial R		Corrected L		Corrected R	
1	7			7				7	100			100	110			110
2	17	17	18	18	16	15	15	16	90	90	90	90	110	110	110	110
3	16	15	15	16	17	17	18	18	90	90	90	90	110	110	110	110
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION