



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

**A311579**

Station #: 70264

Station Name: Golden West Trailer & Equipment

Technician #: 81335

Technician Name: George Carle

Signing Officer #: 91784

Signing Officer Name: Jessica Lybeck

**Customer Details:**

Name: VOGT TRANSPORT

Address: BOX 174, IMPERIAL, Saskatchewan, S0G 2J0

Inspection Completed Date: 07Apr2025

Inspection Expiry Date: 30Apr2026

**Vehicle Details:**

VIN: 1W1K44534P2275527

Hubometer Reading:

Year: 2023

Vehicle Make/Model: WILSON TRAILER/TRAILER

Plate:

Jurisdiction:

Unit: TRI

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

## Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70264

Station Name: Golden West Trailer & Equipment

Technician #: 81335

Technician Name: George Carle

Signing Officer #: 91784

Signing Officer Name: Jessica Lybeck

**Customer Details:**

Name: VOGT TRANSPORT

Address: BOX 174, IMPERIAL, Saskatchewan, S0G 2J0

**Vehicle Details:**

VIN: 1W1K44534P2275527

Hubometer Reading:

Year: 2023

Vehicle Make/Model: WILSON TRAILER TRAILER

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	REPAIR LIC PLATE LIGHT
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	REPLACE HALDEX OVAL BUSHINGS ON SLACK ADJUSTERS AIR LEAK AT RR MAXI POT
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	REPLACE SHOCKS
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

#### Brake/Tire Measurements

##### Axle 1-Pass

---

Wheel1 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

##### Axle 2-Pass

---

Wheel1 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

##### Axle 3-Pass

---

Wheel1 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 85.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 95.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A311579

Inspection Completed Date: 07Apr2025