

03894641

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



001-1

Vehicle Standards and Inspection
Box 45004, Regent Postal Outlet
Winnipeg, MB, R2C 9C7
1-800-955-0000

Manitoba



A864207

Date Inspection Started DAY: 01, MO: 11, YR: 24	Station Number A162510	Station Name FORTAO TRUCK SERVICES LTD	City Fort St. John
Date Inspection Completed DAY: 13, MO: 11, YR: 24	Mechanic Number M8181418	Mechanic Signature [Signature]	Station Phone Number 204-433-3379
Inspection Expiry Date DAY: 30, MO: 11, YR: 25	Vehicle Owner RED RIVER FORGE INC	Address Rt 404 Morris MB R0G1K0	City Morris
Province MB	Postal Code R0G1K0	Phone [Blank]	
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number NO PLATE Vehicle Identification Number 2MS11301976Y110688714 ☒ Confirmed legible Vehicle Identification Number on vehicle	Prov. [Blank] NSC # [Blank] Odometer Reading [Blank] Odom. Type km ☐ mi ☐	Make MANUL Model [Blank] Year 00 Unit # 50307

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X	X	Section 2 Suspension: Defects (if any) RB - RF SUSPENSION HANGER CRACKED, 2C - RC SUSPENSION ARM RUSTED THROUGH
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 2A - ABS FAULT 16H - ADJUST BRAKES 3A - AIR LEAK DETECTED
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) K - LR TAIL LIGHT INOPERATIVE, 1H - LC MARKER LIGHT INOPERATIVE
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 6C - UPPER AIR BAG CROSSMEMBER RUSTED THROUGH AND OTHER CROSSMEMBERS CRACKED
X	X	Section 9 - Tire & Wheel: Defects (if any) 4A - ADJUST TIRE PRESSURES
X	X	Section 10 - Coupling Devices: Defects (if any) 7D - 5TH WHEEL LATCHING MECHANISM SEIZING AND TOP PLATE DRY

Axle	Tread Depth 32ND				Air Pressure PSI			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	15	15	14	14	90	88	92	94
2	16	10	8	9	95	92	100	95
3	17	17	18	18	88	92	88	85
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: