

Detail

Date Printed: 11/07/2025



0000015170

Work Order #: 0000015170

Title: (MC #H107) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 12/06/2024 09:31:00 AM

Expected: 01/05/2025 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (MC #H107) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 12/06/2024 09:31:00 AM

Completed: 12/06/2024 09:55:00 AM

Work requested:

Perform 300 Hour Service for mobile crane.

Action Taken:

300hr service complete

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	3.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	87.50		
Non-inv \$:	361.55		
WO Cost:	449.05	Total Hrs:	3.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	MC #H107 (MC #1)	Mobile Crane	Hours Run	1	10000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		12/06/2024 09:48:00 AM	3.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Advanced Auto Invoice#: 5082433867820		1.00		Dispatched	Qty: 1 Air filter 88595, Air filter 88607
	Advanced Auto Invoice#: 5082433767795		1.00		Dispatched	Qty: 1 Oil filter 84182, fuel filter 86732, Fuel filter 86722, trans filter 84129

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000015170

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil. Change Fuel filter if applicable.				
2	Instruction	Air Filter	Yes	
Replace Air Filter.				
3	Instruction	Fluid Check	Yes	
Check that all fluids are at proper level.				
4	Instruction	Hydraulic filter	Yes	
Replace Hydraulic Filter.				
5	Instruction	Grease	Yes	
Grease all greasable points on machine.				
6	Instruction	Leaks	Yes	
Check for any leaks.				
7	Instruction	Radiator	Yes	
Blow out radiator.				
8	Instruction	Inspect	Yes	
Inspect machine for any wear/damage/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000015169
Title: spotting mirror broken
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 12/06/2024 09:28:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 12/06/2024 09:28:00 AM
Completed: 12/06/2024 09:39:00 AM

Work requested:

the spotting mirror needs to be replaced

Action Taken:

A new spotting mirror was installed

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	12.50		
Non-inv \$:	31.06		
WO Cost:	43.56	Total Hrs:	0.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		12/06/2024 09:32:00 AM	0.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Kansas Powertrain		1.00		Dispatched	Qty: 1 8.5" offset convex mirror 708502

Equipment Usage

Detail

Date Printed: 11/07/2025



0000015169

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000010759

Work Order #: 0000010759

Title: (MC #H107) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 11/20/2023 01:22:00 PM

Expected: 12/20/2023 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (MC #H107) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 11/20/2023 01:22:00 PM

Completed: 11/20/2023 03:25:00 PM

Work requested:

Perform 300 Hour Service for mobile crane.

Action Taken:

300 hour service complete

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	6.50
Total Part Cost:	288.47	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	162.50		
Non-inv \$:	120.15		
WO Cost:	571.12	Total Hrs:	6.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	MC #H107 (MC #1)	Mobile Crane	Hours Run	1	10000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
gary		11/20/2023 03:18:00 PM	6.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	88595		1.00		Dispatched	
	88607		1.00		Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
86732	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
86722	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
84129	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000010759

002

Cenex
Superlube TMS
15W-40 Haas
Crane Oil

Maintenance Shop

25.00 quart

Dispatched

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil. Change Fuel filter if applicable.				
2	Instruction	Air Filter	Yes	
Replace Air Filter.				
3	Instruction	Fluid Check	Yes	
Check that all fluids are at proper level.				
4	Instruction	Hydraulic filter	Yes	
Replace Hydraulic Filter.				
5	Instruction	Grease	Yes	
Grease all greasable points on machine.				
6	Instruction	Leaks	Yes	
Check for any leaks.				
7	Instruction	Radiator	Yes	
Blow out radiator.				
8	Instruction	Inspect	Yes	
Inspect machine for any wear/damage/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000008867

Work Order #: 0000008867

Title: (MC #H107) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 05/25/2023 10:52:00 AM

Expected: 06/24/2023 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (MC #H107) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 05/25/2023 10:52:00 AM

Completed: 06/12/2023 05:07:00 PM

Work requested:

Perform 300 Hour Service for mobile crane.

Action Taken:

300 hour service complete.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	3.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	87.50		
Non-inv \$:	944.22		
WO Cost:	1031.72	Total Hrs:	3.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	MC #H107 (MC #1)	Mobile Crane	Hours Run	1	10000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H		06/12/2023 04:52:00 PM	3.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	86732		1.00		Dispatched	
	86722		1.00		Dispatched	
	84129		1.00		Dispatched	
	84182		1.00		Dispatched	
	88595		1.00		Dispatched	
	88607		1.00		Dispatched	
	15W40 Rotella		24.00		Dispatched	
	86732		1.00		Dispatched	
	86722		1.00		Dispatched	



0000008867

84129	1.00	Dispatched
84182	1.00	Dispatched
88595	1.00	Dispatched
88607	1.00	Dispatched
15W40 Rotella	24.00	Dispatched

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
		Drain old oil. Replace oil filter. Refill oil. Change Fuel filter if applicable.		
2	Instruction	Air Filter	Yes	
		Replace Air Filter.		
3	Instruction	Fluid Check	Yes	
		Check that all fluids are at proper level.		
4	Instruction	Hydraulic filter	Yes	
		Replace Hydraulic Filter.		
5	Instruction	Grease	Yes	
		Grease all greasable points on machine.		
6	Instruction	Leaks	Yes	
		Check for any leaks.		
7	Instruction	Radiator	Yes	
		Blow out radiator.		
8	Instruction	Inspect	Yes	
		Inspect machine for any wear/damage/missing parts.		

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000007912

Work Order #: 0000007912

Title: (MC #H107) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 03/08/2023 08:30:00 AM

Expected: 04/07/2023 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (MC #H107) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 03/08/2023 08:30:00 AM

Completed: 03/08/2023 08:39:00 AM

Work requested:

Perform 300 Hour Service for mobile crane.

Action Taken:

300hr service was completed

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	5.00
Total Part Cost:	72.60	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	125.00		
Non-inv \$:	0.00		
WO Cost:	197.60	Total Hrs:	5.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	MC #H107 (MC #1)	Mobile Crane	Hours Run	1	10000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		03/08/2023 08:31:00 AM	3.00			
Blue		03/08/2023 08:33:00 AM	2.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Advanced Auto Parts Invoice#:50823 06561688		1.00		Dispatched	Qty:1 Air filter 88595, Air filter 88607, transmission hydraulic oil filter 84129, oil filter 84182, fuel filter 86732, fuel filter 86722
002	Cenex Superlube TMS 15W-40 Haas Crane Oil	Maintenance Shop	22.00	quart	Dispatched	

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000007912

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
		Drain old oil. Replace oil filter. Refill oil. Change Fuel filter if applicable.		
2	Instruction	Air Filter	Yes	
		Replace Air Filter.		
3	Instruction	Fluid Check	Yes	
		Check that all fluids are at proper level.		
4	Instruction	Hydraulic filter	Yes	
		Replace Hydraulic Filter.		
5	Instruction	Grease	Yes	
		Grease all greasable points on machine.		
6	Instruction	Leaks	Yes	
		Check for any leaks.		
7	Instruction	Radiator	Yes	
		Blow out radiator.		
8	Instruction	Inspect	Yes	
		Inspect machine for any wear/damage/missing parts.		

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000007910

Title: Fix items found on check in

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 03/08/2023 08:17:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)

Cause: Equipment Wear

Assigned: 03/08/2023 08:17:00 AM

Completed: 03/08/2023 08:28:00 AM

Work requested:

Fix items found on check in: hydraulic oil was low after fixing the lift cylinder, fix electrical issues with the winch, one of the mirrors is broken

Action Taken:

Hydraulic oil was filled, the electrical issues with the winch were fixed, and the mirror was replaced

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	4.00
Total Part Cost:	176.82	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	100.00		
Non-inv \$:	0.00		
WO Cost:	276.82	Total Hrs:	4.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary		03/08/2023 08:21:00 AM	3.00			
Bo		03/08/2023 08:21:00 AM	1.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
--------	------	----------	----------	------	------------	-------------

Detail

Date Printed: 11/07/2025



0000007910

	Kansas Powertrain & Equipment Invoice#:84691		1.00		Dispatched	Qty:1 Mirror center mount
001	Cenex Universal Tractor Fluid Haas Crane Oil	Maintenance Shop	56.00	quart	Dispatched	

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000007909
Title: Check in and prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 03/08/2023 08:10:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Equipment Wear
Assigned: 03/08/2023 08:10:00 AM
Completed: 03/08/2023 08:16:00 AM

Work requested:

Check in and prep for rent

Action Taken:

Machine was checked in and made rent ready

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	75.00		
Non-inv \$:	0.00		
WO Cost:	75.00	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		03/08/2023 08:15:00 AM	2.00			
Blue		03/08/2023 08:16:00 AM	1.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000007909

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006032

Work Order #: 0000006032
Title: This crane came back from two week rental on bare
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Planned
Originated: 09/19/2022 07:38:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jeff Cowan
Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 09/19/2022 08:12:00 AM
Completed: 09/19/2022 09:04:00 AM

Work requested:

This crane came back from two week rental on bare rent to Pendergraft Erection. It is scheduled to go on rent in Garden City Tuesday 9-20-22 and Jason will plan to load it on trailer this afternoon. Please check it out and make sure its good to go on one month rent.

Action Taken:

prep for rent complete.

Comments:

Total Labor Cost:	187.50	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	187.50	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		09/19/2022 08:17:00 AM	2.50			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000006032

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000005867
Title: Crane needs to be serviced and rent ready.
Schedu
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Planned
Originated: 08/29/2022 10:40:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jeff Cowan

Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 08/29/2022 12:06:00 PM
Completed: 08/31/2022 10:53:00 AM

Work requested:

Crane needs to be serviced and rent ready. Scheduled for delivery to a job on Friday 9-2-22.

Action Taken:

this crane is ready to go. its only had 13 hours put on it since the last service. I had to build a new flag pole for this since it is going to a air port.

Comments:

Total Labor Cost:	225.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	225.00	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		08/31/2022 10:52:00 AM	3.00			

Parts

None

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000005867

Documents

None

Safety Programs

None



Work Order #: 0000005595

Title: (MC #H107) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 07/29/2022 10:06:00 AM

Expected: 08/28/2022 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (MC #H107) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 07/29/2022 10:06:00 AM

Completed: 07/29/2022 10:13:00 AM

Work requested:

Perform 300 Hour Service for mobile crane.

Action Taken:

THIS CRANE JUST GOT A NEW HOUR METER INSTALLED SO THE HOURS HAVE STARTED AT 0. IT CURENTLY HAD 8299 HOURS ON THE CRANE WHEN IT QUIT AND WAS IN FROM WHEN IT LAST GOT SERVICED WHEN IT STOPPED. NOT KNOWING EXACTLY HOW MANY HOURS WHERE PUT ON IT SINCE IT STOPPED WORKING I DECIDED TO DO THIS SERVICE SO WE KNOW WHERE WE ARE AT MOVING FORWARD.

Comments:

Total Labor Cost:	225.00	Total Labor Hours:	3.00
Total Part Cost:	264.95	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	137.91		
WO Cost:	627.86	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	MC #H107 (MC #1)	Mobile Crane	Hours Run	1	10000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		07/29/2022 10:09:00 AM	3.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	ADVANCE AUTO PARTS		1.00		Dispatched	88595 AIR FILTER88607 AIR FILTER
86732	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
86722	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000005595

84129	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	20.00	quart	Dispatched

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil. Change Fuel filter if applicable.				
2	Instruction	Air Filter	Yes	
Replace Air Filter.				
3	Instruction	Fluid Check	Yes	
Check that all fluids are at proper level.				
4	Instruction	Hydraulic filter	Yes	
Replace Hydraulic Filter.				
5	Instruction	Grease	Yes	
Grease all greasable points on machine.				
6	Instruction	Leaks	Yes	
Check for any leaks.				
7	Instruction	Radiator	Yes	
Blow out radiator.				
8	Instruction	Inspect	Yes	
Inspect machine for any wear/damage/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000005551

Page 21 of 42

Work Order #: 0000005551

Title: this crane came back from 3-4 month rental.
Pleas

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 07/25/2022 11:16:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 07/26/2022 05:48:00 AM

Completed: 07/29/2022 10:04:00 AM

Work requested:

this crane came back from 3-4 month rental. Please check it out and make sure its rent ready

Action Taken:

THE HOUR METER ON THIS CRANE HAD STOPPED WORKING AT 8299 HOURS. IT WAS 87 HOURS INTO ITS LAST OIL CHANGE WHEN IT QUIT. WERE GUESSING IT QUIT SOMEWHERE WITHIN THE LAST 400 HOURS OR SO. I REPLACED THE HOUR METER SO THAT IT WORKS NOW. ARM REST WERE ALSO IN BAD CONDITION SO WE RECOVERED THEM AND CLEANED IT WELL. I DID A SERVICE ON THIS CRANE AND REPLACED ALL FILTERS AND OIL SO WE KNOW WE'RE STARTING FRESH NOW.

Comments:

Total Labor Cost:	300.00	Total Labor Hours:	4.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	67.49		
WO Cost:	367.49	Total Hrs:	4.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		07/29/2022 10:04:00 AM	4.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Napa 296764		1.00		Dispatched	hour meter 701-1245

Detail

Date Printed: 11/07/2025



0000005551

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000004361

Work Order #: 0000004361
Title: Crane Repair
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 03/03/2022 02:50:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 03/03/2022 02:50:00 PM
Completed: 03/10/2022 08:46:00 AM

Work requested:

Crane in running rough. install new injectors and fuel line.

Action Taken:

- replaced all 6 injectors
- cleaned hard lines and flushed them out
- replaced all 6 valve cover gaskets to fix oil leak

Comments:

first attempt to repair this crane Cody and I got on site at 8:10am I had just received an email that the job site had an emergency and needed the crane. I have now scheduled the repair for 3/9/22.

Total Labor Cost:	2212.50	Total Labor Hours:	29.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	1403.86		
WO Cost:	3616.36	Total Hrs:	29.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
----------	------------	----------	---------	----	----------------	-------------

Date Printed: 11/07/2025



Page 24 of 42



0000004361

Gary H. McCowan	03/03/2022 12:53:00 PM	5.00
Cody Dick	03/03/2022 12:53:00 PM	5.00
Gary H. McCowan	03/10/2022 08:37:00 AM	9.75
Cody Dick	03/10/2022 08:38:00 AM	9.75

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	napa auto 800004157		1.00		Dispatched	valve cover gaskets
	napa auto 800004157		1.00		Dispatched	
	hoys S47748		1.00		Dispatched	CUM4089270RX injectorsGATK080774 serpentine belt

None

None

None

None

None

None

None

None

Detail

Date Printed: 11/07/2025



0000003237

Page 25 of 42

Work Order #: 0000003237

Title: Please do a check-in inspection and have it rental

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 09/08/2021 06:47:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 09/08/2021 06:57:00 AM

Completed: 09/09/2021 10:27:00 AM

Work requested:

Please do a check-in inspection and have it rental ready. This machine also needs to be marked with Haas Crane stickers with ID number (MC-107). No known problems

Action Taken:

Comments:

this machine still has over 200 hours before it needs serviced. HCE stickers have been put on. everything else seems to be good to go.

Total Labor Cost:	262.50	Total Labor Hours:	3.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	262.50	Total Hrs:	3.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		09/09/2021 10:18:00 AM	3.50			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000003237

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002983

Page 27 of 42

Work Order #: 0000002983

Title: Crane is low on hydraulic fluidJob site: Viraco

Origin: Non-PM

Cost Center: 4800

Priority: Critical(ASAP)

Problem: Other

Originated: 07/19/2021 03:55:00 PM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Preventive Maintenance (PM)

Cause: Inadequate Lubrication

Assigned: 07/20/2021 10:25:00 AM

Completed: 07/21/2021 01:54:00 PM

Work requested:

Crane is low on hydraulic fluid

Job site: Viracor - 18000 W 99th St - Lenexa, KS 66219. Levi Brown is contact (616)894-2884

Action Taken:

hydraulic oil was full. Maybe they were trying to check level with it extended.

Comments:

Hour Meter doesn't work Levi Brown said Jeff knows about it

Total Labor Cost:	37.50	Total Labor Hours:	0.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	37.50	Total Hrs:	0.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Cody Dick	Maintenance		cdick@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Cody Dick		07/21/2021 07:24:00 AM	0.50			

Parts

None

Detail

Date Printed: 11/07/2025



0000002983

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002829

Work Order #: 0000002829
Title: see notes
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Broken/Worn Belt
Originated: 06/16/2021 01:10:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Equipment Wear
Assigned: 06/16/2021 01:10:00 PM
Completed: 06/18/2021 01:47:00 PM

Work requested:

belt was broken upon arrival to the job site.

Action Taken:

Comments:

Total Labor Cost:	337.50	Total Labor Hours:	4.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	51.46		
WO Cost:	388.96	Total Hrs:	4.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		06/18/2021 01:45:00 PM	4.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	hoys truck center S42575		1.00		Dispatched	Serpentine belt #GATK080774

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000002829

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002315

Page 31 of 42

Work Order #: 0000002315

Title: Please check out crane and make sure its ready to

Origin: Non-PM

Cost Center: 4800

Priority: High(1-3 days)

Problem: Planned

Originated: 04/06/2021 02:03:00 PM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 04/06/2021 02:18:00 PM

Completed: 06/01/2021 08:14:00 AM

Work requested:

Please check out crane and make sure its ready to go on a job. Its going to TFI for some roof decking on 4-12-21 and then going to KC on a jobsite for several months. No known problems.

Action Taken:

Comments:

Total Labor Cost:	150.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	150.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		06/01/2021 08:14:00 AM	2.00			

Parts

None

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000002315

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000001715

Page 33 of 42

Work Order #: 0000001715

Title: 50 ton crane going on rent - leaving HME early mor

Origin: Non-PM

Cost Center: 4800

Priority: High(1-3 days)

Problem: Planned

Originated: 12/29/2020 02:36:00 PM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 12/30/2020 07:17:00 AM

Completed: 12/31/2020 07:40:00 AM

Work requested:

50 ton crane going on rent - leaving HME early morning 1-4-21.... probably try to get loaded on trailer 12-31-20.

Please go through and make sure its ready to go on jobsite with full check-out. No known problems.

Action Taken:

Approved

Comments:

I guess since this machine isn't in the system right Ill put my hours here again. 8299 is the hours. should have about 220 hours give or take before the service is due again.. as of now it's good to go.

Total Labor Cost:	90.00	Total Labor Hours:	1.20
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	90.00	Total Hrs:	1.20
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		12/31/2020 07:37:00 AM	1.20			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000001715

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000001606
Title: batteries bad
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Other
Originated: 12/02/2020 10:30:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Equipment Wear
Assigned: 12/02/2020 10:30:00 AM
Completed: 12/02/2020 10:33:00 AM

Work requested:

replace batteries

Action Taken:

Comments:

replace batteries and check charging system.

Total Labor Cost:	225.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	239.90		
WO Cost:	464.90	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		12/02/2020 10:31:00 AM	3.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	group 31 battery		2.00		Dispatched	

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000001606

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000001362

Page 37 of 42

Work Order #: 0000001362

Title: This crane will be going on rent 10-26-20. Left f

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Leak

Originated: 10/16/2020 10:11:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Corrective Maintenance (CM)

Cause: Scheduled Maintenance

Assigned: 10/16/2020 11:06:00 AM

Completed: 11/05/2020 02:51:00 PM

Work requested:

This crane will be going on rent 10-26-20. Left front outrigger is leaking.

Action Taken:

Approved

Comments:

Total Labor Cost:	225.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	1661.17		
WO Cost:	1886.17	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		11/05/2020 02:51:00 PM	3.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	North East Hydraulic		1.00		Dispatched	labor to cut apart the old gland
	kirby smith		1.00		Dispatched	gland and wear bands
	kirby smith		1.00		Dispatched	rebuild kit

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000001362

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000001048

Page 39 of 42

Work Order #: 0000001048

Title: Crane needs serviced prior to going to next job.

Origin: Non-PM

Cost Center: 4800

Priority: Low(7-15 days)

Problem: Planned

Originated: 08/17/2020 01:55:00 PM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 08/18/2020 12:41:00 PM

Completed: 08/25/2020 04:27:00 PM

Work requested:

Crane needs serviced prior to going to next job. The items that need attention per Billy: 1) latch on the hook needs to be fixed with several spares in cab. 2) wind meter wouldnt connect with old receiver (possibly a battery issue). 3) Needs a case of grease. 4) Boom needs lubed. 5) Needs a new flag pole - last one was probably left on a prior job-site. 6) exhaust checked out - Steve thought muffler was going bad. 7) needs a bath - last good cleaning was 2.5 years ago.

Action Taken:

Approved

Comments:

the hours show 8293 it was just serviced at 8219. It shouldn't need a service for another 226 hours. The latch on the hook was replaced. I only had one more extra and it is in the cab and I've ordered more. The wind meter had to be Calibrated. it works fine now. A Case of grease is in the crane. The boom was lubed. The original Flag pole was brought back to maintenance a long time ago because it didn't fit anymore. I put it back on and it fit just fine. The exhaust was blown out inside the engine compartment. I rebuilt that and it is working well now.

Total Labor Cost:	525.00	Total Labor Hours:	7.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	80.70		
WO Cost:	605.70	Total Hrs:	7.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		08/25/2020 04:27:00 PM	7.00			

Detail

Date Printed: 11/07/2025



0000001048

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	kansas powertrain 64686		1.00		Dispatched	

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000000183

Work Order #: 0000000183
Title: Install GPS tracking device
Origin: Non-PM
Cost Center: 4800
Priority: Spare Time
Problem: Programming
Originated: 02/20/2020 12:32:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Andy Reddick

Work Type: Improvements
Cause: Unknown
Assigned: 04/13/2020 08:52:00 AM
Completed: 07/06/2020 09:33:00 AM

Work requested:

Install GPS tracking device

Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
HME_00299	MC #H107 (MC #1)	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Grove	RT650E	HME_00299

Source Custom Fields

No	Name	Custom Field	Value
HME_00299	MC #H107 (MC #1)	License Plate #	

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

None

Documents

Detail

Date Printed: 11/07/2025



0000000183

None

Safety Programs

None