

Detail

Date Printed: 11/07/2025



0000019128

Work Order #: 0000019128

Title: fix items found on check in

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 08/29/2025 09:27:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)

Cause: Equipment Wear

Assigned: 08/29/2025 09:27:00 AM

Completed: 09/02/2025 03:20:00 PM

Work requested:

fork bar bent, fuel gauge randomly switches to empty, left front tire bald and starting to patch out, oring leaking on fitting to transmission

Action Taken:

replaced all 4 tires, cleaned electrical lines for fuel gauge at tank, replaced fork bar, replaced boss oring to fitting on transmission

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	75.00		
Non-inv \$:	293.76		
WO Cost:	368.76	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
kagan		08/29/2025 09:29:00 AM	2.00			
Bo		08/29/2025 09:35:00 AM	1.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
--------	------	----------	----------	------	------------	-------------

Detail

Date Printed: 11/07/2025



0000019128

united rentals	1.00	Dispatched	qty 1: fork shaft #225-
invoice#			77TH
252241276-001			

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000019079

Work Order #: 0000019079
Title: (ST #H157) 300 Hour Service
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 08/26/2025 10:04:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 08/26/2025 10:04:00 AM
Completed: 09/02/2025 10:29:00 AM

Work requested:

machine is due for 300 hour service

Action Taken:

300 hour service complete at this time

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.75
Total Part Cost:	186.30	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	18.75		
Non-inv \$:	95.26		
WO Cost:	300.31	Total Hrs:	0.75
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
kagan		08/26/2025 03:23:00 PM	0.75			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	stock parts		1.00		Dispatched	qty 1: air filter #PA31006
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000019079

86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	12.00	quart	Dispatched	

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
		Change oil and oil filter.		
2	Instruction	Fuel Filter	Yes	
		Change fuel filter.		
3	Instruction	Oil Check	Yes	
		Check oil level.		
4	Instruction	Air Filter	Yes	
		Change air filter.		
5	Instruction	Transmission Fluid Check	Yes	
		Check transmission fluid level.		
6	Instruction	Coolant Level Check	Yes	
		Check level of coolant.		
7	Instruction	Grease Unit	Yes	
		Grease ALL greasable points on unit. (Refer to maintenance manual if necessary).		

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000019078
Title: check in and prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 08/26/2025 10:02:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 08/26/2025 10:02:00 AM
Completed: 09/02/2025 10:26:00 AM

Work requested:

check in and prep for rent

Action Taken:

check in and prep for rent complete

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	1.75
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	43.75		
Non-inv \$:	0.00		
WO Cost:	43.75	Total Hrs:	1.75
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
kagan		08/29/2025 09:26:00 AM	1.75			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000019078

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000018058

Work Order #: 0000018058

Title: Check in and prep for rent

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 06/30/2025 10:26:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 06/30/2025 10:26:00 AM

Completed: 07/08/2025 08:26:00 AM

Work requested:

Check in and prep for rent

Action Taken:

Checked in and prepped for rent. last service at 10628

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
kyler		06/30/2025 10:29:00 AM	2.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000018058

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000017528

Work Order #: 0000017528
Title: fix items found on check in
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 05/28/2025 07:06:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford
Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 05/28/2025 07:06:00 AM
Completed: 06/04/2025 03:33:00 PM

Work requested:

door latch broke, hood doesnt hold open, left front inner wheel seal seeping, hydraulic line leaking off transmission, lift cylinder bottom line leaking, holding valve for fork tilt leaking, rear battery strap missing, oil seeping from behind filter on transmission, boom hoses cracked out inside boom, cooler lines off radiator leaking. test point on top of Transmation leaking

last 300 hr service done at 10628

Action Taken:

door latch fixed, hood struts replaced, fix hydraulic leak from line off transmission, fixed hydraulic leak off the bottom of lift cylinder, fixed leak off transmission above filter, tilt cylinder hold valve was replaced, boom hoses were replaced. test point was replaced

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	7.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	175.00		
Non-inv \$:	613.45		
WO Cost:	788.45	Total Hrs:	7.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
----------	------------	----------	---------	----	----------------	-------------

Detail

Date Printed: 11/07/2025



0000017528

kagan	05/28/2025 07:12:00 AM	2.00
kyler	06/04/2025 03:28:00 PM	5.00

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	united rentals invoice#: 245432921-001		1.00		Dispatched	qty:2 hood strut. part # 1001131247
	united rentals invoice#: 248548784-001		1.00		Dispatched	qty:4 hydraulic line assembly qty:1 hold valve assembly 91404382
	united rentals invoice#:24865 7915-001		1.00		Dispatched	qty:1 cartridge cb valve 70031382
	stock parts		1.00		Dispatched	qty:1 test point

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000017526

Work Order #: 0000017526
Title: check in and prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 05/28/2025 07:04:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 05/28/2025 07:04:00 AM
Completed: 06/06/2025 05:42:00 PM

Work requested:

check in and prep for rent

Action Taken:

checked in and prepped for rent. last service at 10628

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	62.50		
Non-inv \$:	0.00		
WO Cost:	62.50	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
kagan		05/28/2025 07:06:00 AM	2.50			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000017526

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000016191
Title: Check in and prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 02/28/2025 08:46:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 02/28/2025 08:46:00 PM
Completed: 03/04/2025 02:51:00 PM

Work requested:

Check in and prep for rent

Action Taken:

Check in and preped for rent. last service at 10698

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Kyler		02/28/2025 08:48:00 PM	2.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000016191

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000016157
Title: (ST #H157) 300 Hour Service
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 02/26/2025 01:33:00 PM
Expected: 03/05/2025 11:59:00 PM

Source Type: Meter Title
WO Status: Completed
Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 02/26/2025 01:33:00 PM
Completed: 02/28/2025 08:35:00 AM

Work requested:
Complete 300 Hour service for lift.
Action Taken:

300hr service complete

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	1.50
Total Part Cost:	329.07	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	37.50		
Non-inv \$:	0.00		
WO Cost:	366.57	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields
None

Assigned To						
	Employee #	Name	Job Title	Phone	Email	Est Hrs Company Name
1		Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00 HME, Inc.

Source						
Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor						
Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
rick		02/28/2025 08:30:00 AM	1.50			

Parts						
Part #	Name	Location	Quantity	Unit	Usage Type	Description
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
93769	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
93767	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
002	Cenex Superlube TMS 15W-40 Haas Crane Oil	Maintenance Shop	13.00	quart	Dispatched	

Detail

Date Printed: 11/07/2025



0000016157

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil.				
2	Instruction	Air Filter	Yes	
Replace Air Filter.				
3	Instruction	Fluid Check	Yes	
Check that all fluids are at the proper level.				
4	Instruction	Grease	Yes	
Grease all greasable points on lift.				
5	Instruction	Leaks	Yes	
Check for any leaks.				
6	Instruction	Radiator	Yes	
Blow out radiator.				
7	Instruction	Inspect	Yes	
Inspect lift for any damaged/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000016156

Work Order #: 0000016156

Title: check in and prep for rent.

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 02/26/2025 01:26:00 PM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 02/26/2025 01:26:00 PM

Completed: 03/06/2025 08:51:00 AM

Work requested:

Check in and prep for rent.

Action Taken:

Check in and prep for rent complete. 300-hour service done at this time.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	62.50		
Non-inv \$:	0.00		
WO Cost:	62.50	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
rick		03/06/2025 08:50:00 AM	2.50			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000016156

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000015139

Work Order #: 0000015139
Title: 10K has an anti-freeze leak under the seat.
Curre
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Leak
Originated: 12/03/2024 11:14:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jeff Cowan
Work Type: Breakdown Maintenance
Cause: Equipment Wear
Assigned: 12/03/2024 01:34:00 PM
Completed: 12/13/2024 07:09:00 AM

Work requested:

10K has an anti-freeze leak under the seat. Currently on rent to Drisco at Desoto Battery Plant. Can either fix on site or we can try to replace machine and bring back to repair at the shop.

Drisco has also requested 6' forks for this machine.... or another machine with 6' forks.

Drisco Shaft Co - machine located at Desoto Battery Plant - 11425 Ad Astra Pkwy - Desoto, KS

Freddie Rose (248)469-7810

They have critical lifts starting early Thursday 12-5-24. Pin drop of location will be sent.

Action Taken:

removed the seat and consol and found that it was leaking at the shut off valve. tighten the hose clamps up and it seemed to stop the leak. cleaned it up and watched for a bit while it ran and didn't see anything leaking. repairs done in DeSoto KS

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	75.00		
Non-inv \$:	0.00		
WO Cost:	75.00	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
----	------	--------------	-------

Detail

Date Printed: 11/07/2025



0000015139

ST #H157 License Plate #

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary		12/13/2024 07:08:00 AM	3.00			

Parts

None

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000013336

Work Order #: 0000013336
Title: fix items found on check in
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 07/16/2024 08:48:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 07/16/2024 08:48:00 AM
Completed: 07/16/2024 09:03:00 AM

Work requested:

two fuel lines need replaced, and one of the light brackets on the front needs replaced

Action Taken:

New fuel lines and light bracket were installed.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	1.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	37.50		
Non-inv \$:	137.29		
WO Cost:	174.79	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		07/16/2024 08:58:00 AM	1.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United Rentals Invoice#: 232065640-001		1.00		Dispatched	Qty: 1 Fuel Supply tube 5368661

Detail

Date Printed: 11/07/2025



0000013336

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000013335

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000013282

Work Order #: 0000013282
Title: Ac not working
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Planned
Originated: 07/09/2024 03:10:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Lance Buchman

Work Type: Corrective Maintenance (CM)
Cause: Unknown
Assigned: 07/09/2024 03:10:00 PM
Completed: 07/09/2024 03:21:00 PM

Work requested:

Charge ac and check for leaks

Action Taken:

Charged ac and checked for leaks

Holds 38.8 ozs R34A

Comments:

Total Labor Cost:	75.00	Total Labor Hours:	1.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	37.32		
WO Cost:	112.32	Total Hrs:	1.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Lance Buchman	Maintenance		lbuchman@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Lance Buchman		07/09/2024 03:13:00 PM	0.50			
Cody Dick		07/09/2024 03:20:00 PM	0.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Freon		2.80		Dispatched	R34A

Detail

Date Printed: 11/07/2025



0000013282

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000012190

Work Order #: 0000012190
Title: Fix items found on check in
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 04/05/2024 09:32:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 04/05/2024 09:32:00 AM
Completed: 04/05/2024 01:34:00 PM

Work requested:

Fix items found on check in: fork tilt cylinder holding valve leaking, hydraulic leak on a fitting by the transmission

Action Taken:

The holding valve and the fitting were resealed.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	1.50
Total Part Cost:	15.79	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	37.50		
Non-inv \$:	0.00		
WO Cost:	53.29	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		04/05/2024 09:35:00 AM	1.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
001	Cenex Universal Tractor Fluid Haas Crane Oil	Maintenance Shop	5.00	quart	Dispatched	

Detail

Date Printed: 11/07/2025



0000012190

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000012189

Work Order #: 0000012189
Title: (ST #H157) 300 Hour Service
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 04/05/2024 08:51:00 AM
Expected: 04/12/2024 11:59:00 PM

Source Type: Meter Title
WO Status: Completed
Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 04/05/2024 08:51:00 AM
Completed: 04/05/2024 01:36:00 PM

Work requested:
Complete 300 Hour service for lift.
Action Taken:

300hr service was completed

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	334.72	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	100.56		
WO Cost:	485.28	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		04/05/2024 09:27:00 AM	2.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Stock		1.00		Dispatched	Qty: 1 Air Filter 93767
002	Cenex Superlube TMS 15W-40 Haas Crane Oil	Maintenance Shop	13.00	quart	Dispatched	
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
CBP/CV52055	Crankcase Vent Filter	Maintenance Shop	1.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000012189

93769

Carquest Air
Filter

Maintenance Shop

1.00 each

Dispatched

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil.				
2	Instruction	Air Filter	Yes	
Replace Air Filter.				
3	Instruction	Fluid Check	Yes	
Check that all fluids are at the proper level.				
4	Instruction	Grease	Yes	
Grease all greasable points on lift.				
5	Instruction	Leaks	Yes	
Check for any leaks.				
6	Instruction	Radiator	Yes	
Blow out radiator.				
7	Instruction	Inspect	Yes	
Inspect lift for any damaged/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000012188

Work Order #: 0000012188

Title: Check in and make rent ready

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 04/05/2024 08:49:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Inspections

Cause: Equipment Wear

Assigned: 04/05/2024 08:49:00 AM

Completed: 04/05/2024 01:31:00 PM

Work requested:

Check in and make rent ready

Action Taken:

Machine was checked in and made rent ready. The 300hr service was completed at this time.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		04/05/2024 09:21:00 AM	2.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000012188

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000011366

Work Order #: 0000011366
Title: heater isn't working
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Part Damage/Failure
Originated: 01/23/2024 10:13:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 01/23/2024 10:13:00 AM
Completed: 07/16/2024 08:40:00 AM

Work requested:

repair cab heater

Action Taken:

after removing the dash and side cover I found that the heater valve wasn't working. after further inspection I found it was leaking coolant as well. I removed it and put in temporary hose barbes so the heat would work until the new heater valve comes in. lift is currently in Ottawa KS.

parts have been ordered.

New heater control valve was installed.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	9.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	225.00		
Non-inv \$:	221.32		
WO Cost:	446.32	Total Hrs:	9.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary		01/23/2024 10:18:00 AM	5.00			

Detail

Date Printed: 11/07/2025



0000011366

Bo	07/11/2024 03:57:00 PM	4.00
----	------------------------	------

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United Rentals Invoice#: 229597133-001		1.00		Dispatched	Qty: 1 Heater control valve 80383231

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000011084
Title: Check in and make rent ready
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 12/22/2023 01:53:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Equipment Wear
Assigned: 12/22/2023 01:53:00 PM
Completed: 12/22/2023 01:59:00 PM

Work requested:

Check in and make rent ready

Action Taken:

Machine was checked in and made rent ready. The last 300hr service was done at 10,095hrs.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Blue		12/22/2023 01:57:00 PM	2.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000011084

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000010583

Work Order #: 0000010583

Title: (ST #H157) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 11/02/2023 12:26:00 PM

Expected: 11/09/2023 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 11/02/2023 12:26:00 PM

Completed: 11/02/2023 12:41:00 PM

Work requested:

Complete 300 Hour service for lift.

Action Taken:

A 300hr service was completed

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	275.68	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	325.68	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		11/02/2023 12:29:00 PM	2.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
84201	Carquest Hydraulic Filter	Maintenance Shop	0.00	each	Dispatched	
CBP/CV52055	Crankcase Vent Filter	Maintenance Shop	1.00	each	Dispatched	
93767	Carquest Air Filter	Maintenance Shop	0.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000010583

002

Cenex
Superlube TMS
15W-40 Haas
Crane Oil

Maintenance Shop

12.00 quart

Dispatched

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil.				
2	Instruction	Air Filter	Yes	
Replace Air Filter.				
3	Instruction	Fluid Check	Yes	
Check that all fluids are at the proper level.				
4	Instruction	Grease	Yes	
Grease all greasable points on lift.				
5	Instruction	Leaks	Yes	
Check for any leaks.				
6	Instruction	Radiator	Yes	
Blow out radiator.				
7	Instruction	Inspect	Yes	
Inspect lift for any damaged/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000010510
Title: Telehandler back from two month rent. Please serv
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Planned
Originated: 10/27/2023 05:51:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jeff Cowan
Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 10/27/2023 06:08:00 AM
Completed: 11/02/2023 12:27:00 PM

Work requested:

Telehandler back from two month rent. Please service and have it rent ready.... going back out 10-30-23.
Action Taken:

Machine was checked in and made rent ready. A 300hr service was completed (on another workorder)

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Blue		11/02/2023 12:27:00 PM	2.00			

Parts

None

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000010510

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000010348

Work Order #: 0000010348
Title: Extend Cylinder Leaking
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Leak
Originated: 10/04/2023 07:34:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 10/04/2023 07:34:00 AM
Completed: 07/16/2024 10:36:00 AM

Work requested:

The extend cylinder is leaking and needs resealed

Action Taken:

The extend cylinder was resealed at the jobsite in Junction City.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	10.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	250.00		
Non-inv \$:	225.52		
WO Cost:	475.52	Total Hrs:	10.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		10/04/2023 07:39:00 AM	5.00			
Gary		07/16/2024 10:35:00 AM	5.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United rentals		1.00		Dispatched	

Equipment Usage

Detail

Date Printed: 11/07/2025



0000010348

None

Tasks/Steps

None

Documents

None

Safety Programs

None



Detail

Date Printed: 11/07/2025



Work Order #: 0000009714
Title: Check in and make rent ready
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 08/09/2023 03:37:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Equipment Wear
Assigned: 08/09/2023 03:37:00 PM
Completed: 08/09/2023 03:41:00 PM

Work requested:

Check in and make rent ready

Action Taken:

Machine was checked in and made rent ready

Last 300hr was at 9789

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	62.50		
Non-inv \$:	0.00		
WO Cost:	62.50	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Blue		08/09/2023 03:40:00 PM	2.50			

Parts

None

Equipment Usage

Detail

Date Printed: 11/07/2025



0000009714

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000009375

Work Order #: 0000009375
Title: Lost a wear pad
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Part Damage/Failure
Originated: 07/10/2023 02:46:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Lance Buchman

Work Type: Corrective Maintenance (CM)
Cause: Improper Installation
Assigned: 07/10/2023 02:46:00 PM
Completed: 07/10/2023 02:53:00 PM

Work requested:

Wear pad fell out

Action Taken:

installed the old wear pad Brad Maccall found

Comments:

Total Labor Cost:	112.50	Total Labor Hours:	1.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	17.00		
WO Cost:	129.50	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Lance Buchman	Maintenance		lbuchman@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Lance Buchman		07/10/2023 02:52:00 PM	1.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Fastenal		1.00		Dispatched	1/2-20x5.5 bolt qty 31/2" washers

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000009375

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000009108

Work Order #: 0000009108

Title: (ST #H157) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 06/16/2023 02:16:00 PM

Expected: 06/23/2023 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 06/16/2023 02:16:00 PM

Completed: 06/17/2023 11:46:00 AM

Work requested:

Complete 300 Hour service for lift.

Action Taken:

Service has been completed; air filter was not replaced due to not being able to find it at the other building

Comments:

Total Labor Cost:	187.50	Total Labor Hours:	2.50
Total Part Cost:	163.77	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	351.27	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Carlos Silva-Aguirre	Maintenance		caguirre@hmeinc.net	0.00	

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Carlos Silva-Aguirre		06/17/2023 11:43:00 AM	2.50			Service completed.

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	12.00	quart	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000009108

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
Drain old oil. Replace oil filter. Refill oil.				
2	Instruction	Fluid Check	Yes	
Check that all fluids are at the proper level.				
3	Instruction	Leaks	Yes	
Check for any leaks.				
4	Instruction	Inspect	Yes	
Inspect lift for any damaged/missing parts.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000008581

Work Order #: 0000008581
Title: Fix items found on check in
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 05/01/2023 07:30:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 05/01/2023 07:30:00 AM
Completed: 05/01/2023 07:47:00 AM

Work requested:

Fix items found on check in: back up alarm not working, battery dead, key switch needs replaced

Action Taken:

The backup alarm was changed, the battery was charged and charging system and draw check was performed and all was good (the key had been left on accessory), the ignition switch was changed

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	62.50		
Non-inv \$:	30.09		
WO Cost:	92.59	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		05/01/2023 07:34:00 AM	2.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United Rentals Invoice#:21886 0894-001		1.00		Dispatched	Qty:1 Ignition Switch 91033317

Detail

Date Printed: 11/07/2025



0000008581

Stock	1.00	Dispatched	Qty:1 Backup alarm
-------	------	------------	--------------------

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000008580

Title: Customer Damage

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Equipment Damage

Originated: 05/01/2023 07:25:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)

Cause: Customer Damage

Assigned: 05/01/2023 07:25:00 AM

Completed: 05/01/2023 08:49:00 AM

Work requested:

Customer Damage: right mirror that is on the mounted above engine hood is missing

Action Taken:

Mirror was replaced

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.25
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	27.50		
Non-inv \$:	27.59		
WO Cost:	55.09	Total Hrs:	0.25
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		05/01/2023 07:54:00 AM	0.25			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United Rentals Invoice#: 218965930		1.00		Dispatched	Qty:1 Mirror

Detail

Date Printed: 11/07/2025



0000008580

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000008579
Title: Check in and make rent ready
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 05/01/2023 07:23:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Equipment Wear
Assigned: 05/01/2023 07:23:00 AM
Completed: 05/01/2023 07:53:00 AM

Work requested:

Check in and make rent ready

Action Taken:

Machine was checked in and made rent ready

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	62.50		
Non-inv \$:	0.00		
WO Cost:	62.50	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		05/01/2023 07:52:00 AM	2.50			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000008579

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000008347
Title: check starting and charging system
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Won't Start
Originated: 04/07/2023 12:55:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Corrective Maintenance (CM)
Cause: Unknown
Assigned: 04/07/2023 12:55:00 PM
Completed: 04/10/2023 12:25:00 PM

Work requested:

machine has had to be jump started 3 days.

Action Taken:

machine started just fine. checked the charging system we have 14V. batteries checked out at this time as well.
(South Topeka)

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	50.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary		04/07/2023 01:10:00 PM	2.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000008347

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000007907

Title: Antifreeze smell in the cab

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 03/08/2023 07:34:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)

Cause: Equipment Wear

Assigned: 03/08/2023 07:34:00 AM

Completed: 05/01/2023 08:52:00 AM

Work requested:

Operator said he could smell a strong antifreeze smell in the cab

Action Taken:

The hose coming off the bottom of the antifreeze reservoir was loose and leaking. The heater core in the cab under the seat has a small leak. The heater core is on order 3-7-23

The heater core was removed and replaced with a new one.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	7.50
Total Part Cost:	5.05	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	187.50		
Non-inv \$:	233.96		
WO Cost:	426.51	Total Hrs:	7.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		03/08/2023 07:47:00 AM	1.00			
Bo		05/01/2023 07:06:00 AM	6.50			

Parts

Detail

Date Printed: 11/07/2025



0000007907

Part #	Name	Location	Quantity	Unit	Usage Type	Description
0000000006	Red Anti Freeze 50/50 Haas Crane Equipment	Maintenance Shop	0.50	gallon	Dispatched	
	United Rentals Invoice#: 217003303		1.00		Dispatched	Qty:1 Heater Core

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000007468

Title: Fix items found on check in

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 02/08/2023 06:57:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)

Cause: Equipment Wear

Assigned: 02/08/2023 06:57:00 AM

Completed: 02/20/2023 08:43:00 AM

Work requested:

Fix items found on check in: hydraulic leaks around fittings by the hydraulic pump, serpentine belt squeaking

Action Taken:

Hose fittings at the top of the hydraulic pump were resealed where it was leaking, a section of the case is leaking between the hydraulic pump case sections (that was not fixed at this time). The serpentine belt and tensioner were replaced.

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	4.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	112.50		
Non-inv \$:	252.48		
WO Cost:	364.98	Total Hrs:	4.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		02/08/2023 07:09:00 AM	1.25			
Bo		02/20/2023 08:38:00 AM	3.25			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
--------	------	----------	----------	------	------------	-------------

Detail

Date Printed: 11/07/2025



0000007468

United Rentals Invoice#:21609 3061-001	1.00	Dispatched	Qty: 1 Fan Belt, Cummins belt 3289179
United Rentals Invoice#:21600 5767-001	1.00	Dispatched	Qty: 1 Belt Tensioner 3976834

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000007467

Title: Check in and prep for rent

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 02/08/2023 06:54:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Inspections

Cause: Equipment Wear

Assigned: 02/08/2023 06:54:00 AM

Completed: 02/20/2023 08:35:00 AM

Work requested:

Check in and prep for rent

Action Taken:

Machine was checked in and made rent ready

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	75.00		
Non-inv \$:	0.00		
WO Cost:	75.00	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo		02/08/2023 08:10:00 AM	3.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000007467

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000006974
Title: Customer damage
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Equipment Damage
Originated: 12/20/2022 04:21:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Customer Damage
Assigned: 12/20/2022 04:21:00 PM
Completed: 01/12/2023 01:25:00 PM

Work requested:

Customer damage: the right mirror (one mounted to the engine compartment door) is broken

Action Taken:

Mirror was replaced

Comments:

Total Labor Cost:	25.00	Total Labor Hours:	1.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	32.26		
WO Cost:	57.26	Total Hrs:	1.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		01/12/2023 01:25:00 PM	1.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United Rentals		1.00		Dispatched	Qty:1 Right mirror

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000006974

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006973

Work Order #: 0000006973

Title: Fix items found on check in

Origin: Non-PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Part Damage/Failure

Originated: 12/20/2022 04:19:00 PM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)

Cause: Equipment Wear

Assigned: 12/20/2022 04:19:00 PM

Completed: 01/12/2023 04:59:00 PM

Work requested:

Fix items found on check in: three of the front lights are not working, the latch for the top have of the cab door needs replaced

Action Taken:

Headlights were replaced, the door latch was modified and replaced

Comments:

Total Labor Cost:	162.50	Total Labor Hours:	6.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	184.97		
WO Cost:	347.47	Total Hrs:	6.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		01/09/2023 04:17:00 PM	6.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	United Rentals Invoice#: 214433807-001		1.00		Dispatched	Qty:1 left hand latch, Qty:1 latch stiffener, Qty:1 left hand door lever

Detail

Date Printed: 11/07/2025



0000006973

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006832

Work Order #: 0000006832
Title: Forklift back from one month rental. Please check
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 12/07/2022 07:48:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jeff Cowan
Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 12/07/2022 12:33:00 PM
Completed: 01/12/2023 05:01:00 PM

Work requested:

Forklift back from one month rental. Please check in and have machine rent ready

Action Taken:

Comments:

Total Labor Cost:	50.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	50.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		01/12/2023 05:00:00 PM	2.00			

Parts

None

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000006832

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006672

Work Order #: 0000006672
Title: Outriggers not working properly. Please stop by
a
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Other
Originated: 11/21/2022 11:35:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jeff Cowan
Work Type: Breakdown Maintenance
Cause: Unknown
Assigned: 11/21/2022 11:37:00 AM
Completed: 11/22/2022 01:42:00 PM

Work requested:

Outriggers not working properly. Please stop by and check out.

Lift is located at the project with multiple duplexes being built on N Topeka Blvd next to Northland Church.

Action Taken:

the potentiometer had been turned way down. turned it back up and everything works fine.

Comments:

Total Labor Cost:	31.25	Total Labor Hours:	1.25
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	31.25	Total Hrs:	1.25
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		11/22/2022 01:39:00 PM	1.25			

Parts

None

Equipment Usage

Detail

Date Printed: 11/07/2025



0000006672

None

Tasks/Steps

None

Documents

None

Safety Programs

None



Detail

Date Printed: 11/07/2025



0000006466

Work Order #: 0000006466
Title: Fix items found on check in
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 10/31/2022 03:45:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 10/31/2022 03:45:00 PM
Completed: 11/03/2022 03:32:00 PM

Work requested:

Fix items found on check in:

Boom lift cylinder fittings leaking

Lights not working

Action Taken:

Hydraulic fittings were tightened and the switch for the lights was changed out

Comments:

Total Labor Cost:	50.00	Total Labor Hours:	2.00
Total Part Cost:	17.28	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	67.28	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		10/31/2022 03:50:00 PM	2.00			

Parts

Detail

Date Printed: 11/07/2025



0000006466

Part #	Name	Location	Quantity	Unit	Usage Type	Description
0315	Schaeffer's 315 Simplex Supreme	Maintenance Shop	4.00	quart	Dispatched	

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006465

Work Order #: 0000006465
Title: Check in and prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 10/31/2022 03:43:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Equipment Wear
Assigned: 10/31/2022 03:43:00 PM
Completed: 11/03/2022 03:40:00 PM

Work requested:

Check in and prep for rent

Action Taken:

Machine was checked in and made rent ready

Comments:

Total Labor Cost:	75.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	75.00	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		10/31/2022 03:48:00 PM	1.50			
Bo Hartford		11/02/2022 04:36:00 PM	1.50			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000006465

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006220

Work Order #: 0000006220
Title: weekly inspection
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Equipment Damage
Originated: 10/05/2022 01:20:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Inspections
Cause: Equipment Wear
Assigned: 10/05/2022 01:20:00 PM
Completed: 10/05/2022 01:29:00 PM

Work requested:

weekly inspection

Action Taken:

weekly inspection "Blue"

Comments:

Total Labor Cost:	37.50	Total Labor Hours:	1.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	37.50	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		10/05/2022 01:29:00 PM	1.50			

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000006220

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000006110
Title: (ST #H157) 300 Hour Service
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 09/27/2022 09:09:00 AM
Expected: 10/04/2022 11:59:00 PM

Source Type: Meter Title
WO Status: Completed
Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 09/27/2022 09:09:00 AM
Completed: 09/27/2022 02:23:00 PM

Work requested:

Complete 300 Hour service for lift.

Action Taken:

All filters and oil changed, all items of 300 HR service complete

Comments:

Total Labor Cost:	62.50	Total Labor Hours:	2.50
Total Part Cost:	294.99	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	357.49	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.
2	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		09/27/2022 02:22:00 PM	2.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
84201	Carquest Hydraulic Filter	Maintenance Shop	1.00	each	Dispatched	
93767	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000006110

44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	11.00	quart	Dispatched
-------	--------------------------------------	------------------	-------	-------	------------

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
	Drain old oil. Replace oil filter. Refill oil.			
2	Instruction	Air Filter	Yes	
	Replace Air Filter.			
3	Instruction	Fluid Check	Yes	
	Check that all fluids are at the proper level.			
4	Instruction	Grease	Yes	
	Grease all greasable points on lift.			
5	Instruction	Leaks	Yes	
	Check for any leaks.			
6	Instruction	Radiator	Yes	
	Blow out radiator.			
7	Instruction	Inspect	Yes	
	Inspect lift for any damaged/missing parts.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006086

Work Order #: 0000006086
Title: ST #H157
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Leak
Originated: 09/24/2022 02:51:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Stephen Gilbert

Work Type: Breakdown Maintenance
Cause: Unknown
Assigned: 09/24/2022 02:51:00 PM
Completed: 09/27/2022 02:59:00 PM

Work requested:

- leaking hydraulic fluid
- Serpentine belt squeaking
- Other items found during repairs

Action Taken:

Fixed hydraulic leak, test port o ring was leaking under the cap. New serpentine belt was put on to fix the squeaking. The front yoke seal has an oil seep, checked fluid level in diff and it was over full. The fan shroud was missing half the bolts and a hose clamp that holds a hose out of the fan was not bolted down, all of which was repaired.

Comments:

Total Labor Cost:	100.00	Total Labor Hours:	4.00
Total Part Cost:	12.96	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	55.28		
WO Cost:	168.24	Total Hrs:	4.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.
2	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
----------	------------	----------	---------	----	----------------	-------------

Detail

Date Printed: 11/07/2025



0000006086

Bo Hartford 09/27/2022 02:22:00 PM 4.00

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
0315	Schaeffer's 315 Simplex Supreme	Maintenance Shop	3.00	quart	Dispatched	
	Napa Auto Parts		1.00		Dispatched	Qty:1 Serpentine belt 25-080670

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000006076

Work Order #: 0000006076
Title: fan belt is squealing
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Equipment Damage
Originated: 09/23/2022 03:23:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 09/23/2022 03:23:00 PM
Completed: 09/23/2022 03:29:00 PM

Work requested:

fan belt is squealing

Action Taken:

cleaned the rubber out of the pullies and made sure we didn't have something trying to lock up. its working now. but we may need to change the belt again if it continues to be an issue

Comments:

Total Labor Cost:	25.00	Total Labor Hours:	1.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	25.00	Total Hrs:	1.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		09/23/2022 03:29:00 PM	1.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000006076

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000005765

Work Order #: 0000005765
Title: check in and prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 08/16/2022 08:45:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Bo Hartford

Work Type: Inspections
Cause: Scheduled Maintenance
Assigned: 08/16/2022 08:45:00 AM
Completed: 08/16/2022 09:03:00 AM

Work requested:

Check in and prep for rent

Action Taken:

Machine washed and fueled

Comments:

Total Labor Cost:	150.00	Total Labor Hours:	2.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	150.00	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		08/16/2022 09:00:00 AM	2.00			

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000005765

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000005581

Work Order #: 0000005581
Title: boom won't come down lines in boom pinched
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 07/28/2022 12:37:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Equipment Wear
Assigned: 07/28/2022 12:37:00 PM
Completed: 08/16/2022 08:30:00 AM

Work requested:

replace boom lines that are bad and replace holding valves

Action Taken:

Boom lines and holding valves were replaced. Both cab fans were replaced.

Comments:

Total Labor Cost:	450.00	Total Labor Hours:	6.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	1169.55		
WO Cost:	1619.55	Total Hrs:	6.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Bo Hartford	Maintenance		bhartford@hmeinc.net	0.00	HME Inc.
2	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Bo Hartford		08/16/2022 08:27:00 AM	6.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	UR 208958155-001		1.00		Dispatched	Hose Assy. 1001097038Cartridge Valve 1001231674

Detail

Date Printed: 11/07/2025



0000005581

UR #208612501- 001	1.00	Dispatched	Condenser fans 91514295 qty 2
--------------------------	------	------------	----------------------------------

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000005498

Work Order #: 0000005498
Title: Belt Squealing
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Bad Bearing
Originated: 07/18/2022 11:57:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Lance Buchman

Work Type: Breakdown Maintenance
Cause: Defective Part
Assigned: 07/18/2022 11:57:00 AM
Completed: 07/27/2022 10:57:00 AM

Work requested:

Belt Squealing bad

Action Taken:

Replaced belt tensioner.

Comments:

Total Labor Cost:	56.25	Total Labor Hours:	0.75
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	215.97		
WO Cost:	272.22	Total Hrs:	0.75
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Cody Dick	Maintenance		cdick@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Cody Dick		07/18/2022 12:15:00 PM	0.75			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Hoyts Truck Center		1.00		Dispatched	Belt tensioner #5259022

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000005498

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000005476

Work Order #: 0000005476
Title: prep for rent
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 07/15/2022 03:09:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Inspections
Cause: Accidental Damage
Assigned: 07/15/2022 03:09:00 PM
Completed: 07/15/2022 03:15:00 PM

Work requested:

prep for rent

Action Taken:

clean and prep for rent. also charged A/C

Comments:

Total Labor Cost:	187.50	Total Labor Hours:	2.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	187.50	Total Hrs:	2.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		07/15/2022 03:14:00 PM	2.50			

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000005476

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000004785

Work Order #: 0000004785
Title: machine is down
Origin: Non-PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Part Damage/Failure
Originated: 04/29/2022 12:27:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Defective Part
Assigned: 04/29/2022 12:27:00 PM
Completed: 06/22/2022 03:38:00 PM

Work requested:

no hydraulics.

Action Taken:

Comments:

JOB SITE STATED THE MACHINE STOPPED. TURNS OUT THE HYDRAULIC PUMP HAS GONE BAD ACCORDING TO THE UR MECHANIC THAT CAME OUT TO HOOK UP TO IT.

Total Labor Cost:	900.00	Total Labor Hours:	12.00
Total Part Cost:	276.48	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	1614.96		
WO Cost:	2791.44	Total Hrs:	12.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		06/22/2022 03:38:00 PM	12.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	UR 205742227-001		1.00		Dispatched	
	UR 205825289-001		1.00		Dispatched	

Detail

Date Printed: 11/07/2025



0000004785

0315	Schaeffer's 315 Simplex Supreme	Maintenance Shop	64.00 quart	Dispatched
------	---------------------------------------	------------------	-------------	------------

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000004287

Page 93 of 237

Work Order #: 0000004287

Title: Dave Watson with Watson Real Estate Development se

Origin: Non-PM

Cost Center: 4800

Priority: Critical(ASAP)

Problem: Won't Start

Originated: 02/21/2022 08:58:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Breakdown Maintenance

Cause: Unknown

Assigned: 02/21/2022 09:32:00 AM

Completed: 02/21/2022 10:15:00 AM

Work requested:

Dave Watson with Watson Real Estate Development sent me a text message this morning that the forklift wouldnt start. The lift is at 934 SW Woodbridge Place.... the on-site contact is Jose (785)670-0160. They tried to jump the machine with no luck.

Action Taken:

Went out to check out lift. Checked batteries and they are newer and were holding at 10V. Used a jump pack to start lift and it fired right off and was charging steady at 14V. Believe the lift got left with the key in the AUX. position which drew the batteries just low enough to keep from being able to start. Instructed on site contact Jose to let lift run for a while to let batteries charge back up and to try and make sure key is left in the off/stop position and not the AUX position. Lift should be good to go.

Comments:

Total Labor Cost:	75.00	Total Labor Hours:	1.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	75.00	Total Hrs:	1.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Wes Nelson	Maintenance		wnelson@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Wes Nelson		02/21/2022 10:15:00 AM	1.00			

Parts

Detail

Date Printed: 11/07/2025



0000004287

None

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003918

Work Order #: 0000003918
Title: wont start
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Won't Start
Originated: 01/03/2022 10:48:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Equipment Wear
Assigned: 01/03/2022 10:48:00 AM
Completed: 01/03/2022 11:01:00 AM

Work requested:

lift is dead and wont start

Action Taken:

Comments:

I went out to the job site and tried to jump start the lift. I couldn't get it to do anything. come to find out the batteries had completely discharged and frozen solid. I put two new batteries in and brought the old ones back to the shop to see if they'll take a charge when they thaw out.

Total Labor Cost:	225.00	Total Labor Hours:	3.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	531.00		
WO Cost:	756.00	Total Hrs:	3.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		01/03/2022 10:53:00 AM	3.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Interstate Battery		2.00		Dispatched	31P-MHD

Detail

Date Printed: 11/07/2025



0000003918

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003787

Work Order #: 0000003787
Title: (ST #H157) 300 Hour Service
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 12/09/2021 07:48:00 AM
Expected: 12/16/2021 11:59:00 PM

Source Type: Meter Title
WO Status: Completed
Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 12/09/2021 07:48:00 AM
Completed: 12/10/2021 07:52:00 AM

Work requested:
Complete 300 Hour service for lift.
Action Taken:

Cameron Service

Time is under Lance Buchman

Comments:

Total Labor Cost:	112.50	Total Labor Hours:	1.50
Total Part Cost:	202.57	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	35.15		
WO Cost:	350.22	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields	
None	

Assigned To					
Employee #	Name	Job Title	Phone	Email	Est Hrs Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00 HME, Inc.

Source						
Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor						
Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Lance Buchman		12/10/2021 06:17:00 AM	1.50			

Parts						
Part #	Name	Location	Quantity	Unit	Usage Type	Description
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	12.00	quart	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
84201	Carquest Hydraulic Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	FF63054NN replaces FF63009

Detail

Date Printed: 11/07/2025



0000003787

Baldwin Air Filter	Maintenance Shop	1.00	Dispatched
--------------------	------------------	------	------------

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
	Drain old oil. Replace oil filter. Refill oil.			
2	Instruction	Air Filter	Yes	
	Replace Air Filter.			
3	Instruction	Fluid Check	Yes	
	Check that all fluids are at the proper level.			
4	Instruction	Grease	Yes	
	Grease all greasable points on lift.			
5	Instruction	Leaks	Yes	
	Check for any leaks.			
6	Instruction	Radiator	Yes	
	Blow out radiator.			
7	Instruction	Inspect	Yes	
	Inspect lift for any damaged/missing parts.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003655

Work Order #: 0000003655
Title: repair leaks
Origin: Non-PM
Cost Center: 4800
Priority: Spare Time
Problem: Leak
Originated: 11/17/2021 07:12:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Corrective Maintenance (CM)
Cause: Equipment Wear
Assigned: 11/17/2021 07:12:00 AM
Completed: 04/07/2022 12:30:00 PM

Work requested:

repair leaks when it comes back from the job site.

Action Taken:

Comments:

this machine is currently on rent. when it comes back it needs to have some leaks repaired. the rear pinion seal is leaking. the right rear hub seal is leaking. it also has a leak that appears to be coming out of the valve body on the transmission.

This machine has had a problem blowing the fuses to the ECM. I finally got it back to the shop and pulled the fuse box and the engine wiring harness off the machine. I found 2 different spots where a total of 7 wires had been rubbed threw and shorting out. I repaired the harness and put everything back on the machine. hopefully this will be the fix we've been looking for.

Total Labor Cost:	2250.00	Total Labor Hours:	30.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	918.57		
WO Cost:	3168.57	Total Hrs:	30.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
----------	------------	----------	---------	----	----------------	-------------

Detail

Date Printed: 11/07/2025



0000003655

Gary H. McCowan	12/09/2021 09:05:00 AM	4.00
Gary H. McCowan	04/07/2022 12:28:00 PM	19.00
Cody Dick	04/07/2022 12:28:00 PM	7.00

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	UR 201707595-001		1.00		Dispatched	7028714 bushing.
	flu-con		1.00		Dispatched	new boom lines
	O'reilly		1.00		Dispatched	battery and terminal end

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003642
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 11/15/2021 08:06:00 AM
Expected: 11/20/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 11/15/2021 08:06:00 AM
Completed: 11/19/2021 03:17:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003642

Page 102 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]

Detail

Date Printed: 11/07/2025



0000003642

[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	
	FL #33	License Plate #	
	FL #H164	License Plate #	
	FL #35	License Plate #	
	FL #36	License Plate #	

Detail

Date Printed: 11/07/2025



0000003642

	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

Detail

Date Printed: 11/07/2025



0000003642

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003599
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 11/09/2021 12:51:00 PM
Expected: 11/14/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 11/09/2021 12:51:00 PM
Completed: 11/12/2021 03:12:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003599

Page 107 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]

Detail

Date Printed: 11/07/2025



0000003599

[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	
	FL #33	License Plate #	
	FL #H164	License Plate #	
	FL #35	License Plate #	
	FL #36	License Plate #	
	FL #60	License Plate #	



0000003599

	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
	Complete Weekly Lift Inspection			
2	Instruction	Problem	No	
	Note any problems found with lifts and any repairs made.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003545

Work Order #: 0000003545
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 11/01/2021 08:07:00 AM
Expected: 11/06/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 11/01/2021 08:07:00 AM
Completed: 11/04/2021 10:53:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003545

Page 111 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003545

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003545

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003545

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003511
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 10/25/2021 08:06:00 AM
Expected: 10/30/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 10/25/2021 08:06:00 AM
Completed: 10/29/2021 02:01:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003511

Page 116 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]

Detail

Date Printed: 11/07/2025



0000003511

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003511

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003511

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003459
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 10/18/2021 08:06:00 AM
Expected: 10/23/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 10/18/2021 08:06:00 AM
Completed: 10/22/2021 02:00:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003459

Page 121 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]

Detail

Date Printed: 11/07/2025



0000003459

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003459

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003459

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003420

Work Order #: 0000003420
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 10/11/2021 08:07:00 AM
Expected: 10/16/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 10/11/2021 08:07:00 AM
Completed: 10/14/2021 11:39:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003420

Page 126 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003420

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	



0000003420

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003420

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003335

Work Order #: 0000003335
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 09/27/2021 08:06:00 AM
Expected: 10/02/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 09/27/2021 08:06:00 AM
Completed: 10/08/2021 01:36:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003335

Page 131 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003335

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	



0000003335

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003335

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				
Documents				
None				
Safety Programs				
None				

Detail

Date Printed: 11/07/2025



0000003321

Page 135 of 237

Work Order #: 0000003321

Title: Please check in - go through machine and get it re

Origin: Non-PM

Cost Center: 4800

Priority: High(1-3 days)

Problem: Planned

Originated: 09/23/2021 07:38:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 09/23/2021 07:44:00 AM

Completed: 10/19/2021 04:00:00 PM

Work requested:

Please check in - go through machine and get it rental ready. Gary is aware of some of the issues needing to be addressed.

Action Taken:

Comments:

this machine has has a hydraulic leak at the cooler.

tires are in bad shape one has a split down the side.

I took the radiator and inner cooler out and had them cleaned. ordered a new hydraulic/trans cooler and replaced it.

we exchanged tires with another machine in the yard so it should be good to go.

Total Labor Cost:	825.00	Total Labor Hours:	11.00
Total Part Cost:	69.12	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	1265.16		
WO Cost:	2159.28	Total Hrs:	11.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		10/05/2021 09:56:00 AM	5.00			pull radiator for repair
Gary H. McCowan		10/19/2021 03:59:00 PM	6.00			



0000003321

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	united rentals		1.00		Dispatched	
Cenex HDRED50/50 120GAL	Cenex Red Anti Freeze 50/50 HME	Maintenance Shop	5.00	gallon	Dispatched	
0315	Schaeffer's 315 Simplex Supreme	Maintenance Shop	6.00	quart	Dispatched	

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003308
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 09/20/2021 08:06:00 AM
Expected: 09/25/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 09/20/2021 08:06:00 AM
Completed: 09/24/2021 01:44:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003308

Page 138 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]

Detail

Date Printed: 11/07/2025



0000003308

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003308

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003308

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003261
Title: wont start
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Equipment Damage
Originated: 09/14/2021 02:36:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Equipment Wear
Assigned: 09/14/2021 02:36:00 PM
Completed: 09/14/2021 02:41:00 PM

Work requested:

crank no start

Action Taken:

Comments:

This machine would crank over but wouldn't start it was throwing a code for can buss no ecu communication I found some wiring that was rubbed through and grounding causing a dead short. repaired that and replaced the blown fuses everything seemed to be good on it when I left.

Total Labor Cost:	375.00	Total Labor Hours:	5.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	375.00	Total Hrs:	5.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		09/14/2021 02:38:00 PM	5.00			

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000003261

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003249
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 09/13/2021 08:07:00 AM
Expected: 09/18/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 09/13/2021 08:07:00 AM
Completed: 09/17/2021 01:56:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003249

Page 145 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003249

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	



0000003249

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003249

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				
Documents				
None				
Safety Programs				
None				

Detail

Date Printed: 11/07/2025



Work Order #: 0000003230
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 09/06/2021 08:06:00 AM
Expected: 09/11/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 09/06/2021 08:06:00 AM
Completed: 09/10/2021 01:40:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003230

Page 150 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]

Detail

Date Printed: 11/07/2025



0000003230

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003230

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003230

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003200
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 08/30/2021 08:06:00 AM
Expected: 09/04/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 08/30/2021 08:06:00 AM
Completed: 09/03/2021 01:28:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003200

Page 155 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]

Detail

Date Printed: 11/07/2025



0000003200

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003200

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps



0000003200

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				
Documents				
None				
Safety Programs				
None				

Detail

Date Printed: 11/07/2025



Work Order #: 0000003177
Title: hydraulic leak
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Leak
Originated: 08/23/2021 04:56:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Gary H. McCowan

Work Type: Breakdown Maintenance
Cause: Accidental Damage
Assigned: 08/23/2021 04:56:00 PM
Completed: 08/23/2021 05:04:00 PM

Work requested:

repair hydraulic leak

Action Taken:

Comments:

the steel hydraulic line on the side of the stabilizer cylinder had been ripped off. I removed the cylinder and brought it back to the shop. I took it all apart so we didn't damage the seals during the repair. we welded in a new steel line on and put it back together. It is back on the machine now and working as it should.

Total Labor Cost:	825.00	Total Labor Hours:	11.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	26.91		
WO Cost:	851.91	Total Hrs:	11.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		08/23/2021 04:58:00 PM	10.00			
Lance Buchman		08/23/2021 05:04:00 PM	1.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	flu-con		1.00		Dispatched	steel hydraulic line.

Detail

Date Printed: 11/07/2025



0000003177

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003172
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 08/23/2021 08:07:00 AM
Expected: 08/28/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 08/23/2021 08:07:00 AM
Completed: 08/27/2021 01:42:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003172

Page 162 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003172

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	



0000003172

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003172

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003128
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 08/16/2021 08:06:00 AM
Expected: 08/21/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 08/16/2021 08:06:00 AM
Completed: 08/20/2021 01:44:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003128

Page 167 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003128

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003128

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003128

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003088
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 08/09/2021 08:06:00 AM
Expected: 08/14/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 08/09/2021 08:06:00 AM
Completed: 08/13/2021 01:57:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003088

Page 172 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003088

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	



0000003088

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003088

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000003082

Work Order #: 0000003082

Title: (ST #H157) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 08/06/2021 02:15:00 PM

Expected: 08/13/2021 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 08/06/2021 02:15:00 PM

Completed: 08/09/2021 06:45:00 PM

Work requested:

Complete 300 Hour service for lift.

Action Taken:

Serviced By Jakob Ridder

Comments:

Total Labor Cost:	112.50	Total Labor Hours:	1.50
Total Part Cost:	100.06	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	212.56	Total Hrs:	1.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Jakob Ridder		08/09/2021 06:45:00 PM	1.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	8.00	quart	Dispatched	

Equipment Usage

None

Tasks/Steps

Type	Name/Description	Done	Document
------	------------------	------	----------



0000003082

1	Instruction	Oil Change	Yes
	Drain old oil. Replace oil filter. Refill oil.		
2	Instruction	Air Filter	Yes
	Replace Air Filter.		
3	Instruction	Fluid Check	Yes
	Check that all fluids are at the proper level.		
4	Instruction	Grease	Yes
	Grease all greasable points on lift.		
5	Instruction	Leaks	Yes
	Check for any leaks.		
6	Instruction	Radiator	Yes
	Blow out radiator.		
7	Instruction	Inspect	Yes
	Inspect lift for any damaged/missing parts.		

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003054
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 08/02/2021 08:07:00 AM
Expected: 08/07/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 08/02/2021 08:07:00 AM
Completed: 08/06/2021 02:08:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003054

Page 179 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003054

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003054

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003054

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000003009
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 07/26/2021 08:06:00 AM
Expected: 07/31/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 07/26/2021 08:06:00 AM
Completed: 07/30/2021 01:26:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000003009

Page 184 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000003009

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000003009

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000003009

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002971

Work Order #: 0000002971
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 07/19/2021 08:06:00 AM
Expected: 07/24/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 07/19/2021 08:06:00 AM
Completed: 07/23/2021 02:02:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000002971

Page 189 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000002971

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	



0000002971

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000002971

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002933
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 07/12/2021 08:06:00 AM
Expected: 07/17/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 07/12/2021 08:06:00 AM
Completed: 07/12/2021 06:02:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000002933

Page 194 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000002933

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000002933

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000002933

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002909
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 07/05/2021 08:06:00 AM
Expected: 07/10/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 07/05/2021 08:06:00 AM
Completed: 07/09/2021 02:06:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000002909

Page 199 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]



0000002909

[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]
[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	

Detail

Date Printed: 11/07/2025



0000002909

	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000002909

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002874
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Other
Originated: 06/28/2021 08:07:00 AM
Expected: 07/03/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 06/28/2021 08:07:00 AM
Completed: 07/02/2021 01:24:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #14	HME Metal Sales	HME Metal Sales	Komatsu	FG25T-12	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #19	Cycle Zone	Cycle Zone	Clark	C500YS80	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000002874

Page 204 of 237

[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #63	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #64	HME, Inc.	Building #1	Yale	GLC050RFNUA E084	[N/A]
[N/A]	FL #65	TFI Structural Shop	TFI Structural Shop	Hyster	S155XL	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #13	HME, Inc.	Building #1	SkyTrak	10042	[N/A]
[N/A]	ST #SZ166	Six Zero	Six Zero	SkyJack	SJ1056TH	[N/A]

Detail

Date Printed: 11/07/2025



0000002874

[N/A]	ST #H168	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Xtreme	XR1255	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H175	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	FL #H196	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Combilift	C6000	[N/A]
[N/A]	ST #F198	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #F199	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #SZ197	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]
[N/A]	ST #F200	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #14	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #19	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	
	FL #33	License Plate #	
	FL #H164	License Plate #	
	FL #35	License Plate #	
	FL #36	License Plate #	
	FL #60	License Plate #	



0000002874

	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #63	License Plate #
	FL #64	License Plate #
	FL #65	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
	ST #H132	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H145	License Plate #
	ST #H151	License Plate #
	ST #H152	License Plate #
	ST #H156	License Plate #
	ST #H157	License Plate #
	ST #13	License Plate #
	ST #SZ166	License Plate #
	ST #H168	License Plate #
	ST #H171	License Plate #
	ST #H172	License Plate #
	ST #H175	License Plate #
	ST #H195	License Plate #
	FL #H196	License Plate #
	ST #F198	License Plate #
	ST #F199	License Plate #
	ST #SZ188	License Plate #
	ST #SZ197	License Plate #
	ST #F200	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
	Complete Weekly Lift Inspection			
2	Instruction	Problem	No	
	Note any problems found with lifts and any repairs made.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002655

Work Order #: 0000002655

Title: (ST #H157) 300 Hour Service

Origin: PM

Cost Center: 4800

Priority: Medium(3-7 days)

Problem: Planned

Originated: 05/20/2021 08:28:00 PM

Expected: 05/27/2021 11:59:00 PM

Source Type: Meter Title

WO Status: Completed

Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)

Cause: Scheduled Maintenance

Assigned: 05/20/2021 08:28:00 PM

Completed: 05/30/2021 08:22:00 AM

Work requested:

Complete 300 Hour service for lift.

Action Taken:

Completed service

Comments:

Total Labor Cost:	150.00	Total Labor Hours:	2.00
Total Part Cost:	244.08	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	394.08	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Ethan Kortan	Maintenance		ekortan@hmeinc.net	0.00	HME, Inc.
2	Stephen Gilbert	Maintenance		sgilbert@hmeinc.net	0.00	

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Ethan Kortan		05/30/2021 08:20:00 AM	2.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	9.00	quart	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
84201	Carquest Hydraulic Filter	Maintenance Shop	1.00	each	Dispatched	
93769	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	

Detail

Date Printed: 11/07/2025



0000002655

FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched
-----------	------------------------	------------------	------	------	------------

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
	Drain old oil. Replace oil filter. Refill oil.			
2	Instruction	Air Filter	Yes	
	Replace Air Filter.			
3	Instruction	Fluid Check	Yes	
	Check that all fluids are at the proper level.			
4	Instruction	Grease	Yes	
	Grease all greasable points on lift.			
5	Instruction	Leaks	Yes	
	Check for any leaks.			
6	Instruction	Radiator	Yes	
	Blow out radiator.			
7	Instruction	Inspect	Yes	
	Inspect lift for any damaged/missing parts.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002620
Title: no lift capacity mark on boom
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Planned
Originated: 05/17/2021 08:25:00 AM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Andy Reddick

Work Type: Improvements
Cause: Scheduled Maintenance
Assigned: 05/17/2021 01:09:00 PM
Completed: 05/18/2021 11:56:00 AM

Work requested:
no lift capacity mark on boom
Action Taken:

Lift is labeled up like it should be

Comments:

Total Labor Cost:	75.00	Total Labor Hours:	1.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	75.00	Total Hrs:	1.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Cody Dick	Maintenance		cdick@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Cody Dick		05/18/2021 11:56:00 AM	1.00			

Parts

None

Equipment Usage

None

Tasks/Steps

None

Detail

Date Printed: 11/07/2025



0000002620

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002611
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 05/17/2021 08:06:00 AM
Expected: 05/22/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 05/17/2021 08:06:00 AM
Completed: 05/20/2021 08:32:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]



0000002611

[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]

Source Custom Fields			
No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	

Detail

Date Printed: 11/07/2025



0000002611

	FL #23	License Plate #
	FL #25	License Plate #
	FL #26	License Plate #
	FL #27	License Plate #
	FL #28	License Plate #
	FL #29	License Plate #
	FL #03	License Plate #
	FL #30	License Plate #
	FL #31	License Plate #
	FL #32	License Plate #
	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H157	License Plate #
	ST #H172	License Plate #
	ST #H195	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	Yes	
	Complete Weekly Lift Inspection			
2	Instruction	Problem	Yes	
	Note any problems found with lifts and any repairs made.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002550
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 05/10/2021 08:06:00 AM
Expected: 05/15/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 05/10/2021 08:06:00 AM
Completed: 05/14/2021 02:03:00 AM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]

Detail

Date Printed: 11/07/2025



0000002550

Page 215 of 237

[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JCB #2	Peak to Peak Engineered Railings	Peak to Peak Shop	JCB	520	[N/A]
[N/A]	JCB #3	HME, Inc.	Plasma Shop	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H132	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	8042	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H145	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrack	10054	[N/A]
[N/A]	ST #H151	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skyjack	SJ843TH	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H156	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G12-55A	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #H172	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]



0000002550

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	
	FL #23	License Plate #	
	FL #25	License Plate #	
	FL #26	License Plate #	
	FL #27	License Plate #	
	FL #28	License Plate #	
	FL #29	License Plate #	
	FL #03	License Plate #	
	FL #30	License Plate #	
	FL #31	License Plate #	
	FL #32	License Plate #	
	FL #33	License Plate #	
	FL #H164	License Plate #	
	FL #35	License Plate #	
	FL #36	License Plate #	
	FL #60	License Plate #	
	FL #61	License Plate #	
	FL #62 (Luigi)	License Plate #	
	FL #66	License Plate #	
	FL #08	License Plate #	
	JCB #1	License Plate #	
	JCB #2	License Plate #	
	JCB #3	License Plate #	
	JLG #1	License Plate #	
	JLG #2	License Plate #	
	LH #1	License Plate #	
	ST #04	License Plate #	
	ST #05	License Plate #	
	ST #06	License Plate #	
	ST #07	License Plate #	
	ST #H122	License Plate #	
	ST #H123	License Plate #	
	ST #H132	License Plate #	
HME_00519	Unit #141 (Yard Dog)	License Plate #	
	FL #H144	License Plate #	
	ST #H145	License Plate #	
	ST #H151	License Plate #	
	ST #H152	License Plate #	
	ST #H156	License Plate #	
	ST #H157	License Plate #	

Detail

Date Printed: 11/07/2025



0000002550

ST #H172 License Plate #

Labor

None

Parts

None

Equipment Usage

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002463
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 04/26/2021 08:06:00 AM
Expected: 05/01/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 04/26/2021 08:06:00 AM
Completed: 05/06/2021 06:43:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	0.00	Total Labor Hours:	0.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	0.00	Total Hrs:	0.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]



0000002463

[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JCB #2	Peak to Peak Engineered Railings	Peak to Peak Shop	JCB	520	[N/A]
[N/A]	JCB #3	HME, Inc.	Plasma Shop	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H123	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H152	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
[N/A]	ST #H195	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Genie	GTH5519	[N/A]
[N/A]	ST #SZ188	Six Zero	Six Zero	Skyjack	SJ1056TH	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	

Detail

Date Printed: 11/07/2025



0000002463

	FL #15	License Plate #
	FL #17	License Plate #
	FL #18	License Plate #
	FL #02	License Plate #
	FL #20	License Plate #
	FL #21	License Plate #
	FL #22	License Plate #
	FL #23	License Plate #
	FL #25	License Plate #
	FL #26	License Plate #
	FL #27	License Plate #
	FL #28	License Plate #
	FL #29	License Plate #
	FL #03	License Plate #
	FL #30	License Plate #
	FL #31	License Plate #
	FL #32	License Plate #
	FL #33	License Plate #
	FL #H164	License Plate #
	FL #35	License Plate #
	FL #36	License Plate #
	FL #60	License Plate #
	FL #61	License Plate #
	FL #62 (Luigi)	License Plate #
	FL #66	License Plate #
	FL #08	License Plate #
	JCB #1	License Plate #
	JCB #2	License Plate #
	JCB #3	License Plate #
	JLG #1	License Plate #
	JLG #2	License Plate #
	LH #1	License Plate #
	ST #04	License Plate #
	ST #05	License Plate #
	ST #06	License Plate #
	ST #07	License Plate #
	ST #H122	License Plate #
	ST #H123	License Plate #
HME_00519	Unit #141 (Yard Dog)	License Plate #
	FL #H144	License Plate #
	ST #H152	License Plate #
	ST #H157	License Plate #
	ST #H171	License Plate #
	ST #H195	License Plate #
	ST #SZ188	License Plate #

Labor

None

Parts

None

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000002463

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Weekly Inspection	No	
Complete Weekly Lift Inspection				
2	Instruction	Problem	No	
Note any problems found with lifts and any repairs made.				

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002386

Work Order #: 0000002386
Title: lights not working
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Part Damage/Failure
Originated: 04/13/2021 07:10:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Jakob Ridder

Work Type: Corrective Maintenance (CM)
Cause: Unknown
Assigned: 04/13/2021 07:10:00 PM
Completed: 04/16/2021 12:58:00 AM

Work requested:

find issue with the lights

Action Taken:

Comments:

went through checked all the fuses and switch for the light. ended up replacing the light switch itself

Total Labor Cost:	37.50	Total Labor Hours:	0.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	37.50	Total Hrs:	0.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Jakob Ridder		04/13/2021 07:15:00 PM	0.50			

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000002386

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002310
Title: (ST #H157) 300 Hour Service
Origin: PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Planned
Originated: 04/06/2021 08:55:00 AM
Expected: 04/13/2021 11:59:00 PM

Source Type: Meter Title
WO Status: Completed
Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 04/06/2021 08:55:00 AM
Completed: 04/06/2021 08:59:00 AM

Work requested:
Complete 300 Hour service for lift.
Action Taken:

Comments:

Total Labor Cost:	150.00	Total Labor Hours:	2.00
Total Part Cost:	283.90	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	433.90	Total Hrs:	2.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	
2	Eric Lewis	Maintenance		elewis@hmeinc.net	0.00	

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Eric Lewis		04/07/2021 01:49:00 PM	2.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	12.00	quart	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
93769	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
93767	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	

Equipment Usage

Detail

Date Printed: 11/07/2025



0000002310

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
	Drain old oil. Replace oil filter. Refill oil.			
2	Instruction	Air Filter	Yes	
	Replace Air Filter.			
3	Instruction	Fluid Check	Yes	
	Check that all fluids are at the proper level.			
4	Instruction	Grease	Yes	
	Grease all greasable points on lift.			
5	Instruction	Leaks	Yes	
	Check for any leaks.			
6	Instruction	Radiator	Yes	
	Blow out radiator.			
7	Instruction	Inspect	Yes	
	Inspect lift for any damaged/missing parts.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002300
Title: Bad Battereis
Origin: Non-PM
Cost Center: 4800
Priority: Critical(ASAP)
Problem: Part Damage/Failure
Originated: 04/05/2021 02:25:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Lance Buchman

Work Type: Corrective Maintenance (CM)
Cause: Defective Part
Assigned: 04/05/2021 02:25:00 PM
Completed: 04/05/2021 02:30:00 PM

Work requested:

Replace both batteries

Action Taken:

Replace both group 31 batteries one went bad from age of the battery

Comments:

Total Labor Cost:	37.50	Total Labor Hours:	0.50
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	250.96		
WO Cost:	288.46	Total Hrs:	0.50
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Lance Buchman	Maintenance		lbuchman@hmeinc.net	0.00	HME, Inc.

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Lance Buchman		04/05/2021 02:28:00 PM	0.50			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	Interstate Battery Group 31		2.00		Dispatched	

Equipment Usage

None

Detail

Date Printed: 11/07/2025



0000002300

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000002291
Title: Forklifts Weekly Inspection
Origin: PM
Cost Center: 4000
Priority: Medium(3-7 days)
Problem: Planned
Originated: 04/05/2021 08:07:00 AM
Expected: 04/10/2021 11:59:00 PM

Source Type: Asset
WO Status: Completed
Originator: Forklifts Weekly Inspection

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 04/05/2021 08:07:00 AM
Completed: 04/08/2021 09:43:00 PM

Work requested:
Complete weekly lift inspection.
Action Taken:

Comments:

Total Labor Cost:	375.00	Total Labor Hours:	5.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	375.00	Total Hrs:	5.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary D. McCowan	Maintenance		garydmccowan@gmail.com	0.00	HME, Inc.
2	Jakob Ridder	Maintenance		jridder@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	CL #1	HME, Inc.	Main Paint Shop	Combilift	10000XL-D	[N/A]
[N/A]	CL #2	HME, Inc.	Building #1	Combilift	10000XL-D	[N/A]
[N/A]	CL #3	HME, Inc.	Loading Department	Combilift	C55000	[N/A]
[N/A]	CL #4	HME, Inc.	HME, Inc. South	Combilift	C10000XL	[N/A]
[N/A]	FL #15	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #17	HME, Inc.	Press Brake Shop	Komatsu	FG25TLP-12	[N/A]
[N/A]	FL #18	HME, Inc.	Miscellaneous Metal Shop	Hyster	H60XL	[N/A]
[N/A]	FL #02	HME, Inc.	Building #1	Toyota	02-3FG40	[N/A]
[N/A]	FL #20	Cycle Zone	Cycle Zone	Komatsu	FG25T-12	[N/A]
[N/A]	FL #21	HME, Inc.	Main Paint Shop	Komatsu	FG25T-12	[N/A]
[N/A]	FL #22	HME, Inc.	Parts Room	Komatsu	FG35BCS-8	[N/A]
[N/A]	FL #23	TFI Structural Shop	TFI Structural Shop	Komatsu	FG30HT-14	[N/A]
[N/A]	FL #25	HME, Inc.	Miscellaneous Metal Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #26	Peak to Peak Engineered Railings	Peak to Peak Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #27	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #28	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]



0000002291

[N/A]	FL #29	HME, Inc.	Structural Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #03	HME, Inc.	Structural Shop	Nissan	CPH02A25V (C50Y)	[N/A]
[N/A]	FL #30	HME, Inc.	Structural Shop	Daewoo	G25E-3	[N/A]
[N/A]	FL #31	HME, Inc.	Building #1	Daewoo	G25E-3	[N/A]
[N/A]	FL #32	HME, Inc.	Main Paint Shop	Komatsu	FG25T-14	[N/A]
[N/A]	FL #33	HME, Inc.	Saw Building	Daewoo	D25S-5	[N/A]
[N/A]	FL #H164	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Daewoo	G25E-5	[N/A]
[N/A]	FL #35	HME, Inc.	HME, Inc. South	Clark	C25CL	[N/A]
[N/A]	FL #36	HME, Inc.	Structural Shop	Daewoo	D25S-5	[N/A]
[N/A]	FL #60	TFI Machine Shop	TFI Machine Shop	Hyster	H50XM	[N/A]
[N/A]	FL #61	TFI Structural Shop	TFI Cut Shop	Yale	GLC155CANGB E098	[N/A]
[N/A]	FL #62 (Luigi)	HME, Inc.	Maintenance Shop	Namco	LC20-15	[N/A]
[N/A]	FL #66	TFI Machine Shop	TFI Machine Shop	BT Prime-mover	RR34B	[N/A]
[N/A]	FL #08	HME, Inc.	Plate Processing Room	Manitou	MSI30LPG	[N/A]
[N/A]	JCB #1	HME, Inc.	Plate Processing Room	JCB	520	[N/A]
[N/A]	JCB #2	Peak to Peak Engineered Railings	Peak to Peak Shop	JCB	520	[N/A]
[N/A]	JCB #3	HME, Inc.	Plasma Shop	JCB	520	[N/A]
[N/A]	JLG #1	HME, Inc.	Loading Department	Skytrak	8042	[N/A]
[N/A]	JLG #2	HME, Inc.	Loading Department	JLG	G9-43A	[N/A]
[N/A]	LH #1	HME, Inc.	Loading Department	Lull	6K-37	[N/A]
[N/A]	ST #04	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #05	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #06	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #07	HME, Inc.	Loading Department	Skytrak	10054	[N/A]
[N/A]	ST #H122	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]
HME_00519	Unit #141 (Yard Dog)	HME, Inc.	Trucking Department	Ottawa	[N/A]	HME_00519
[N/A]	FL #H144	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Doosan	G30P-5	[N/A]
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]
[N/A]	ST #H171	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	Skytrak	10054	[N/A]

Source Custom Fields			
No	Name	Custom Field	Value
	CL #1	License Plate #	
	CL #2	License Plate #	
	CL #3	License Plate #	
	CL #4	License Plate #	
	FL #15	License Plate #	
	FL #17	License Plate #	
	FL #18	License Plate #	
	FL #02	License Plate #	
	FL #20	License Plate #	
	FL #21	License Plate #	
	FL #22	License Plate #	



0000002291

FL #23	License Plate #
FL #25	License Plate #
FL #26	License Plate #
FL #27	License Plate #
FL #28	License Plate #
FL #29	License Plate #
FL #03	License Plate #
FL #30	License Plate #
FL #31	License Plate #
FL #32	License Plate #
FL #33	License Plate #
FL #H164	License Plate #
FL #35	License Plate #
FL #36	License Plate #
FL #60	License Plate #
FL #61	License Plate #
FL #62 (Luigi)	License Plate #
FL #66	License Plate #
FL #08	License Plate #
JCB #1	License Plate #
JCB #2	License Plate #
JCB #3	License Plate #
JLG #1	License Plate #
JLG #2	License Plate #
LH #1	License Plate #
ST #04	License Plate #
ST #05	License Plate #
ST #06	License Plate #
ST #07	License Plate #
ST #H122	License Plate #
HME_00519	Unit #141 (Yard Dog)
FL #H144	License Plate #
ST #H157	License Plate #
ST #H171	License Plate #

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Jakob Ridder		04/08/2021 01:26:00 AM	3.00			
Jakob Ridder		04/08/2021 09:42:00 PM	2.00			

Parts

None

Equipment Usage

None

Tasks/Steps

Type	Name/Description	Done	Document
1	Instruction Complete Weekly Lift Inspection	Weekly Inspection	No
2	Instruction Note any problems found with lifts and any repairs made.	Problem	No

Documents

None

Detail

Date Printed: 11/07/2025



0000002291

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000002216

Page 232 of 237

Work Order #: 0000002216

Title: Please go through check in process. forklift been

Origin: Non-PM

Cost Center: 4800

Priority: High(1-3 days)

Problem: Planned

Originated: 03/23/2021 09:52:00 AM

Expected:

Source Type: Asset

WO Status: Completed

Originator: Jeff Cowan

Work Type: Inspections

Cause: Scheduled Maintenance

Assigned: 03/24/2021 08:53:00 AM

Completed: 04/09/2021 07:21:00 AM

Work requested:

Please go through check in process. forklift been on long term rent. Paperwork, photos, cleaned up, fuel (bill this to Haas crane and mark as Job # 19-088 if possible...or mark down ID number of machine), tagged. I know receiving was in need of another forklift.... wanted maintenance to at least look at machine prior to it being used since its been on a job 6+ months.

Action Taken:

Comments:

all is good now these lift is in the yard now

Total Labor Cost:	300.00	Total Labor Hours:	4.00
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	735.30		
WO Cost:	1035.30	Total Hrs:	4.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Eric Lewis	Maintenance		elewis@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Eric Lewis		04/09/2021 07:18:00 AM	4.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
	flu-con		1.00		Dispatched	
	wiese usa		1.00		Dispatched	

Detail

Date Printed: 11/07/2025



0000002216

Equipment Usage

None

Tasks/Steps

None

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



0000000662

Work Order #: 0000000662
Title: (ST #H157) 300 Hour Service
Origin: PM
Cost Center: 4800
Priority: Medium(3-7 days)
Problem: Planned
Originated: 05/27/2020 12:20:00 PM
Expected: 06/03/2020 11:59:00 PM

Source Type: Meter Title
WO Status: Completed
Originator: (ST #H157) 300 Hour Service

Work Type: Preventive Maintenance (PM)
Cause: Scheduled Maintenance
Assigned: 05/27/2020 12:20:00 PM
Completed: 05/29/2020 02:15:00 PM

Work requested:
Complete 300 Hour service for lift.
Action Taken:

Comments:

Total Labor Cost:	300.00	Total Labor Hours:	4.00
Total Part Cost:	329.82	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	629.82	Total Hrs:	4.00
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Gary H. McCowan	Maintenance		gmccowan@hmeinc.net	0.00	HME, Inc.

Source

Name	Meter Title #	Asset	Category	Type	Min Threshold	Max Threshold
Hours	[N/A]	ST #H157	Material Handling	Hours Run	1	20000

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Gary H. McCowan		05/29/2020 02:13:00 PM	4.00			

Parts

Part #	Name	Location	Quantity	Unit	Usage Type	Description
44644	Cenex Superlube TMS 15W-40 HME	Maintenance Shop	11.00	quart	Dispatched	
84182	Carquest Oil Filter	Maintenance Shop	1.00	each	Dispatched	
84201	Carquest Hydraulic Filter	Maintenance Shop	1.00	each	Dispatched	
93769	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
93767	Carquest Air Filter	Maintenance Shop	1.00	each	Dispatched	
86965	Carquest Fuel Filter	Maintenance Shop	1.00	each	Dispatched	
FF63054NN	Fleetguard Fuel Filter	Maintenance Shop	1.00	each	Dispatched	

Equipment Usage

Detail

Date Printed: 11/07/2025



0000000662

None

Tasks/Steps

	Type	Name/Description	Done	Document
1	Instruction	Oil Change	Yes	
	Drain old oil. Replace oil filter. Refill oil.			
2	Instruction	Air Filter	Yes	
	Replace Air Filter.			
3	Instruction	Fluid Check	Yes	
	Check that all fluids are at the proper level.			
4	Instruction	Grease	Yes	
	Grease all greasable points on lift.			
5	Instruction	Leaks	Yes	
	Check for any leaks.			
6	Instruction	Radiator	Yes	
	Blow out radiator.			
7	Instruction	Inspect	Yes	
	Inspect lift for any damaged/missing parts.			

Documents

None

Safety Programs

None

Detail

Date Printed: 11/07/2025



Work Order #: 0000000628
Title: Slow tilt and hard turning
Origin: Non-PM
Cost Center: 4800
Priority: High(1-3 days)
Problem: Unknown
Originated: 05/20/2020 02:26:00 PM
Expected:

Source Type: Asset
WO Status: Completed
Originator: Casey Kirkham

Work Type: Corrective Maintenance (CM)
Cause: Unknown
Assigned: 05/20/2020 02:26:00 PM
Completed: 05/27/2020 09:54:00 AM

Work requested:

Jared Haas says this lift is slow to tilt and turns hard to the right

Action Taken:

Comments:

there is a knob that controls the tilt in the cab of these lift

Total Labor Cost:	22.50	Total Labor Hours:	0.30
Total Part Cost:	0.00	Total Other Hours:	0.00
Equipment Usage Cost	0.00		
Total Other Cost:	0.00		
External Labor \$:	0.00		
Non-inv \$:	0.00		
WO Cost:	22.50	Total Hrs:	0.30
		Est Hrs:	0.00

Custom Fields

None

Assigned To

Employee #	Name	Job Title	Phone	Email	Est Hrs	Company Name
1	Eric Lewis	Maintenance		elewis@hmeinc.net	0.00	

Source

Asset #	Name	Site	Location	Make	Model	Barcode
[N/A]	ST #H157	Haas Crane & Equipment Rentals, LLC	Haas Crane & Equipment Rentals, LLC	JLG	G10-55A	[N/A]

Source Custom Fields

No	Name	Custom Field	Value
	ST #H157	License Plate #	

Labor

Employee	Start Date	End Date	Hour(s)	OT	OT Cost Factor	Description
Eric Lewis		05/27/2020 09:53:00 AM	0.30			

Parts

None

Equipment Usage

None

Tasks/Steps

Detail

Date Printed: 11/07/2025



0000000628

None

Documents

None

Safety Programs

None