

Gill Ventures

Work Order

Date 28/08/24

Name Lms

Model 378 PTE

Hours 24240-24161

Kms

Done ☒

On Hold ☐

Unit # VT20

Next Service 24270 hours

Kms

Service ☐

Repairs ☒

Hours

- ☒ CHECK FLUIDS + TIRES
- ☒ CHECK AND REPAIR CHECK VALVES FUEL
- ☒ TIGHTEN FAN BELTS
- ☒ REPAIR FUSE BOX
- ☒ SEND TO TRUSTED
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

Total

Notes:

011-5

Date Sept 25 2023

Gill Ventures

date: ☒

Name Tanner

Work order

on hold: ☐

Model: Peterbilt Gravel Truck

Unit #: VT 20

HRG: _____

Next serv: _____ hrs

KMS: _____

_____ hrs

Description

SERVICE _____

REPAIRS ☒

Hrs.

12 Fix tarp issue

☒

14 Replace driver door window lift

☒

15 _____

16 _____

17 _____

18 _____

19 _____

20 _____

21 _____

22 _____

23 _____

24 _____

25 _____

26 _____

27 _____

28 _____

29 _____

30 _____

31 _____

32 _____

Total:

Notes:

Date: JAN 18/23

Gill Ventures

done: ☒Name: Rob

Work order

on hold: ☐Model: PETEUnit #: VT20HRS: 24019Next serv: 2 kmsKms: 140309824,269 hrs

Description

SERVICE

REPAIRS

Hrs.

REPAIR TAILGATE HINGES	✓
FILL ALCOHOL IN SECTOR	✓
CHECK TARP TAIL	✓
FIX OIL LEAK ON TRAILER HOOK UP	✓
CHECK LEAK ON PTO	✓
CHECK DIFF LEAKS (TIGHTEN BOLTS ON FRONT)	✓
TRANS CHECK PLUG (GET OUT + WELD NUT ON)	✓
FIX CAB LIGHT	✓
FIX BOX LIGHTS	✓
FIX MIRROR LIGHTS	✓
DASH LIGHTS	✓
CHECK FUSES	✓
LH TAILGATE SUPPORT	✓
DRAW AIR TANKS	✓
INSTALL AIR UP VALVE	✓
HOOD SUPPORT BRACKET	✓
FIX RH DOOR HANDLE + LATCH	✓
FIX WASHER TANK	✓

Total:

Notes:

NEEDS TIRESTARP FABRIC STRETCHED OUT OF SHAPEPTO SEEPING OIL

Date: 28/10/22

Gill Ventures

done: _____

Name: LARS + STEVE + ROBY Work order

on hold: _____

Model: CONNI BLUE VT20-PETE

Unit #: VT 20

HRS: _____

Next serv: _____ kms

Kms: _____

_____ hrs

Description

SERVICE X

REPAIRS X

- | Description | Hrs. |
|---|------|
| - FILL ALCOHOL INJECTION | ✓ |
| - CHECK OVEN UNIT | ✓ |
| - INSTALL TURBO | ✓ |
| - FIX ENGINE LEAKS | ✓ |
| - REPLACE STEERING WHEEL | ✓ |
| - REPLACE INNER DOOR HANDLE | ✓ |
| - DRIVER'S SIDE | ✓ |
| - CHECK ALL FLUIDS | ✓ |
| - REPLACE OIL PAN GASKET | ✓ |
| - OIL CHANGE + FILTER ENGINE LABEL SPRING | ✓ |
| - AIR FILTER | ✓ |
| - REPAIR TAIL GATE HINGES IN | ✓ |
| - FIX FITTING HOOK UP FOR THATCHER | ✓ |
| - PTO LEAK | ✓ |
| - HOIST LEAK | ✓ |
| - LEAK ON HYDRAULIC FLUID BOX WONT LIFT | ✓ |
| - BOTH DIFFS LEAKING | ✓ |
| - FRONT AXLE HUBS - TOP | ✓ |
| - TOP POWER STEERING | ✓ |
| - FILL PUMP TRANS MISSION | ✓ |
| - REPLACE STEERING WHEEL | ✓ |
| - CENTRE ROOF LIGHT OUT | ✓ |
| - BOX LIGHTS 3 LIGHTS OUT | ✓ |
| - RHS AIR FILTER 1 LIGHT OUT | ✓ |
| - MIRROR LIGHTS NOT WORKING | ✓ |
| - DASH LIGHTS | ✓ |
| - CHECK ALL FUSES LABEL DASH !! | ✓ |
| - GREASE WONT - TOP TIRES | ✓ |

Notes:

Total:

+ FIX REVERSE LIGHT

Date: July 24 2025

Gill Ventures

done: ☒

Name: Jason

Work order

on hold: ☐

Model: Peterbilt Snow Truck

Unit #: VT 20

MRS: 24149

Next serv: time:

Kms: 1406751

24270 hrs

Description

SERVICE ☒

REPAIRS ☐

Hrs.

1	Check all fluids	✓
2	Check lights	✓
3	check tires and air up 60psi	✓
4	check exhaust	✓
5	check belts, hose, leaks	✓
6	Drain air tanks and check for leaks	✓
7	check air filters	✓
8	check defrost, wipers, horn	✓
9	check tarp	✓
10	check front hubs	✓
11	Grease unit	✓
12	Replace Oil Fill Cap	✓
13	Replace hood latch	✓
14	Replace oil return line o-ring on turbo	✓
15	Check brakes, suspension	✓
16	Replace Solenoid for tarps	✓
17		
18		
19		
20		

Total:

Notes: