

P02-7 A971720

Date Inspection Started: 31 03 25  
Date Inspection Completed: 11 04 25  
Inspection Expiry Date: 30 04 26

Station Number: C0103  
Station Name: Diamond Ready Mix  
City: Steinbach  
Mechanic Number: M0956  
Mechanic Signature: *Danton Jukka*  
Station Phone Number: 204-326-3456

Vehicle Owner: Diamond Ready Mix Concrete Ltd.  
Address: 399 Hwy-12 North, Steinbach, MB R5G 1V1  
Phone: (204) 326-3455 FAX: (204) 326-6077

License Number: CP6676  
Prov: MB  
NSC #: ND9006467  
Odometer Reading: 921745  
Odom. Type:  km  mi

Vehicle Identification Number: 1M1AK07Y155W0107630  
Make: *Make*  
Model: *CXK63*  
Year: 2003  
Unit #: 7230

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

Confirmed legible Vehicle Identification Number on vehicle

**THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED**

Truck  KGS   Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

| P | R | Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section  |
|---|---|--|
| X | X | Section 1 - Power Train: Defects (if any) <i>12A, Fuel tank leaking</i>  |
| X | X | Section 2 Suspension: Defects (if any) <i>2C, torque Rod Busting 1</i>   |
| X | X | Section 3 - Brake Systems: <i>3H SA</i><br>Defects (if any) <i>1d, air filter 2g, air leak, locking valve 16c, BRAKE S/P, brake pad rotors 16d, BRAKE adjust nut 19a, ABS light on</i><br>Brake Inspection Type: A B <input checked="" type="checkbox"/> D E Circle appropriate Letter for Internal Brake Component Inspection |
| X | X | Section 4 - Steering: Defects (if any) <i>1a, Steering leak</i>  |
| X | X | Section 5 - Instruments & Auxiliary Equipment: Defects (if any) <i>7b, wipers torn</i>   |
| X | X | Section 6 - Lamps: Defects (if any) <i>1b, headlight aim</i>   |
| X | X | Section 7 - Electrical System: Defects (if any) <i>1a, dirt lock harness loose &amp; on Battery cover</i>  |
| X | X | Section 8 - Body: Defects (if any) <i>4d, edges on 1/2 fenders 13b cracked wind shield</i>   |
| X | X | Section 9 - Tire & Wheel: Defects (if any) <i>4a tire pressures</i>  |
| X |   | Section 10 - Coupling Devices: Defects (if any)  |

  

| Axle | Tread Depth |    |           |    | Air Pressure |     |           |     |
|------|-------------|----|-----------|----|--------------|-----|-----------|-----|
|      | Initial     |    | Corrected |    | Initial      |     | Corrected |     |
|      | L           | R  | L         | R  | L            | R   | L         | R   |
| 1    | 13          | 13 |           |    | 80           | 110 | 110       |     |
| 2    | 11          | 10 | 9         | 8  | 100          | 100 | 100       | 105 |
| 3    | 15          | 17 | 13        | 15 | 100          | 80  | 100       | 100 |
| 4    |             |    |           |    |              |     |           |     |
| 5    |             |    |           |    |              |     |           |     |

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: *Duplicate cert # 03894710 Decal # 0902544  
Station # A0205*

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Date: \_\_\_\_\_  
Signature