04082927

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL NOT VALID WITHOUT

Manitoba C072833

Date Inspection Started: 06 (DAY) 05 (MO.) 26 (YR.)

Date Inspection Completed: 06 (DAY) 05 (MO.) 26 (YR.)

Inspection Expiry Date: 31 (DAY) 05 (MO.) 27 (YR.)

Station Number: A19718 **Station Name:** Oakwood Ind Inc **City:** St Andrews

Mechanic Number: M26662 **Mechanic Signature:** [signature] **Station Phone Number:** 338-2901

Vehicle Owner: Strada Recycling

Address | **City** | **Province** | **Postal Code** | **Phone**

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: 377DLY **Prov.:** MB **NSC #:** **Odometer Reading:** **Odom. Type:** ☐ km ☐ mi

Vehicle Identification Number: 4ZEGH2630DL035878 **Make:** LOAD TRAIL **Model:** **Year:** 13 **Unit #:**

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS ____Truck Tractor __X__Trailer ____Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** (3H) 3A (Circle Brake Type) Defects (if any): X10A - Repair Seized lever arm LM RM
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any): X1H - Replace LR side marker
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any): X4A - Correct tire pressure
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	5/32	5/32	12.040	12.039		
2	6/32	5/32	12.037	12.045		
3	6/32	6/32	12.041	12.042		
4						
5						
	Final Measurement					

Axle	Tread Depth (mm) Initial L	Initial R	Corrected L	Corrected R	Air Pressure Initial L	Initial R	Corrected L	Corrected R
1	10	8			80	80	100	100
2	11	11			80	80	100	100
3	7	8			80	80	100	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-06/25)

PRESENT THIS COPY WHEN REGISTERING VEHICLE