

MAINTENANCE HISTORY REPORT

UNIT # 171022

LAST 60 MONTHS OF MAINTENANCE ACTIVITY

VIN 1GRAA7228HE703214 Year, Make, Model 2017 GDT FROZEN

Vehicle Description 36FT T/A REEFER TRAILER

Engine N/A **Transmission** N/A Color WHITE

Odometer 310,534 miles

DATE	MILEAGE	DESCRIPTION
08/20/25	310,534 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
08/20/25	310,534 miles	COMPLETE T1G - TRAILER AND LIFTGATE, FEDERAL ANNUAL INSPECTION
06/14/25	291,455 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
06/14/25	291,455 miles	COMPLETE T1G - TRAILER AND LIFTGATE, FEDERAL ANNUAL INSPECTION
03/27/25	286,671 miles	COMPLETE TR2 - TRAILER REEFER, MAINTENANCE INSPECTION
03/27/25	286,671 miles	COMPLETE T1G - TRAILER AND LIFTGATE, FEDERAL ANNUAL INSPECTION
03/27/25	286,671 miles	REPLACE HYDRAULIC LIFT SYSTEM MOTOR - ELECTRIC
01/17/25	281,181 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
01/17/25	281,181 miles	COMPLETE T1G - TRAILER AND LIFTGATE, FEDERAL ANNUAL INSPECTION
10/19/24	272,925 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
10/19/24	272,925 miles	COMPLETE T1G - TRAILER AND LIFTGATE, FEDERAL ANNUAL INSPECTION
07/25/24	263,999 miles	REPLACE BRAKE LINING/SHOE FRONT AXLE (BOTH WHEELS)
07/25/24	263,999 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
07/25/24	263,999 miles	COMPLETE T1G - TRAILER AND LIFT GATE, FEDERAL ANNUAL INSPECTION
04/18/24	254,816 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION

THIS MAINTENANCE HISTORY REPORT INCLUDES ONLY CERTAIN MAINTENANCE ACTIVITIES THAT WERE PERFORMED AND RECORDED BY PENSKE TRUCK LEASING CO., L.P.("PENSKE") DURING THE SIXTY (60) MONTH PERIOD PRIOR TO THE DATE OF THIS REPORT THE MILEAGE AMOUNT SET FORTH ABOVE IS THE AMOUNT LAST RECORDED BY PENSKE WITHOUT VERIFICATION FOR THIS REPORT AND MAY NOT REPRESENT THE ACTUAL MILEAGE OF THE VEHICLE. THE MILEAGE AMOUNT WILL BE VERIFIED UPON SALE.

PENSKE DOES NOT REPRESENT OR WARRANT THAT THIS REPORT INCLUDES ALL MAINTENANCE AND/OR REPAIRS PERFORMED BY PENSKE OR PERFORMED BY ANY THIRD PARTY WITH OR WITHOUT PENSKE"S CONSENT. PENSKE SHALL NOT BE LIABLE FOR ANY ERRORS OR OMISSIONS IN THE CONTENT OF THIS REPORT. PENSKE MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE VEHICLE(S) COVERED BY THIS REPORT, AND ANY SUCH WARRANTIES (INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE) ARE EXPRESSLY DISCLAIMED AND EXCLUDED. ALL VEHICLES ARE SOLD BY PENSKE AS-IS, IN THEIR PRESENT CONDITION. THE PURCHASER OF ANY VEHICLE SHALL RELY SOLELY ON ITS OWN INSPECTION OF THE VEHICLE PRIOR TO PURCHASE. THE PURCHASE OF ANY VEHICLE REFERENCED IN THIS REPORT SHALL BE SUBJECT TO THE TERMS AND CONDITIONS SET FORTH IN THE MOTOR VEHICLE BILL OF SALE.



MAINTENANCE HISTORY REPORT

UNIT # 171022

LAST 60 MONTHS OF MAINTENANCE ACTIVITY

VIN 1GRAA7228HE703214 Year, Make, Model 2017 GDT FROZEN

Vehicle Description 36FT T/A REEFER TRAILER

Engine N/A **Transmission** N/A Color WHITE

Odometer 310,534 miles

DATE	MILEAGE	DESCRIPTION
04/18/24	254,816 miles	COMPLETE T1G - TRAILER AND LIFT GATE, FEDERAL ANNUAL INSPECTION
02/11/24	246,730 miles	COMPLETE TR2 - TRAILER REEFER, MAINTENANCE INSPECTION
02/11/24	246,730 miles	COMPLETE T1G - TRAILER AND LIFT GATE, FEDERAL ANNUAL INSPECTION
11/03/23	234,235 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
11/03/23	234,235 miles	COMPLETE T1G - TRAILER AND LIFT GATE, FEDERAL ANNUAL INSPECTION
08/28/23	226,381 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
08/28/23	226,381 miles	COMPLETE T1G - TRAILER AND GATE, INSPECTION
04/28/23	214,653 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
04/28/23	214,653 miles	COMPLETE T1G - TRAILER AND GATE, INSPECTION
02/15/23	205,708 miles	COMPLETE T1G - TRAILER AND GATE, INSPECTION
02/15/23	205,708 miles	COMPLETE TR2 - TRAILER REEFER, MAINTENANCE INSPECTION
11/14/22	195,347 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
11/14/22	195,347 miles	COMPLETE T1G - TRAILER AND GATE, INSPECTION
08/09/22	186,035 miles	REPLACE HYDRAULIC LIFT SYSTEM MOTOR - ELECTRIC
07/04/22	182,351 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION

THIS MAINTENANCE HISTORY REPORT INCLUDES ONLY CERTAIN MAINTENANCE ACTIVITIES THAT WERE PERFORMED AND RECORDED BY PENSKE TRUCK LEASING CO., L.P.("PENSKE") DURING THE SIXTY (60) MONTH PERIOD PRIOR TO THE DATE OF THIS REPORT THE MILEAGE AMOUNT SET FORTH ABOVE IS THE AMOUNT LAST RECORDED BY PENSKE WITHOUT VERIFICATION FOR THIS REPORT AND MAY NOT REPRESENT THE ACTUAL MILEAGE OF THE VEHICLE. THE MILEAGE AMOUNT WILL BE VERIFIED UPON SALE.

PENSKE DOES NOT REPRESENT OR WARRANT THAT THIS REPORT INCLUDES ALL MAINTENANCE AND/OR REPAIRS PERFORMED BY PENSKE OR PERFORMED BY ANY THIRD PARTY WITH OR WITHOUT PENSKE"S CONSENT. PENSKE SHALL NOT BE LIABLE FOR ANY ERRORS OR OMISSIONS IN THE CONTENT OF THIS REPORT. PENSKE MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE VEHICLE(S) COVERED BY THIS REPORT, AND ANY SUCH WARRANTIES (INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE) ARE EXPRESSLY DISCLAIMED AND EXCLUDED. ALL VEHICLES ARE SOLD BY PENSKE AS-IS, IN THEIR PRESENT CONDITION. THE PURCHASER OF ANY VEHICLE SHALL RELY SOLELY ON ITS OWN INSPECTION OF THE VEHICLE PRIOR TO PURCHASE. THE PURCHASE OF ANY VEHICLE REFERENCED IN THIS REPORT SHALL BE SUBJECT TO THE TERMS AND CONDITIONS SET FORTH IN THE MOTOR VEHICLE BILL OF SALE.



MAINTENANCE HISTORY REPORT

UNIT # 171022

LAST 60 MONTHS OF MAINTENANCE ACTIVITY

VIN 1GRAA7228HE703214 Year, Make, Model 2017 GDT FROZEN

Vehicle Description 36FT T/A REEFER TRAILER

Engine N/A **Transmission** N/A Color WHITE

Odometer 310,534 miles

DATE	MILEAGE	DESCRIPTION
07/04/22	182,351 miles	COMPLETE T1G - TRAILER AND GATE, INSPECTION
04/04/22	176,306 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
04/04/22	176,306 miles	COMPLETE T1G - TRAILER AND GATE, INSPECTION
01/04/22	165,754 miles	COMPLETE T1G - TRAILER AND RAIL GATE, INSPECTION
01/04/22	165,754 miles	COMPLETE TR2 - TRAILER REEFER, MAINTENANCE INSPECTION
09/30/21	157,373 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
09/30/21	157,373 miles	COMPLETE T1G - TRAILER AND GATE INSPECTION
07/19/21	151,229 miles	COMPLETE T1G - TRAILER W/GATE INSPECTION
07/19/21	151,229 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
04/19/21	141,933 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
03/31/21	139,920 miles	COMPLETE T1 - TRAILER, FEDERAL ANNUAL INSPECTION
02/04/21	134,127 miles	COMPLETE TR2 - TRAILER REEFER, MAINTENANCE INSPECTION
12/14/20	128,939 miles	COMPLETE TR1 - TRAILER REEFER, OPERATIONAL INSPECTION
12/14/20	128,939 miles	COMPLETE T1 - TRAILER, FEDERAL ANNUAL INSPECTION

THIS MAINTENANCE HISTORY REPORT INCLUDES ONLY CERTAIN MAINTENANCE ACTIVITIES THAT WERE PERFORMED AND RECORDED BY PENSKE TRUCK LEASING CO., L.P.("PENSKE") DURING THE SIXTY (60) MONTH PERIOD PRIOR TO THE DATE OF THIS REPORT THE MILEAGE AMOUNT SET FORTH ABOVE IS THE AMOUNT LAST RECORDED BY PENSKE WITHOUT VERIFICATION FOR THIS REPORT AND MAY NOT REPRESENT THE ACTUAL MILEAGE OF THE VEHICLE. THE MILEAGE AMOUNT WILL BE VERIFIED UPON SALE.

PENSKE DOES NOT REPRESENT OR WARRANT THAT THIS REPORT INCLUDES ALL MAINTENANCE AND/OR REPAIRS PERFORMED BY PENSKE OR PERFORMED BY ANY THIRD PARTY WITH OR WITHOUT PENSKE"S CONSENT. PENSKE SHALL NOT BE LIABLE FOR ANY ERRORS OR OMISSIONS IN THE CONTENT OF THIS REPORT. PENSKE MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE VEHICLE(S) COVERED BY THIS REPORT, AND ANY SUCH WARRANTIES (INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE) ARE EXPRESSLY DISCLAIMED AND EXCLUDED. ALL VEHICLES ARE SOLD BY PENSKE AS-IS, IN THEIR PRESENT CONDITION. THE PURCHASER OF ANY VEHICLE SHALL RELY SOLELY ON ITS OWN INSPECTION OF THE VEHICLE PRIOR TO PURCHASE. THE PURCHASE OF ANY VEHICLE REFERENCED IN THIS REPORT SHALL BE SUBJECT TO THE TERMS AND CONDITIONS SET FORTH IN THE MOTOR VEHICLE BILL OF SALE.