



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan



Station #: 71872

Station Name: RPM Diesel Inc.

Technician #: 88893

Technician Name: Kyle Edin

Signing Officer #: 91059

Signing Officer Name: Sarah Edin

Customer Details:

Name: Pure Ag Ltd

Address: Box 4617, Melfort, Saskatchewan, S0E 1A0

Inspection Completed Date: 05Oct2026

Inspection Expiry Date: 31Oct2027

Vehicle Details:

VIN: 1PMS34229B1004417

Hubometer Reading:

Year: 1980

Vehicle Make/Model: POLAR/TRAILER

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71872

Station Name: RPM Diesel Inc.

Technician #: 88893

Technician Name: Kyle Edin

Signing Officer #: 91059

Signing Officer Name: Sarah Edin

Customer Details:

Name: Pure Ag Ltd

Address: Box 4617, Melfort, Saskatchewan, S0E 1A0

Vehicle Details:

VIN: 1PMS34229B1004417

Hubometer Reading:

Year: 1980

Vehicle Make/Model: POLAR TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 23 mm

Wheel3-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 18 mm • Cam Rotation: 50.0 degrees • Brake Stroke: 25 mm

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 45.0 degrees • Brake Stroke: 22 mm

Wheel3-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 90.0 degrees • Brake Stroke: 24 mm

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A360964

Inspection Completed Date: 05Oct2026