

04017133

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

R01-23

Vehicle Standards and Ins.
Box 45084, Winnipeg, MB, R2G 5G7
1-204-985-0920

Manitoba

C015183

Date Inspection Started: 02 10 25
Date Inspection Completed: 02 10 25
Inspection Expiry Date: 31 10 26

Station Number: A1518106
Mechanic Number: M918141

Station Name: SIGFUSSON NORTHERN
Mechanic Signature: [Signature]

City: LUNDAR
Station Phone Number: 204-762-5500

Vehicle Owner: SIGFUSSON NORTHERN
Address: BOX 51
City: LUNDAR
Province: MB
Postal Code: R0C1Y0

Phone: 204-762-5500

☒ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: TE92945
Vehicle Identification Number: 1599942327476347

Prov: MB
NSC #
Make: SMITH
Model: SINE DUMP
Year: 07
Unit: 7588

Odometer Reading: [Blank]
Odom. Type: km mi
Confirmed legible Vehicle Identification Number on vehicle: ☐

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3/4</td> <td>3/4</td> <td>16.52</td> <td>16.52</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>11/16</td> <td>5/8</td> <td>16.54</td> <td>16.53</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td>5/8</td> <td>5/8</td> <td>16.53</td> <td>16.54</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/4	3/4	16.52	16.52	1.5	1.5	2	11/16	5/8	16.54	16.53	1.5	1.5	3	5/8	5/8	16.53	16.54	1.5	1.5	4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	3/4	3/4	16.52	16.52	1.5	1.5																																																																		
2	11/16	5/8	16.54	16.53	1.5	1.5																																																																		
3	5/8	5/8	16.53	16.54	1.5	1.5																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>18</td> <td>19</td> <td>19</td> <td>19</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>14</td> <td>16</td> <td>19</td> <td>20</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>15</td> <td>12</td> <td>17</td> <td>18</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	18	19	19	19	100	100	100	100	2	14	16	19	20	100	100	100	100	3	15	12	17	18	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	18	19	19	19	100	100	100	100																																																																
2	14	16	19	20	100	100	100	100																																																																
3	15	12	17	18	100	100	100	100																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

e received without repairs by:

Signature

Date: