

03966537

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Ins.
Box 45064 Regent Postal O
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A963767

Date Inspection Started DAY: 31 MO: 03 YR: 25	Station Number A51364	Station Name Rocky Mountain Eg. R.	City Waskia
Date Inspection Completed DAY: 31 MO: 03 YR: 25	Mechanic Number M161563	Mechanic Signature Ch. Walker	Station Phone Number 534-2463
Inspection Expiry Date DAY: 31 MO: 03 YR: 26	Vehicle Owner Municipality of Boissevain Morton		
	Address 420 Spruceway St Boissevain MB R0K0E0 534-2433		
	City Boissevain	Province MB	Postal Code R0K0E0
	Phone 534-2433		
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number CET8133	Prov. MB	NSC # MB9083824
	Vehicle Identification Number 1AFTYV95B5RVA27429	Make Ford	Model L9000
	Year 1994	Unit #	
	Confirmed legible Vehicle Identification Number on vehicle		

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ^{GVWR} 22679 KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
		Section 1 - Power Train: Defects (if any)																																																																						
Y		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
Y		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining "</th><th colspan="2">Drum/Rotor "</th><th colspan="2">Stroke "</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>7/16</td><td>7/16</td><td>15.036</td><td>15.044</td><td>1 1/4</td><td>1 1/4</td></tr><tr><td>2</td><td>4/2</td><td>4/2</td><td>16.556</td><td>16.561</td><td>1 1/4</td><td>1 1/4</td></tr><tr><td>3</td><td>9/16</td><td>9/16</td><td>16.567</td><td>16.559</td><td>1 1/4</td><td>1 1/4</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining "		Drum/Rotor "		Stroke "		L	R	L	R	L	R	1	7/16	7/16	15.036	15.044	1 1/4	1 1/4	2	4/2	4/2	16.556	16.561	1 1/4	1 1/4	3	9/16	9/16	16.567	16.559	1 1/4	1 1/4	4							5							Final Measurement																					
Axle	Lining "			Drum/Rotor "		Stroke "																																																																		
	L	R	L	R	L	R																																																																		
1	7/16	7/16	15.036	15.044	1 1/4	1 1/4																																																																		
2	4/2	4/2	16.556	16.561	1 1/4	1 1/4																																																																		
3	9/16	9/16	16.567	16.559	1 1/4	1 1/4																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
Y		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any) 16 license plate lamp																																																																						
X	X	Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any) 10a deck retaining bolts loose																																																																						
X	Y	Section 9 - Tire & Wheel: Defects (if any) 4a Inflation Pressure																																																																						
X	X	<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth 32nd</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>20</td><td>20</td><td></td><td></td><td>90</td><td>90</td><td>100</td><td>100</td></tr><tr><td>2</td><td>24</td><td>24</td><td>15</td><td>24</td><td>90</td><td>90</td><td>100</td><td>100</td></tr><tr><td>3</td><td>24</td><td>11</td><td>24</td><td>24</td><td>90</td><td>90</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td>90</td><td>90</td><td>100</td><td>100</td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth 32nd				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	20	20			90	90	100	100	2	24	24	15	24	90	90	100	100	3	24	11	24	24	90	90	100	100	4					90	90	100	100	5								
Axle	Tread Depth 32nd				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	20	20			90	90	100	100																																																																
2	24	24	15	24	90	90	100	100																																																																
3	24	11	24	24	90	90	100	100																																																																
4					90	90	100	100																																																																
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

