

04046589

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920



Date Inspection Started: 11 DAY, 03 MO., 26 YR.  
 Date Inspection Completed: 17 DAY, 03 MO., 26 YR.  
 Inspection Expiry Date: 17 DAY, 03 MO., 27 YR.

Station Number: A41043 Station Name: Bloomfield Garage, W...  
 Mechanic Number: 10368 Mechanic Signature: Austin Brown Station Phone Number: (204)870-1032  
 Vehicle Owner: Sollio Agriculture  
 Address: 137-99 Scarfield Blvd, Winnipeg, MB R3Y1Y1

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

Licence Number: CGU755 Prov. MB NSC #  
 Odometer Reading: 538537 Odom. Type:  km  mi  
 Vehicle Identification Number: 1X1PFID1419X614DR097510 Make: Peterbilt Model: 378 Year: 2003 Unit #  
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GVWR  KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

**Section 1 - Power Train: Defects (if any)**

**Section 2 Suspension: Defects (if any)** 5, 6, (2) Rear Air-springs replaced due to Exposed Ply + cracking.

**Section 3 - Brake Systems: Defects (if any)** 3H 3A  
 Circle Brake Type: 2, 6, - Large Air Leak repaired on compressor discharge lines  
 Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	3/8	7/16	16.529	16.547	1 1/4	1 1/4
2	5/16	9/16	16.549	16.559	1 3/4	1 3/4
3	9/16	7/16	16.556	16.531	1 1/2	1 1/2
4						
5						

Final Measurement

**Section 4 - Steering: Defects (if any)**

**Section 5 - Instruments & Auxiliary Equipment: Defects (if any)**

**Section 6 - Lamps: Defects (if any)** 11, 6, License Plate Lamp Inoperative.

**Section 7 - Electrical System: Defects (if any)**

**Section 8 - Body: Defects (if any)** 11, 9, Replaced damaged Rear Bumper.

**Section 9 - Tire & Wheel: Defects (if any)**

Axle	Tread Depth mm				Air Pressure psi			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	12	9			95	45		
2	13	12	12	13	105	105	105	105
3	12	11	12	12	105	105	105	105
4								
5								

**Section 10 - Coupling Devices: Defects (if any)**

- THIS INSPECTION IS NOT A WARRANTY -  
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Date: \_\_\_\_\_  
 Signature