

## Annual Inspection Certificate & Safety Standards Certificate


### VEHICLE INFORMATION

Plate#:	T1445J	Year:	2021
VIN:	1UYVS2531M7207509	Make:	UTILITY TRAILER
GVWR (kg):	29500	Model:	TRAILER
Odometer (km):		Type:	Trailer

### CERTIFICATE INFORMATION

Annual Inspection Certificate	Expires at the end of: Apr 2026
Safety Standards Certificate	Expires at the end of: May 7, 2025
Vehicle Inspection Certificate Number	DG30AD70
Inspection Start Date	Apr 1, 2025 System Time: 11 : 23
Inspection End Date	Apr 1, 2025 System Time: 13 : 04

### VEHICLE INSPECTION CENTRE

Vehicle Inspection Centre #: 11378	Technician: GURJOT GREWAL
FLEET CARE INC.	
/A FLEET CARE INC.	
73 GLIDDEN RD #1, BRAMPTON, ON	Technician Signature
BRAMPTON, ON L6W1H9	Technician ID: 218299
47-308-0037	STO ID/Account: 20006374
	Trade Code: 310T

I verify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?

Call the Public Contact Centre 1-833-420-2103 or go to

<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>.

MINISTRY OF TRANSPORTATION  
SAFETY INSPECTION REPORT

Vehicle Inspection Certificate Number: DG30AD70

Start Date / Time: Apr 1, 2025, 11:23 AM

End Date / Time: Apr 1, 2025, 1:04 PM

## VEHICLE/ENGINE INFORMATION

## CHASSIS

Plate#: T1445J

Year: 2021

VIN: 1UYVS2531M7207509

Make: UTILITY TRAILER

GVWR(kg): 29500

Model: TRAILER

Odometer:

Fleet ID: 11378

## SAFETY INSPECTION RESULT

PASS

## SAFETY SYSTEM INSPECTION RESULTS

All Safety System Components Passed Inspection

## MANDATORY ITEMS

Inspection Item	Result
Axle 1, Driver Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	720
Axle 1, Driver Side, Outer Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	13
Drum Inside Diameter (mm)	418.9
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	35

Inspection Item	Result
Axle 1, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Axle 1, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	7
Initial Tire Pressure (kPa)	720
Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	12
Drum Inside Diameter (mm)	419.66
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	35

Inspection Item	Result
Axle 2, Driver Side, Inner Tire	
Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	720
Axle 2, Driver Side, Outer Tire	

Inspection Item	Result
Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	720
Axle 2, Passenger Side, Outer Tire	

Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	13
Drum Inside Diameter (mm)	418.88
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	35

Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	11
Drum Inside Diameter (mm)	419.88
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	35

Vehicle Inspection Centre #: 11378

FLEET CARE INC.

273 GLIDDEN RD #1, BRAMPTON, ON  
BRAMPTON, ON L6W1H9

647-308-0037

Software Version: 2024.08.21.1

Technician #: 218299

Name: GURJOT GREWAL

Report Number: 244

Tablet ID: 804

STO ID/Account: 20006374

Trade Code: 310T

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to  
<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>