



Henkel's Ag Repair Co.
 240474 Highland Road
 Scottsbluff, NE 69361
 Ph:(308)575-1403
 Fax:(308)575-1406
 www.henkelsagrepair.com

SOLD TO
 FRAN03 FRANK IMPLEMENT COMPANY
 230340 HIGHLAND RD.
 SCOTTSBLUFF, NE 69361

SHIP TO



MACDON M1240 SN: HR .0 W:00
 Sold By: DH PO #: RR M1240 MISC Date 4/28/25 WORK ORDER WS04479
 Ship By: Tax #: 14:51:15

Tax	D	Qty	Description	Price	Amount	
Group: 01						
COMPLAINT						
PER TY;						
RR; INSPECT MACHINE AND MAKE A LIST OF REPAIRS.						
DESC OF REPAIRS						
BRING MACHINE IN AND LOOKED OVER MACHINE AND HEAD.						
MAKE A LIFT OF REPAIRS. NO REPAIRS TO THE HEAD. TAKE						
MACHINE AND REMOVE HEAD FROM MACHINE. REMOVE THE						
DRIVE MOTOR FOR THE HEAD SET IT ON THE CHUTE. ONCE						
TRIED TO REMOVE THE HEAD IT WAS STUCK ON THE ARMS DUE						
TO THE ONE SIDE BEING SO BENT. TRIED JARRING IT BACK						
AND FORTH, HEAD WOULD NOT COME OFF. ENDED UP HAVING						
TO HOOK IT TO THE PICKUP AND JERK IT OFF THE MACHINE.						
BRING MACHINE INTO SHOP. REMOVE THE R/H TIRE. REMOVE						
THE PINS FROM THE R/H ARM AND REMOVE. REMOVE THE LINK						
FOR THE ARM AS WELL. PINS WERE WORN AS WELL.						
INSTALLED NEW LINK AND SHIMS. INSTALLED NEW RUBBER						
STOP INSIDE NEW ARM. INSTALL ARM BACK ON MACHINE.						
REMOVE SIDE COVERS TO GAIN ACCESS TO LEAKING LIFT						
CYLINDER HOSE. REMOVE CLAMPS AND HOSE. INSTALL NEW						
HOSE AND CLAMPS. THAN INSIDE REMOVE THE COLUMN						
PLASTIC AND THE BAD TILT CYLINDER. INSTALLED NEW						
CYLINDER AND PINS. INSTALL NEW PLASTIC FOR THE COLUMN						
SINCE THE OLD WAS BROKE. TEST TO MAKE SURE IT WORKS.						
SLID WALK WAY OUT OF THE WAY TO GAIN ACCESS TO THE						
LEAKING COUPLER. REMOVE THE COUPLER FROM THE HOSE AND						
INSTALLED NEW. REMOVE ONE FROM THE FRAME AND HOSE						
UNDERNEATH. INSTALLED NEW AND REASSEMBLED. TEST						
MACHINE FOR LEAKS. INSTALLED WHEEL BACK ON MACHINE.						
TAKE OUTSIDE AND HOOK UP HEAD, IT WENT ON WITH NO						
ISSUES. RUN HEAD TO DOUBLE CHECK EVERYTHING AND ALL						
WORKED FINE.						
SERVICE LABOR						
					** TOTAL SERVICE LABOR	3600.00
SHOP PARTS						
N		2	WBS D74332	813 ORFS FE WBSBIN	13.49 26.98	
N		9	WBS D74521	1/2" HOSE B HOSE RAC	4.10 36.90	
N		1	HOR 135474	COUPLER HYD	87.63 87.63	
N		1	HOR 252190	FITTING-COU	55.95 55.95	
N		1	HOR 208016	KIT, GAS ST	116.96 116.96	

Thank you for your business!!!

PAY THIS AMOUNT

There will be a \$25.00 charge for all returned checks. 13% interest will be assessed on all unpaid balances after 30 days.



Henkel's Ag Repair Co.
 240474 Highland Road
 Scottsbluff, NE 69361
 Ph:(308)575-1403
 Fax:(308)575-1406
 www.henkelsagrepair.com



SOLD TO
 FRAN03 FRANK IMPLEMENT COMPANY
 230340 HIGHLAND RD.
 SCOTTSBLUFF, NE 69361

SHIP TO

MACDON M1240 SN: HR 0 W:00
 Sold By: DH PO #: RR M1240 MISC Date 4/28/25 WORK ORDER WS04479
 Ship By: Tax #: 14:51:15

Tax	D	Qty	Description	Price	Amount	
N		1	HOR 208806	BOTTOM COVE	40.30	40.30
N		2	HOR 183820	PIN, FLOAT	69.98	139.96
N		1	HOR 112727	ARM FLOAT L	833.69	833.69
N		4	HOR 139134	SEAL	4.24	16.96
N		1	HOR 183821	PIN-STRAIGH	83.32	83.32
N		2	HOR 42497	RUBBER PAD	25.64	51.28
N		4	HOR 110853	SHIM LINKAG	20.49	81.96
N		4	HOR 112789	BEARING NEE	23.82	95.28
N		1	HOR 306193	ASSY LIFT A	2389.13	2389.13
** TOTAL SHOP PARTS						4056.30
FREIGHT						
N			FREIGHT		58.65	
N			FREIGHT		92.88	
N			FREIGHT		185.64	
** TOTAL FREIGHT						337.17
SHOP SUPPLIES						125.00
N					125.00	
ENERGYSURCHARGE						125.00
N					125.00	

Thank you for your business!!!

** SUBTOTAL 8243.47

X _____ Charge Sale

Phone: 633-8400
 Page 2 Last Page

PAY THIS AMOUNT

\$8243.47

There will be a \$25.00 charge for all returned checks. 13% interest will be assessed on all unpaid balances after 30 days.