



**RDO Equipment Co.**  
 20 Iowa Avenue  
 Riverside, CA 92507  
 951-778-3700  
 Fax: 951-778-3746  
 www.rdoequipment.com

For Billing Inquiries or to  
 receive invoices via E-mail or  
 MyDealer website, please contact  
 RDOAR@rdoequipment.com

Ship to:

**Branch**  
 RIVERSIDE, CA

**Date** 11/10/23 **Time** 21:10:57 (B) **Page** 01  
**Account No.** **Phone No.** **Invoice No.**  
 W9679535

Invoice to:

**Ship Via** **Purchase Order**  
 ?  
**Tax Exemption Number** **Federal ID Number**

**Salesperson**  
 MD8 / MD8

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X540406	870GLC BASE EXCAVA	7064	1FF870GXCCE870073	10/09/15	
814413	870GLC		1ZUXL15617870	10/07/19	5000 X

- \*\* Get 10% off your first construction technology service with RDO Service Centers.
- \*\* Ask how you can get a FREE Winter Service Inspection for your Vermeer equipment.

SEGMENT# 1 C BWG01 RVZONE20 09/20/23 10/03/23  
 Riverside Round trip travel to and from location.  
CONDITION:

10401099	LABOR	454.00
	SEGMENT TOTAL==>	454.00

SEGMENT# 2 C BWG01 RDO-020-DIAG 09/20/23 09/27/23  
 ENGINE DIAGNOSTICS  
CONDITION:  
 customer installed new engine need us to assist in start up  
CAUSE:  
 assist with new engine start up  
CORRECTION:  
 customer just installed new engine  
 installed new ECU  
 installed turbo controller  
 hooked up to ECU with IDSS and verified software and injector cal.  
 attempted to start engine, crank no start  
 bleed air from fuel system but still no start  
 hooked up MpDr and monitored fuel readings  
 low pressure fuel was at 48PSI but no rail pressure

CONTINUED ON PAGE 02

Thank you for your business





**RDO Equipment Co.**  
 20 Iowa Avenue  
 Riverside, CA 92507  
 951-778-3700  
 Fax: 951-778-3746  
 www.rdoequipment.com

For Billing Inquiries or to  
 receive invoices via E-mail or  
 MyDealer website, please contact  
 RDOAR@rdoequipment.com

Ship to:

**Branch**  
 RIVERSIDE, CA

**Date** 11/10/23 **Time** 21:10:57 (B) **Page** 02  
**Account No.** **Phone No.** **Invoice No.** W9679535

Invoice to:

**Ship Via** **Purchase Order**  
 ?  
**Tax Exemption Number** **Federal ID Number**

**Salesperson**  
 MD8 / MD8

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X540406 870GLC BASE EXCAVA	7064	1FF870GXCCE870073	10/09/15	
814413 870GLC		1ZUXL15617870	10/07/19	5000 X
tested rail relief, all good bled air from fuel system one component at a time starting from tank found air in line from fuel manifold to secondary filters found supply and return lines from secondary fuel filters to manifold swapped hooked up lines in the correct position and bleed air from system engine started ran engine to operating temp and monitored no leaks or issues customer will finish assembling machine				
CR6WG1XZSA01R	ENGINE CORE	1-	10000.00	10000.00-
6WG1XZSA01R	DIESEL ENGINE	1 N	70000.00	70000.00
CR6WG1XZSA01R	ENGINE CORE		10000.00	10000.00
			PARTS	70000.00
			LABOR	2092.20
10401099			SEGMENT TOTAL==>	72092.20

SEGMENT# 3 C KAB01 NA 09/20/23 10/03/23  
 na

SEGMENT# 4 C KAB01 NA 09/20/23 10/03/23  
 na

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS 70000.00  
 LABOR 2546.20

CONTINUED ON PAGE 03

Thank you for your business



