

Experian AutoCheck Report

Report run: 05/08/2026 11:40:38 EDT

2009 Volkswagen GLI

Sedan 4D (2.0L 14 Ft Gasoline)

VIN:	3VWFJ71K09M160631
Class:	Car - Compact
Country of Assembly:	Mexico
Vehicle Age:	17 year(s)
Estimated In Service:	08/31/2009
Last Reported Odometer:	153,449 (05/18/2017)

Owners - 7



Vehicle Usage
Personal



AutoCheck Score

Similar vehicles usually range between 23 and 37

Vehicle History at a Glance

<p>State Title Brand Multiple State Title Brands</p> <p>ISSUES FOUND</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage Water Damage</p> <p>MODERATE</p>
<p>Open Recall Check</p> <p>3 OPEN RECALL(S)</p>	<p>Insurance Loss / Transfer</p> <p>INSURANCE LOSS REPORTED</p>	<p>Odometer Check Last reported odometer: 153,449 (05/18/2017)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair 1 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History Lien Reported</p> <p>EVENTS REPORTED</p>

This vehicle is not eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Accident & Damage

Point of Impact Not Available

Airbag Deployed

Structural Damage

Overturned

Moderate

Damage Date	Damage Type	Severity
04/18/2016	Water Damage	Moderate

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

Open Recall Check

Information Reported: AutoCheck found 3 open recall(s).
 It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 01/17/2017

Recall Type - Safety

NHTSA / OEM Recall No. - N/A / 45F2

Campaign Description - Safety Recall: ABS CONTROL MODULE
 Status: Remedy Unknown

Recall Date - 01/17/2017

Recall Type - Safety

NHTSA / OEM Recall No. - N/A / 45F2

Campaign Description - Safety Recall: ABS CONTROL MODULE
 Status: Remedy Unknown

Recall Date - 01/17/2017

Recall Type - Safety

NHTSA / OEM Recall No. - N/A / 45F2

Campaign Description - Safety Recall: ABS CONTROL MODULE
 Status: Remedy Unknown

[More information](#) including remedy or risk factors. Locate your nearest authorized **VW Dealer** to schedule repair.

Odometer Check

Your Vehicle Checks Out
 No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.
Vehicle: 2009 Volkswagen GLI (3VWFJ71K09M160631) Report Run Date: 05/08/2026 11:40:38 EDT

2009

Owner 1

Location: MS

Owned From: 08/2009

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
08/31/2009			Independent Source	Vehicle Manufactured and Shipped to Dealer
08/31/2009	SONTAG, MS	47	Motor Vehicle Dept.	Title(Title #:F321223-01) (Lien Reported)
09/01/2009	SONTAG, MS		Motor Vehicle Dept.	Registration Event/Renewal
08/17/2010	SONTAG, MS		Motor Vehicle Dept.	Registration Event/Renewal
08/18/2011	SONTAG, MS		Motor Vehicle Dept.	Registration Event/Renewal
08/06/2012	SONTAG, MS		Motor Vehicle Dept.	Registration Event/Renewal
08/06/2013	SONTAG, MS		Motor Vehicle Dept.	Registration Event/Renewal
10/17/2013	SONTAG, MS	98,500	Motor Vehicle Dept.	Title(Title #:F321223-02)

2014

Owner 2

Location: TX

Owned From: 10/2014

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
10/15/2014	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal
10/22/2014	HOUSTON, TX	109,500	Motor Vehicle Dept.	Title(Title #:10173341925162113)

2015

Owner 3

Location: TX

Owned From: 06/2015

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
06/04/2015	FORT WORTH, TX		Motor Vehicle Dept.	Registration Event/Renewal
06/25/2015	FORT WORTH, TX	123,562	Motor Vehicle Dept.	Title(Title #:04300242171112959)
08/27/2015	FORT WORTH, TX	129,398	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
08/28/2015	HOUSTON, TX	129,805	Service Contract Company	Service Contract Issued

2015

Owner 4



Location: TX Owned From: 10/2015 Usage: Personal				
Event Date	Location	Odometer	Data Source	Details
10/13/2015	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal
10/23/2015	SPRING, TX	129,806	Motor Vehicle Dept.	Title(Title #:10131042291124052) (Lien Reported)
04/18/2016	TX		Auto Insurance Source	Vehicle Reported as Total Loss Vehicle Had Flood Damage
06/15/2016	HOUSTON, TX	141,829	Motor Vehicle Dept.	Title(Title #:29741042532141512) (Lien Reported) Salvage Water Damage

2016

Owner 5

Location: TX Owned From: 07/2016 Usage: Personal				
Event Date	Location	Odometer	Data Source	Details
07/11/2016	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal
07/11/2016	BAYTOWN, TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage
07/19/2016	BAYTOWN, TX	141,856	Motor Vehicle Dept.	Title(Title #:10122242560101036) Rebuilt/Rebuildable Salvage Water Damage
01/17/2017			Manufacturer	Manufacturer Recall Mfr. Recall 45F2 Safety Recall: ABS CONTROL MODULE LOCATE YOUR NEAREST AUTHORIZED VW DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown Manufacturer Recall Mfr. Recall 45F2 Safety Recall: ABS CONTROL MODULE LOCATE YOUR NEAREST AUTHORIZED VW DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown Manufacturer Recall Mfr. Recall 45F2 Safety Recall: ABS CONTROL MODULE LOCATE YOUR NEAREST AUTHORIZED VW DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
05/18/2017	BAYTOWN, TX	153,449	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
08/10/2017	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal Rebuilt/Rebuildable Salvage Water Damage
08/01/2021	TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage Bonded Excluded/Exempt

2021

Owner 6

Location: TX Owned From: 08/2021 Usage: Personal				
Event Date	Location	Odometer	Data Source	Details
08/02/2021	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal
08/10/2021	BAYTOWN, TX		Motor Vehicle Dept.	Title(Title #:10160644408180847)
07/01/2022	TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage Bonded Excluded/Exempt

Event Date	Location	Odometer	Data Source	Details
11/01/2022	TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage Bonded Excluded/Exempt

2023

Owner 7

Location: TX	Owned From: 05/2023	Usage: Personal
--------------	---------------------	-----------------

Event Date	Location	Odometer	Data Source	Details
05/17/2023	COLDSRING, TX		Motor Vehicle Dept.	Registration Event/Renewal
07/01/2023	TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage Bonded Excluded/Exempt
07/04/2023	COLDSRING, TX		Motor Vehicle Dept.	Title(Title #:10184145101160730)
10/19/2023	HUMBLE, TX		Motor Vehicle Dept.	Title(Title #:26830045216083434)
02/01/2024	TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage Bonded Excluded/Exempt
01/28/2025	HUMBLE, TX		Motor Vehicle Dept.	Registration Event/Renewal
02/01/2025	TX		Motor Vehicle Dept.	Rebuilt/Rebuildable Salvage Water Damage Bonded Excluded/Exempt

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic i	-	-		36 months / 36000 miles
Battery i	-	-	-	Contact a certified dealer to verify coverage
Corrosion i	-	-		144 months / Unlimited miles
Powertrain i	-	-		60 months / 60000 miles
Roadside Assistance i	-	-		36 months / 36000 miles
Safety Restraint i	-	-	-	Contact a certified dealer to verify coverage

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (3VWFJ71K09M160631) does not qualify for AutoCheck Buyback Protection.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.