

Experian AutoCheck Report

Report run: 06/11/2026 16:32:43 EDT

2016 Ford Transit 350 XL / XLT

Passenger 3D (3.7L V6 SMPI Gasoline)

VIN:	1FBZX2ZM5GKA30148
Class:	Van - Fullsize
Country of Assembly:	United States
Vehicle Age:	10 year(s)
Estimated In Service:	10/14/2015
Last Reported Odometer:	139,011 (10/09/2025)

Owners - 4



Vehicle Usage
Lease, Rental



AutoCheck Score

Similar vehicles usually range between 72 and 85

Vehicle History at a Glance

<p>State Title Brand Salvage, Rebuilt / Rebuildable</p> <p>TITLE BRAND REPORTED</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage Damage Reported</p> <p>SEVERE</p>
<p>Open Recall Check</p> <p>3 OPEN RECALL(S)</p>	<p>Insurance Loss / Transfer</p> <p>INSURANCE LOSS REPORTED</p>	<p>Odometer Check Last reported odometer: 139,011 (10/09/2025)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair 1 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History Lien Reported, Duplicate Title</p> <p>EVENTS REPORTED</p>




This vehicle is not eligible for Buyback Protection


Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)


Accident & Damage




Airbag Deployed



Structural Damage



Overturned



Severe

Damage Date	Damage Type	Severity
06/24/2020	Collision	Severe
06/24/2020	Collision	Severe

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

 **Open Recall Check**

Information Reported: AutoCheck found 3 open recall(s).
 It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 10/28/2019
 Recall Type - Safety
 NHTSA / OEM Recall No. - / 19S38
 Campaign Description - Safety Recall: DRIVESHAFT FLEX COUPLING
 Status: Remedy Available

Recall Date - 09/02/2020
 Recall Type - Safety
 NHTSA / OEM Recall No. - 19V767 / 19S38
 Campaign Description - Safety Recall: DRIVESHAFT FLEX COUPLING
 Status: Remedy Unknown

Recall Date - 09/10/2020
 Recall Type - Safety
 NHTSA / OEM Recall No. - 19V767 / 19S38
 Campaign Description - Safety Recall: DRIVESHAFT FLEX COUPLING
 Status: Remedy Unknown

[More information](#) including remedy or risk factors. Locate your nearest authorized [Ford Dealer](#) to schedule repair.

 **Recommended Maintenance**

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services



135000 Mile Service

- Adjust Tire Pressure
- Balance Tires
- Ford Factory Multi-Point Inspection



140000 Mile Service

Not Yet Due

- Adjust Tire Pressure
- Balance Tires
- Ford Factory Multi-Point Inspection



145000 Mile Service

Not Yet Due

- Adjust Tire Pressure
- Balance Tires
- Ford Factory Multi-Point Inspection



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2016 Ford Transit 350 XL / XLT (1FBZX2ZM5GKA30148) Report Run Date: 06/11/2026 16:32:43 EDT

2015

Vehicle Prep and Other Pre-Titling Events

Location: CAPreparation Date: 10/2015

Event Date	Location	Odometer	Data Source	Details
10/14/2015	CA		Independent Source	Vehicle Manufactured and Shipped to Dealer

2015

Owner 1

Location: FLOwned From: 10/2015Usage: Lease, Rental

Event Date	Location	Odometer	Data Source	Details
10/19/2015	FL	5	Motor Vehicle Dept.	Odometer Reading from DMV
10/19/2015	ORLANDO, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle) Titled or Registered as a Rental Vehicle, or Part of a Rental Fleet
10/22/2015	ORLANDO, FL		Motor Vehicle Dept.	Title(Title #:0120639096) (Leased Vehicle) (Lien Reported) Titled or Registered as a Rental Vehicle, or Part of a Rental Fleet
04/18/2016	SOUTHEASTERN REGION	4,597	Auto Auction	Reported at Auto Auction
05/12/2016	FL	5,130	Motor Vehicle Dept.	Odometer Reading from DMV
06/01/2016	ALACHUA, FL		Motor Vehicle Dept.	Title(Title #:0120639096) (Leased Vehicle) (Lien Reported)
06/01/2016	ALACHUA, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
11/29/2016	ALACHUA, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)

2017

Owner 2

Location: FL

Owned From: 12/2017

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
12/19/2017	TALLAHASSEE, FL	34,634	Motor Vehicle Dept.	Title(Title #:0120639096)
12/19/2017	TALLAHASSEE, FL		Motor Vehicle Dept.	Registration Event/Renewal
01/10/2018	TALLAHASSEE, FL		Motor Vehicle Dept.	Title(Title #:0120639096)
10/19/2018	TALLAHASSEE, FL	44,791	Service Record	Vehicle Serviced or Inspected
01/02/2019	TALLAHASSEE, FL		Motor Vehicle Dept.	Registration Event/Renewal
10/28/2019			Manufacturer	Manufacturer Recall Mfr. Recall 19S38 Safety Recall: DRIVESHAFT FLEX COUPLING LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Available
06/24/2020	FL	62,832	Auto Insurance Source	Reported as Insurance Loss - Vehicle Sold by Insurer. Claim Paid to Insured Vehicle Loss Caused by Collision
06/24/2020	TALLAHASSEE, FL		Police Report	Rear Impact with Another Vehicle Accident Reported(Report #:200086385) Vehicle Damage Reported as Disabling Vehicle Was Towed
07/15/2020	TALLAHASSEE, FL		Damage Report	Accident or Damage Reported Severe Damage Reported Left Side Damage or Repair Reported Right Side Damage or Repair Reported Front Damage or Repair Reported Rear Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Wheels Reported Damage or Repair to Grille Reported Damage or Repair to Side Panel Reported
07/16/2020	TALLAHASSEE, FL		Damage Report	Accident or Collision Reported Severe Damage Reported Body Repair Performed
07/20/2020	TALLAHASSEE, FL	62,832	Motor Vehicle Dept.	Title(Title #:0120639096) Duplicate Title
07/21/2020	FL	62,832	Auto Auction	Reported at Auto Auction
07/24/2020	WINTER HAVEN, FL		Motor Vehicle Dept.	Title(Title #:0120639096) Rebuilt/Rebuildable Salvage Vehicle Titled/Registered to an Insurance Company
09/02/2020			Manufacturer	Manufacturer Recall NHTSA Recall 19V767 / Mfr. Recall 19S38 Safety Recall: DRIVESHAFT FLEX COUPLING LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
09/10/2020			Manufacturer	Manufacturer Recall NHTSA Recall 19V767 / Mfr. Recall 19S38 Safety Recall: DRIVESHAFT FLEX COUPLING LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown

2020

Owner 3

Location: FL

Owned From: 10/2020

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
10/16/2020	MIAMI, FL	62,911	Motor Vehicle Dept.	Title(Title #:0120639096)
10/16/2020	MIAMI, FL		Motor Vehicle Dept.	Registration Event/Renewal Rebuilt/Rebuildable
10/25/2021	HOMESTEAD, FL		Motor Vehicle Dept.	Registration Event/Renewal Rebuilt/Rebuildable

Event Date	Location	Odometer	Data Source	Details
11/21/2022	HOMESTEAD, FL		Motor Vehicle Dept.	Registration Event/Renewal Rebuilt/Rebuildable
10/19/2023	HOMESTEAD, FL		Motor Vehicle Dept.	Registration Event/Renewal Rebuilt/Rebuildable
11/05/2024	HOMESTEAD, FL		Motor Vehicle Dept.	Registration Event/Renewal Rebuilt/Rebuildable
10/09/2025	FL	139,011	Motor Vehicle Dept.	Odometer Reading from DMV
10/10/2025	MIAMI, FL		Motor Vehicle Dept.	Title(Title #:0120639096) Rebuilt/Rebuildable

2025

Owner 4

Location: FL	Owned From: 12/2025	Usage: Personal		
Event Date	Location	Odometer	Data Source	Details
12/29/2025	LAKE WORTH, FL		Motor Vehicle Dept.	Title(Title #:0120639096) Rebuilt/Rebuildable

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic <i>i</i>	-	-	✘	36 months / 36000 miles
Battery <i>i</i>	-	-	-	Contact a certified dealer to verify coverage
Corrosion <i>i</i>	-	-	✘	60 months / Unlimited miles
Powertrain <i>i</i>	-	-	✘	60 months / 60000 miles
Roadside Assistance <i>i</i>	-	-	✘	60 months / 60000 miles
Safety Restraint <i>i</i>	-	-	✘	60 months / 60000 miles Seat belts and air bag Supplemental Restraint System.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FBZX2ZM5GKA30148) does not qualify for AutoCheck Buyback Protection.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.