

03979658

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba 501-1

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A955273

Date Inspection Started: DAY 10, MO. 07, YR. 25
 Date Inspection Completed: DAY 14, MO. 07, YR. 25
 Inspection Expiry Date: DAY 31, MO. 07, YR. 26

Station Number: A5978
 Station Name: PEACE TRUCK CENTRE WJ
 City: WJ
 Station Phone Number: 204-633-9100
 Mechanic Number: M9763
 Mechanic Signature: [Signature]
 Vehicle Owner: GORDON FORD SERVICES CANADA LTD
 Address: 310 STRANDBY LYONS WJ MB R3P 0T3
 City: WJ Province: MB Postal Code: R3P 0T3 Phone: 204-793-9781

Pass/Safe Vehicle Fail/Unsafe Vehicle Fail/Hazardous
 Licence Number: G NUS 14 Prov. MB NSC #
 Odometer Reading: 443,588 Odom. Type: km mi
 Vehicle Identification Number: 4U4W095H64W252473 Make: VOLVO Model: 300 Year: 202 Unit #: 619710
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section	Defects (if any)
X	X	Section 1 - Power Train	124 RIGHT FUL THROTTLE SHUTOFF VALVE 2d REAR DIFFUSER PIPE
X		Section 2 Suspension	
X	X	Section 3 - Brake Systems	3H 3A 15b L RD BRAKE SHOES + DRUM 15b RD BRAKE SHOES 15b RED BRAKE SHOES 15b LEFT STEER BRAKE SHOES 15b RIGHT STEER BRAKE SHOES 12a RIGHT STEER BRAKE DUST PLATE
X		Section 4 - Steering	
X	X	Section 5 - Instruments & Auxiliary Equipment	16 FIRE EXTINGUISHER BRACKET
X	X	Section 6 - Lamps	10a CAB REAR REFLECTOR TAPE
X		Section 7 - Electrical System	
X	X	Section 8 - Body	13b WINDSHIELD 6a DECK PLATE 10a RIGHT SIDE ENGINE HEAT EXHAUST PIPE
X		Section 9 - Tire & Wheel	
X		Section 10 - Coupling Devices	

Brake Inspection Type: A B C D E (Circle appropriate letter for Internal Brake Component Inspection)

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	13/16	13/16	16.589	16.561	1 1/2	1 1/2
2	13/16	13/16	16.564	16.510	1 1/2	1 1/2
3	13/16	13/16	16.621	16.576	1 1/2	1 1/2
4						
5						

Final Measurement

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	15	14			110	110		
2	9	4	4	4	110	110	110	110
3	15	7	4	5	110	110	110	110
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: INSPECTED BY # M 10227

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature