



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A317231

Station #: 71947

Technician #: 83418

Signing Officer #: 83698

Station Name: Revolution Diesel Services Inc.

Technician Name: Travis Hutchison

Signing Officer Name: Layne Allen

Customer Details:

Name: Wesson Farms Ltd

Address: Box 442, Maidstone, Saskatchewan, S0M1M0

Inspection Completed Date: 13Nov2025

Inspection Expiry Date: 31May2026

Vehicle Details:

VIN: 3HSDMAPR1JN577460

Odometer Reading: 326434 km

Year: 2018

Vehicle Make/Model: INTERNATIONAL/HEAVY VEHICLE

Plate: 490MWG

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71947	Station Name: Revolution Diesel Services Inc.
Technician #: 83418	Technician Name: Travis Hutchison
Signing Officer #: 83698	Signing Officer Name: Layne Allen

Customer Details:	
Name: Wesson Farms Ltd	Address: Box 442, Maidstone, Saskatchewan, S0M1M0

Vehicle Details:	
VIN: 3HSDMAPR1JN577460	Odometer Reading: 326434 km
Year: 2018	Vehicle Make/Model: INTERNATIONAL HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
		x		Trailer Hitch (10)	Fifth wheel/riser
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

		x		Air Brake System/Components (3.2)	air leak
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	leak

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .55 in • Cam Rotation: 90.0 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .8 in • Cam Rotation: 32.0 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 22/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 22/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .5 in • Cam Rotation: 100.0 degrees • Brake Stroke: 1.25 in

Wheel3-On : Tire Tread Depth: 22/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .61 in • Cam Rotation: 76.0 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 22/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 22/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .5 in • Cam Rotation: 95.0 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 22/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .7 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 22/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A317231

Inspection Completed Date: 13Nov2025