



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan



Station #: 71872

Station Name: RPM Diesel Inc.

Technician #: 88893

Technician Name: Kyle Edin

Signing Officer #: 91059

Signing Officer Name: Sarah Edin

Customer Details:

Name: Pure Ag Ltd

Address: Box 4617, Melfort, Saskatchewan, S0E 1A0

Inspection Completed Date: 05Oct2026

Inspection Expiry Date: 30Apr2027

Vehicle Details:

VIN: 1NPXD49XXRD670809

Odometer Reading: 241199 km

Year: 2024

Vehicle Make/Model: PETERBILT/HEAVY VEHICLE

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71872	Station Name: RPM Diesel Inc.
Technician #: 88893	Technician Name: Kyle Edin
Signing Officer #: 91059	Signing Officer Name: Sarah Edin

Customer Details:	
Name: Pure Ag Ltd	Address: Box 4617, Melfort, Saskatchewan, S0E 1A0

Vehicle Details:	
VIN: 1NPXD49XXRD670809	Odometer Reading: 241199 km
Year: 2024	Vehicle Make/Model: PETERBILT HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 15 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 45.26 mm

Wheel2-Off : Tire Tread Depth: 15 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 45.20 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 13 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 13 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 45.09 mm

Wheel3-Off : Tire Tread Depth: 12 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 44.61 mm

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 11 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17.5 mm • Brake Drum/Rotor: 45.20 mm

Wheel3-On : Tire Tread Depth: 10 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 44.54 mm

Wheel4 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.