



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A267777

Station #: 71689

Station Name: Golden West Trailer & Equipment

Technician #: 90063

Technician Name: Ryan Mellquist

Signing Officer #: 89841

Signing Officer Name: Colby Griffin

Customer Details:

Name: LEONARD & MARILYN YASIE NIUK

Address: RR1, RICHARD, Saskatchewan, S0M290

Inspection Completed Date: 27Jan2026

Inspection Expiry Date: 31Jan2027

Vehicle Details:

VIN: 4WW4372A6J7715170

Hubometer Reading:

Year: 2018

Vehicle Make/Model: WILSON TRAILER/TRAILER

Plate: 982JGX

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71689

Station Name: Golden West Trailer & Equipment

Technician #: 90063

Technician Name: Ryan Mellquist

Signing Officer #: 89841

Signing Officer Name: Colby Griffin

Customer Details:

Name: LEONARD & MARILYN YASIE NIUK

Address: RR1, RICHARD, Saskatchewan, S0M290

Vehicle Details:

VIN: 4WW4372A6J7715170

Hubometer Reading:

Year: 2018

Vehicle Make/Model: WILSON TRAILER TRAILER

Inspection Details:

| Pass | Rejected | Corrected | Req Attn | DRIVERS COMPARTMENT | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x | | | | Vehicle Identification (5) | |
| x | | | | Fire Extinguisher (5) | |
| x | | | | Auxiliary Controls/Equip (5) | |

| Pass | Rejected | Corrected | Req Attn | BODY EXTERIOR | Comments |
|------|----------|-----------|----------|-------------------------------|----------|
| x | | | | Lamps (6) | |
| x | | | | Reflex Reflectors (6) | |
| x | | | | Retro Reflective Markings (6) | |
| x | | | | Trailer Hitch (10) | |
| x | | | | Attached Equipment (8) | |
| x | | | | Cargo Bodies/Vessels (8) | |
| x | | | | Mud Flaps/Fenders (8) | |
| x | | | | Landing Gear (8) | |
| x | | | | Rear Impact Guard (8) | |
| x | | | | Trailer Power Cord (7) | |

| Pass | Rejected | Corrected | Req Attn | ENGINE COMPARTMENT | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x | | | | Fuel System (1) | |
| x | | | | Battery/Wiring Condition (7) | |

| Pass | Rejected | Corrected | Req Attn | CHASSIS | Comments |
|------|----------|-----------|----------|---|-------------------------------|
| x | | | | Hyd Brake System/Components (3.1) | |
| x | | | | Air Brake System/Components (3.2) | |
| x | | | | Elec Brake System/Components (3.1) | |
| x | | | | Wheel Bearings (9) | |
| x | | | | Tires/Wheels (9) | |
| x | | | | Self-Steering Axle (2&4) | |
| x | | | | Frame/Crossmembers/Mounts (8) | |
| | | x | | Suspension/Axles (2) | LEFT FRONT WHEEL SEAL LEAKING |
| x | | | | Exhaust/Emission System (1) | |
| x | | | | Sliding Axle Assembly (if equipped) (8) | |

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 28.0 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 11 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 32.0 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 28.0 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30.0 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A267777

Inspection Completed Date: 27Jan2026