



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A291562

Station #: 70207	Station Name: Frontline Truck & Trailer
Technician #: 88657	Technician Name: Thomas Fehr
Signing Officer #: 90414	Signing Officer Name: Howard Thomson

Customer Details:	
Name: Trewin Farms Corp.	Address: Box 102, Laird, Saskatchewan, S0K 2H0

Inspection Completed Date: 11Jun2026	Inspection Expiry Date: 30Jun2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2DEALBE37T2048090	Hubometer Reading:
Year: 2026	Vehicle Make/Model: DOEPKER TRAILER/TRAILER
Plate: 422 JUD	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70207

Station Name: Frontline Truck & Trailer

Technician #: 88657

Technician Name: Thomas Fehr

Signing Officer #: 90414

Signing Officer Name: Howard Thomson

Customer Details:

Name: Trewin Farms Corp.

Address: Box 102, Laird, Saskatchewan, S0K 2H0

Vehicle Details:

VIN: 2DEALBE37T2048090

Hubometer Reading:

Year: 2026

Vehicle Make/Model: DOEPKER TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
			x	Fire Extinguisher (5)	Not applicable
			x	Auxiliary Controls/Equip (5)	Not applicable

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
			x	Fuel System (1)	Not applicable
			x	Battery/Wiring Condition (7)	Not applicable

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
			x	Hyd Brake System/Components (3.1)	Not applicable
		x		Air Brake System/Components (3.2)	Adjusted brakes
			x	Elec Brake System/Components (3.1)	Not applicable
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
			x	Self-Steering Axle (2&4)	Not applicable
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
			x	Exhaust/Emission System (1)	Not applicable
			x	Sliding Axle Assembly (if equipped) (8)	Not applicable

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Wheel2 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Wheel2 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Wheel2 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

PASS - vehicle passes inspection	Decal # A291562	Inspection Completed Date: 11Jun2026
----------------------------------	-----------------	--------------------------------------