



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A291563

Station #: 70207	Station Name: Frontline Truck & Trailer
Technician #: 88657	Technician Name: Thomas Fehr
Signing Officer #: 90414	Signing Officer Name: Howard Thomson

Customer Details:	
Name: Trewin Farms Corp.	Address: Box 102, Laird, Saskatchewan, S0K 2H0

Inspection Completed Date: 11Jun2026	Inspection Expiry Date: 30Jun2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2DEALBA22T2048091	Hubometer Reading:
Year: 2026	Vehicle Make/Model: DOEPKER TRAILER/TRAILER
Plate: 423 JUD	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.
--



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70207

Station Name: Frontline Truck & Trailer

Technician #: 88657

Technician Name: Thomas Fehr

Signing Officer #: 90414

Signing Officer Name: Howard Thomson

Customer Details:

Name: Trewin Farms Corp.

Address: Box 102, Laird, Saskatchewan, S0K 2H0

Vehicle Details:

VIN: 2DEALBA22T2048091

Hubometer Reading:

Year: 2026

Vehicle Make/Model: DOEPKER TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
			x	Fire Extinguisher (5)	Not applicable
			x	Auxiliary Controls/Equip (5)	Not applicable

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
			x	Fuel System (1)	Not applicable
			x	Battery/Wiring Condition (7)	Not applicable

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
			x	Hyd Brake System/Components (3.1)	Not applicable
		x		Air Brake System/Components (3.2)	Adjusted brakes
			x	Elec Brake System/Components (3.1)	Not applicable
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
			x	Self-Steering Axle (2&4)	Not applicable
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
			x	Exhaust/Emission System (1)	Not applicable
			x	Sliding Axle Assembly (if equipped) (8)	Not applicable

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Wheel2 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

Wheel2 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 31.0 degrees • Brake Stroke: 1 3/4 in

PASS - vehicle passes inspection

Decal # A291563

Inspection Completed Date: 11Jun2026