



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A209332

Station #: 71933

Station Name: TR Repair Inc.

Technician #: 86691

Technician Name: Tyson Brown

Signing Officer #: 91584

Signing Officer Name: Cynthia Brown

Customer Details:

Name: Yas-Farms Ltd

Address: RR#1, Richard, Saskatchewan, S0M2P0

Inspection Completed Date: 05Feb2026

Inspection Expiry Date: 31Aug2026

Vehicle Details:

VIN: 1XKDDP0XXEJ965515

Odometer Reading: 888832 km

Year: 2014

Vehicle Make/Model: KENWORTH/HEAVY VEHICLE

Plate: 360MDI

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71933

Station Name: TR Repair Inc.

Technician #: 86691

Technician Name: Tyson Brown

Signing Officer #: 91584

Signing Officer Name: Cynthia Brown

Customer Details:

Name: Yas-Farms Ltd

Address: RR#1, Richard, Saskatchewan, S0M2P0

Vehicle Details:

VIN: 1XKDDP0XXEJ965515

Odometer Reading: 888832 km

Year: 2014

Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

X				Air Brake System/Components (3.2)	
X				Wheel Bearings (9)	
X				King Pins/Ball Joints (4)	
X				Steering Linkage (4)	
X				Tires/Wheels (9)	
X				Self-Steering Axle (4)	
X				Engine/Transmission Mounts (1)	
X				Frame/Crossmembers/Mounts (8)	
X				Suspension/Axles (2)	
X				Drive Shaft/Universal Joints (1)	
X				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 18 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 0.698 in • Cam Rotation: 58.0 degrees • Brake Stroke: 36 mm

Wheel2-On : Tire Tread Depth: 18 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 0.684 in • Cam Rotation: 62.0 degrees • Brake Stroke: 37 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 22 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 22 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 0.869 in • Cam Rotation: 18.0 degrees • Brake Stroke: 35 mm

Wheel3-On : Tire Tread Depth: 22 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 0.862 in • Cam Rotation: 22.0 degrees • Brake Stroke: 36 mm

Wheel4 : Tire Tread Depth: 22 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 22 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 22 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 0.865 in • Cam Rotation: 18.0 degrees • Brake Stroke: 38 mm

Wheel3-On : Tire Tread Depth: 22 mm

Brake(1): S-CAM Brake

- Min Brake Lining/Pad: 0.498 in • Cam Rotation: 98.0 degrees • Brake Stroke: 37 mm

Wheel4 : Tire Tread Depth: 22 mm

Brake(1): No Brake

N/A