



JPRO® DIAGNOSTIC REPORT

Connection Date: February 12, 2026 7:44 AM
 Print Date: February 12, 2026 7:44 AM

VIN	1FVHCYBS2BDBB3812
Vehicle Make	Freightliner
Model	M2
Series	106 Medium Duty
Model Year	2011

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins 8.3L ISC	73155258	04993120 00042581 062110132232 05030404 I0 BBO	J1939 (High)
Brakes	WABCO E Basic(12V) 4S/4M	382130	E208	J1939 (High) J1587 (Low)
Instrument Cluster	DTNA ICU3X-2010	N/A	U.r.4.3.0	J1939 (High)
Bulkhead Module	Freightliner BHM_L	146358	U.r.1.G1.06.60	J1939 (High) J1587 (Low)
Chassis Module	Freightliner CHM_L	N/A	U.r.1.E0.03.40	J1939 (High)



JPRO® DIAGNOSTIC REPORT

Connection Date: February 12, 2026 7:44 AM

Print Date: February 12, 2026 7:44 AM

Vehicle Key Data Points

Description	Parameter Value	Description	Parameter Value
Avg Fuel Econ	5.30 mpg	Idle Fuel Used	95.90 gal
Battery Potential	12.70 volts	DPF Soot Level	Low
Total Idle Hrs	108.90 hrs	DPF Derate	Low
Idle Shutdown	Not Available	Total Engine Run Time	250.10 hrs
Road Speed Limit	75.00 mph	Cruise Spd Limit	75.00 mph
PTO Status	Off/Disabled	Malfunction Indicator Lamp	Off
Red Stop Lamp	Off	Amber Warning Lamp	On
Protect Lamp	Off	Parking Brake Switch	On
Engine Speed	0 rpm	DPF Lamp Command	Off
Exhaust System High Temperature Lamp Command	Off	ABS Control Status	Off
ABS Control Status, Trailer	Not Available	Odometer	4,845.08 mi
Engine Odometer	4,845.08 mi	Instrument Cluster Odometer	4,845.08 mi
Fuel	30%	Coolant	Normal
Diesel Exhaust Fluid	96%		

Vehicle Issues



No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count