

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 12/23/2021

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 5

Work performrd (print)

Reset start up codes set to

1430 and 1776 and did inspection

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert willingham, Justin Groufalias

Total Hours spent on Repair: 4

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/7/2022

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 9

Work performrd (print)

Had to do a remote reflash on
machine

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin garoufalias

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin ~~YBN 20495~~ **6/14** Serial: YBN20495
Make: cat location: 3514
Model: 336 Hours/Mileage: 12

Work performrd (print)

Removed old teeth and installed
double spike teeth

Parts/supplies used (print)

A: 7- 505-4105 double spike teeth

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert willingham , Justin Garoufalias

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/4/2023 Serial: YBN20495
Make: cat location: 3514
Model: 336 Hours/Mileage: 504

Work performrd (print)
Did 500 hour service

Parts/supplies used (print)

- A: 1-496-9841 air filter
- B: 1-434-3928 fuel filter
- C: 1-523-4987 fuel water/sep
- D: 1-500-0483 oil filter
- E: 1-500-0957 A/C filter
- F: 1-580-5439 cab-n-air filter

Repaired Completed By (Mechanic-Print)
Robert Willingham,Justin Garoufalias

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/27/2023 Serial: YBN20495
Make: cat location: 3514
Model: 336 Hours/Mileage: 903

Work performrd (print)
removed old battery's and Installed
new

Parts/supplies used (print)
A: 2-115-2422 battery

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Jared Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 9/11/2023

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 944

Work performrd (print)

Reset engine fault with ET ran

function test will try one more time

if it trips out will have to call mustang

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 10/11/2023

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 972

Work performrd (print)

replaced fuel filter's

Parts/supplies used (print)

A: 2-434-3928 fuel filter

B: 1-523-4987 fuel water/sep filter

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Jared willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Mechanic Equipment Repair Report

Date begin 10/12/2023 Serial: YBN20495
Make: cat location: 3514
Model: 336 Hours/Mileage: 972

Work performrd (print)
Tried to reset aftertreatment fault
code would not reset had to call
mustang for warranty work

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain: waiting on mustang cat

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 10/13/2023

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 972

Work performrd (print)

discussed and meet Mustang Cat
about the DEF codes

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Mechanic Equipment Repair Report

Date begin 10/25/2023 Serial: YBN20495
Make: cat location: 3514
Model: 336 Hours/Mileage: 1,010

Work performrd (print)
Did 1,000 hour service

Parts/supplies used (print)

- A: 1-496-9841 air filter

- B: 2-434-3928 fuel filter

- C: 1-523-4987 fuel water/sep filter

- D: 1-500-0483 oil filter

- E: 1-500-0957 cab-n-air filter
 1-580-5439 A/C filter

- F: 8-515-3973 1 gallon engine oil

Repaired Completed By (Mechanic-Print)
Jared Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 11/1/2023 Serial: YBN20495
Make: Cat location: 3514
Model: 336 Hours/Mileage: 1,013

Work performrd (print)

Looked up hours on track hoe @ 3514
checked warranty on left hand controller's
and called mustang for warranty on horn
buttons for YBN20495 and LKG20052

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 4

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 11/21/2023

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 1,015

Work performrd (print)

worked with mustang on replacing
left controller to repair horn button
waranty

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/23/2024

Serial: YBN20485

Make: cat

location: R/C

Model: 336

Hours/Mileage: 2,965

Work performrd (print)
did 500 hour service

Parts/supplies used (print)

A: 1-496-9841 air filter

B: 1-434-3928 fuel filter

C: 1-523-4987 fuel water/sep filter

D: 1-500-0483 oil filter

E: 1-500-0957 cab-n-air filter

F: 1-580-5439 A/C filter

8-515-3973 1 gallon engine oil

Repaired Completed By (Mechanic-Print)

Robert,Danyel Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Mechanic Equipment Repair Report

Date begin 12/16/2024

Serial: YBN20495

Make: cat

location: 3514

Model: 336

Hours/Mileage: 1,413

Work performrd (print)

Troubleshoot code's found bad
wire on stick postion sensor
ordered part's

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 1/14/2025 Serial: YBN20495
Make: cat location: R/C
Model: 336 Hours/Mileage: 1,542

Work performrd (print)

Did 500 hour service,changed oil in
final drive's and Installed wiring Harness
on stick

Parts/supplies used (print)

- A: 1-496-9841 air filter
 1-434-3928 fuel filter
- B: 1-523-4987 fuel water/sep filter
 1-500-0483 oil filter
- C: 1-500-0957 A/C filter
 1-580-5439 cab-n-air filter
- D: 515-3973 1 gallon engine oil
 1-579-5233 harness
- E: 1-8t-9576 5 gallon gear oil

F:

Repaired Completed By (Mechanic-Print)
Robert , Danyel Willignham

Total Hours spent on Repair: 6

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/11/2025 Serial: YBN20495
Make: Cat location: R/C
Model: 336 Hours/Mileage: 2,000

Work performrd (print)

Did 2,000 hour service and drained
and filled left and right hand final drive's

Parts/supplies used (print)

A: 1-496-9841 air filter
 1-496-9842 air filter (secondary)
B: 1-439-3928 fuel filter
 1-523-4987 fuel water/sep filter
C: 1-500-0486 oil filter
 1-580-0957 A/C filter
D: 1-580-5439 cab-n-air filter
 1-515-3973 1 gallon engine oil
E: 1-8T-9576 5 gallon 50w oil

F:

Repaired Completed By (Mechanic-Print)
Robert,Danyel willingham

Total Hours spent on Repair: 5 1/2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/15/2025

Serial: YBN20495

Make: cat

location: R/C

Model: 336

Hours/Mileage: 2,000

Work performrd (print)

cut and removed old teeth and Installed
new

Parts/supplies used (print)

A:

B: 7-505-4105 Double spike teeth

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert ,Danyel Willingham

Total Hours spent on Repair: 3 1/2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 10-14-2025 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 2,391

Work Performed (print)

Removed and installed fuel filter's and
cleared code's

Parts/supplies used

- A. 1-434-3928 fuel filter
- B. 1-523-4987 fuel water/sep filter
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 1

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 12/10/2025 Serial# YBN20495
Make: Cat Location: R/C
Model: 336 Hours/Mileage: 2,489

Work Performed (print)

trouble shoot stick jerking found bad
valve solenoid ordered part's

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 1-30-2026 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 2,641

Work Performed (print)

Trouble shoot stick shaking found bad
pilot control valve sticking ordered part

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: |

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 01-28-2026 Serial# YBN20495
Make: cat Location: R/C
Model: 349 Hours/Mileage: 2,630

Work Performed (print)

made sure machine would start and let run
and warm up for job in the morning

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):

Robert Willingham

Toatal hours spent on Repairs: /

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -

Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 04/01/2026 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 2,787

Work Performed (print)

Code came on for Def pump reverse valve
stuck cleared code and will monitor

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 04-29-2026 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 2,802

Work Performed (print)

Hyd levers stoped working and boom would just stop and the A/c quit working,found harness full of water and called mustang to have ECM flashed and ordered new harness

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) no

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 4-30-2026 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 2,802

Work Performed (print)

Flashed ECM with mustang cat Got
A/C working good still intermittenly
Hyd lock needs to be cycled waiting
on part

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 3 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) no

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 05-14-2026 Serial# YBN20495
Make: Cat Location: R/C
Model: 336 Hours/Mileage: 2,826

Work Performed (print)

Cleared codes because we changed IMU sensor on stick

Parts/supplies used

- A.
- B. 1-616-4042 IMU sensor
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 05/04/2026 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 7,100

Work Performed (print)

Removed and installed harness fixed that problem and found position sensor bad prdered part's

Parts/supplies used

- A.
- B. 1-579-5233 harness
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 3 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 06-22-2026 Serial# YBN20495
Make: cat Location: R/C
Model: 336 Hours/Mileage: 2,914

Work Performed (print)

Remoed and installed fuel filter,reset
code and got measurements for weld
on wear plates for stick

Parts/supplies used

- A. 1-434-3928 fuel filters
- B. 1-523-4987 fuel water/sep filter
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: **272**

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 06-26-2026 Serial# YBN20495

Make: cat Location: R/C

Model: 336 Hours/Mileage: 2,922

Work Performed (print)

hammered pin out of stick to bucket, cleaned out grease from stick, cut bushing's with cutting torch, and pressed in new bushing's and seal's, welded shim's on side of stick and installed stick to bucket with hammered in pin

Parts/supplies used

- A.
- B. 1-251-2552 pin
- C.
- D. 2-367-8467 seal
- E. 2-166-1496 seal
- F. 2-504-7633 bushing (bearing)
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 8

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain: