

Name:	[REDACTED]	Vin #:	BL4134	Date:	6-12-23
Phone #:	[REDACTED]	Mileage:	789,799	Engine:	DD15
Lic. Plate #:	[REDACTED]	Unit #:	41		
Comments:					

Job Description:	Parts	Labor	Labor Total
1) New Engine <u>See Attachment</u>	↓	↓	↓
	8457.68	8,000.00	16,457.68
		Subtotal \$	16,457.68
		Tax	
		G. Total \$	16,457.68

I agree to pay for work done as above described. I agree that I checked my vehicle and the repair done.
The work performed was satisfactory. If any repair to a used tire is done, it is without warranty and at my own risk.
Warranty on engine work should be written on receipt. Customer is responsible for bringing truck for warranty, if any.

Authorized by: _____

I agree to pay for work done as above described. I agree that I checked my vehicle and the repair done. The work performed was satisfactory. If any repair to a used tire is done, it is without warranty and at my own risk. Warranty on engine work should be written on receipt. Customer is responsible for bringing truck for warranty, if any. Authorized by _____

Authorized by: _____

wo:3781

TRUCK #41

VIN: BL4134

<u>JOB DESCRIPTION</u>	<u>PARTS</u>	<u>LABOR</u>	<u>TOTAL</u>
1). New MOTOR (Parts by customer)	-	8,000.00	8,000.00
2). Valve Calibration (Pedro 5/26/23)	500.00	-	500.00
3). Installetion Kit outside parts	624.42		624.42
4).Air compressor Rebuild (D&M)/ Hose Assy -Air discharge	938.89		938.89
5). Wiring Harness, Fuel Injectors	195.98		195.98
6).Breather Assembly Crancase	276.47		276.47
7). Engine belts	91.96		91.96
8). Turbo-transmission (turbina)	2,317.98		2,317.98
9).Isolator-Assy , engine front &Rear	520.00		520.00
10). High Pressure fuel Lines	113.87		113.87
11).Transmission Synt Oil,Input shaft & cover kit,Oil filter	641.05		641.05
12).Gaskets/Fittings/Clamps/Hoses	840.63		840.63
13). Hood Mount Mirror & Fog Assemblies	286.43		286.43
14). Tow truck to Dealer For Warranty-missing valve lock	450.00		450.00
5). Oil service & Filters & Antifreeze	660.00		660.00
TOTAL	8,457.68	8,000.00	16,457.68

