

## Search Work Orders - All History(All work types)

| Assigned To                  | Scheduled Date | WO #  | Entity Name | Problem Description                                                                                                                                                                                                                                                                                                                                                                              | Location | Status Date | Type   |
|------------------------------|----------------|-------|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------|--------|
| Anthony Magri                | 8/31/2026      | 21801 | HT30        | troubleshoot no start                                                                                                                                                                                                                                                                                                                                                                            | 24-1001  | 8/28/2026   | Non PM |
| Marcos Erivez                | 8/27/2026      | 21780 | HT27        | close belly pan on haul truck/ help peter with ht30                                                                                                                                                                                                                                                                                                                                              | 26-1008  | 8/24/2026   | Non PM |
| Pedro Suarez                 | 8/27/2026      | 21771 | HT30        | replace 2 orings of hyd filters                                                                                                                                                                                                                                                                                                                                                                  | 24-1001  | 8/24/2026   | Non PM |
| Marcos Erivez, Eddie Salas   | 6/20/2026      | 21325 | HT30        | installed batteries and turn machine on and move to wash bay<br>pull out batteries to charge cleaned out the box where batteries go<br>checked cables and they are good                                                                                                                                                                                                                          | 24-1001  | 7/23/2026   | Non PM |
| Anthony Magri                | 4/13/2026      | 20854 | HT30        | RR Belt/ test run/troubleshoot leak                                                                                                                                                                                                                                                                                                                                                              | 24-1001  | 5/6/2026    | Non PM |
| John Kiley                   | 3/5/2026       | 20543 | HT30        | Work n putting exhaust & air box back in. Test run. Oil leak from turbo, fix & top off engine oil & coolant.                                                                                                                                                                                                                                                                                     | 24-1001  | 3/20/2026   | Non PM |
| John Kiley, Colton Yeaman    | 1/26/2026      | 19086 | HT30        | Volvo DPF re-install<br>Remove DPF for cleaning<br>Diag exhaust issue.                                                                                                                                                                                                                                                                                                                           | 24-1001  | 2/12/2026   | Non PM |
| Jose Gallegos                | 12/18/2025     | 19081 | HT30        | Cleaning the windows inside and out to the haul truck.<br>Power washing haul truck                                                                                                                                                                                                                                                                                                               | 24-1001  | 1/23/2026   | Non PM |
| Alfredo Lopez, Anthony Magri | 8/21/2025      | 18402 | HT30        | Air conditioning not working.<br>A/C<br>From: Inspections<br>Recorder: Emanuel Lecona Galvez<br>Job: 24-1001<br>Reported: 8/8/2025<br>Form: Claystone Equipment<br>Inspection (Espanol)<br>Item: Acondiciona dor de airo<br>Note:<br>Recorder: Emanuel Lecona Galvez<br>Job: 24-1001<br>Reported: 8/9/2025<br>Form: Claystone Equipment<br>Inspection (Espanol)<br>Item: Acondiciona dor de airo | 24-1001  | 8/27/2025   | Non PM |
| Anthony Magri                | 4/25/2025      | 17597 | HT30        | Service                                                                                                                                                                                                                                                                                                                                                                                          | 24-1001  | 5/22/2025   | PM     |
| Anthony Magri                | 4/25/2025      | 17594 | HT30        | Fill dBox<br>From: Inspections<br>Recorder: Librado Diaz<br>Job: 24-1001<br>Reported: 4/4/2025<br>Form: Claystone Equipment<br>Inspection (Espanol)<br>Item: Fugas Hydraulicas<br>Note: Tione fugas idraulicas                                                                                                                                                                                   | 24-1001  | 5/15/2025   | Non PM |
| Anthony Magri, Noel Pavon    | 1/31/2025      | 15725 | HT30        | start machine                                                                                                                                                                                                                                                                                                                                                                                    | 24-1001  | 5/15/2025   | Non PM |
| Pedro Suarez                 | 11/8/2024      | 15163 | HT30        | Check 360 and order parts                                                                                                                                                                                                                                                                                                                                                                        | 24-1001  | 5/15/2025   | Non PM |
| Anthony Magri, Noel Pavon    | 11/1/2024      | 15104 | HT30        | Clean air/oil filter. Service                                                                                                                                                                                                                                                                                                                                                                    | 24-1001  | 3/11/2025   | Non PM |

|                                                                  |           |       |           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |         |            |        |
|------------------------------------------------------------------|-----------|-------|-----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|------------|--------|
| Noel Pavon, Pedro Suarez, Stormy Wetherington, Troy Wetherington | 1/25/2024 | 11772 | RHT VOLVO | 1st A60H serial # is<br>VCE0A60HK00340050 Claystone unit<br># should be RHT27 (current Rango unit # 12603 stenciled in red on truck)<br>PS 2.0 FE<br>2nd A60H serial # is<br>VCE0A60HK00340062 Claystone unit<br># should be RHT28 (current Rango unit # 12605 stenciled in red on truck)<br>PS 2.0 FE<br>TW/SW 4.8 Start<br>3rd A60H serial # is<br>VCE0A60HE00340105 Claystone unit<br># should be RHT29 (current Rango unit # 12607 stenciled in red on truck)<br>NP 5.0<br>PS 1.5 FE<br>4th A60H serial # is<br>VCE0A60HE00340115 Claystone unit<br># should be RHT30 (current Rango unit # 12612 stenciled in red on truck)<br>NP 2.5<br>PS 2.0 FE<br>5th A60H serial # is<br>VCE0A60HK00340143 Claystone unit<br># should be RHT31 (current Rango unit # 12614 stenciled in red on truck)<br>NP 1.5<br>PS 1.0 FE<br>TW/SW 6.8 Start<br>6th A60H serial # is<br>VCE0A60HJ00350009 Claystone unit # should be RHT32 (current Rango unit # 12618 stenciled in red on truck)<br>PS 2.0 FE<br>TW/SW 4.8 Start<br>NP 1.0 tire PSI<br>7th A60H serial # is<br>VCE0A60HA00350029 Claystone unit # should be RHT33 (current Rango unit # 12619 stenciled in red on truck)<br>PS 2.5 FE<br>SW 1.0 Mirror<br>8th A60H serial # is<br>VCE0A60HA00350032 Claystone unit # should be RHT34 (current Rango unit # 12622 stenciled in red on truck)<br>PS 2.0 FE<br>TW/SW 4.8 Start<br>9th A60H serial # is<br>VCE0A60HJ00350053 Claystone unit # should be RHT35 (current Rango unit # 12629 stenciled in red on truck)<br>PS 2.0 FE<br>10th A60H serial # is<br>VCE0A60HJ00350074 Claystone unit # should be RHT36 (current Rango unit # 12640 stenciled in red on truck)<br>PS 1.5 FE<br>TW/SW 4.8 Start<br><br>TW 1.0 Tailgate pin. |         | 11/16/2024 | Non PM |
| Anthony Magri, Noel Pavon                                        | 10/4/2024 | 14832 | HT30      | Troubleshoot eng                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | 24-1001 | 11/16/2024 | Non PM |
| Anthony Magri, Noel Pavon                                        | 9/27/2024 | 14788 | HT30      | Troubleshoot inspect steer cyl                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | 24-1001 | 11/16/2024 | Non PM |

|                                                |           |       |       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |         |            |        |
|------------------------------------------------|-----------|-------|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|------------|--------|
| Stormy Wetherington                            | 9/13/2024 | 14656 | HT30  | Fill tire<br>From: Inspections<br>Recorder: Jose Argueta<br>Job: 24-1001<br>Reported: 9/7/2024<br>Form: Claystone Equipment<br>Inspection (Espanol)<br>Item: Neumaticos<br>Note: Neum?tico de enfrente lado derecho le falta aire<br>Troubleshoot brake adj                                                                                                                                                                                                                                                                           | 24-1001 | 11/16/2024 | Non PM |
| Anthony Magri, Noel Pavon                      | 9/6/2024  | 14601 | HT30  | From: Inspections<br>Recorder: Nicholas MacIntosh<br>Job: 24-1001<br>Reported: 8/24/2024<br>Form: Claystone Equipment<br>Inspection<br>Item: Brakes-Park<br>Note: Park brake does not hold                                                                                                                                                                                                                                                                                                                                            | 24-1001 | 11/16/2024 | Non PM |
| Anthony Magri, Noel Pavon                      | 8/30/2024 | 14555 | HT30  | Hook up computer. Test run                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 24-1001 | 11/16/2024 | Non PM |
| Anthony Magri, Noel Pavon                      | 8/30/2024 | 14553 | HT30  | Troubleshoot bad fan. Fan broke.<br>Coolant RR                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 24-1001 | 11/16/2024 | Non PM |
| Anthony Magri, Noel Pavon, Stormy Wetherington | 9/12/2024 | 14604 | HT30  | Rebuild hydraulic fan for radiator<br>Fan assembly disassemble broken fan.                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 24-1001 | 11/2/2024  | Non PM |
|                                                |           | 14046 | HT30  | Ht30 has a injector system failure code on. Repaired by Chris at ETI<br>Requested By: Francisco Moreno<br>Requested Date: 3/12/2024 11:24:30 AM<br>From: HCSS Field                                                                                                                                                                                                                                                                                                                                                                   | 24-1001 | 7/12/2024  | Non PM |
| Noel Pavon                                     | 5/23/2024 | 12735 | HT30  | Troubleshoot drive train. Take oil sample.<br>From: Inspections<br>Recorder: Carlos Quiroz Martinez<br>Job: 24-1001<br>Reported: 5/13/2024<br>Form: Claystone Equipment<br>Inspection (Espanol)<br>Item: Transmission<br>Note: Al momento de meter velocidad y de quit?rsela truena<br>Y al meter reversa igual truena.<br>Como si fuera abajo por el diferencial<br>Recorder: Jose Ciprian<br>Job: 24-1001<br>Reported: 3/19/2024<br>Form: Claystone Equipment<br>Inspection<br>Item: Oil Level<br>Note: Low hydraulic and motor oil | 24-1001 | 6/10/2024  | Non PM |
| Noel Pavon                                     | 5/2/2024  | 12499 | HT30  | Coolant leak. Swap revisor with down truck.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 24-1001 | 6/3/2024   | Non PM |
| Noel Pavon                                     | 5/23/2024 | 12734 | RHT30 | Troubleshoot drive train. Take oil sample.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 24-1001 | 5/20/2024  | Non PM |
| Noel Pavon                                     | 4/25/2024 | 12431 | HT30  | Check tire PSI.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 24-1001 | 5/6/2024   | Non PM |
| Alfonso Rodriguez-Rodriguez                    | 3/7/2024  | 12060 | HT30  | 500 hour service.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 24-1001 | 3/18/2024  | Non PM |
| Pedro Suarez                                   | 2/29/2024 | 11982 | HT30  | Install stickers.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 24-1001 | 3/4/2024   | Non PM |
| Pedro Suarez                                   | 2/22/2024 | 11960 | HT30  | Air tires.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 24-1001 | 3/4/2024   | Non PM |

Filter:

Wednesday, September 9, 2026