

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
25/08/2021 R01087724		
101	01VOBD	ATTEND VOLVO BREAKDOWN
102	01	BREAKDOWN LABOUR
103	VT84161777	SEAT BELT KIT RHS FH VER4
104	N	C: seat belt stuck wont release
105	N	C: internal fault in seat betl mechanism
106	N	C: drove to breakdown in
107	N	mt view quarry , located truck, checked for the issue, found belt
108	N	stuck, and won't go out. can't free it up. Removed and replaced
109	N	seat belt
110	N	Op/code: 88408 @ 0.8
111	N	Defect : 32
112	N	Causal P/no. 84161777
113	N	Job ref: 8194549-1
114	STAR	*****
401	01VOBD	ATTEND VOLVO BREAKDOWN
402	TC	TRAVEL CUSTOMER
403	N	C: R/H seat belt stuck
404	N	C-Seat belt seized
405	N	C: Travel to vehicle
406	N	Op/code: 19400 @ 1.5
407	N	25/8/21 5.30 PM – 6.40 PM
408	N	25/8/21 7.00 – 7.20 PM
409	N	KLMS - 33
410	N	Defect: 32
411	N	VEHICLE LOCATED AT WYNDDHAM VALE QUARRY, BALLAN RD
412	N	unable to claim due to less than 50 km and sold by CMV Derrimut
413	STAR	*****
13/11/2021 R01089852		
101	11VO	CHECK AND RECTIFY ENGINE LIGHT ON THE DASH
102	11	ENGINE ELECTRICAL LABOUR
103	N	P) Check engine light on the dash.
104	N	C) P055B64: Piston Cooling Oil Pressure Sensor Range/Performance,
105	N	Signal Plausibility Failure and P007164: Ambient Air Temperature
106	N	Sensor Range/Performance, Signal Plausibility Failure
107	N	C: Connected tech tool, checked and found piston cooling oil pressure
108	N	and ambient air temp faults. Programmed EMS and VMCU, cleared fault
109	N	codes, test drove vehicle, rechecked for fault and all okay.
110	N	Op/code: 17026 @ 0.2
111	N	Op/code: 17906 @ 0.5
112	N	Defect : 49
113	N	Causal : 23141251
114	N	Job ref: 8199950-1
401	02CAMP	CAMPAIGN CHECK
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BYDONNA.....
405	N	DATE ...13/11/2021
406	N	*****
701	COVIDSAN	SANITISE TRUCK
702	STAR	*****
703	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
704	N	THE START & COMPLETION OF WORKS
16/11/2021 R01089906		
101	11VO	Rectify Engine system malfunction and De rate at next stop
102	11	Rectify Engine system malfunction and De rate at next stop
103	N	C-Inspect and rectify engine light on dash
104	N	C-Ambient temp & piston cooling fault P007164: Ambient Air
105	N	Temperature Sensor Range/Performance, Signal Plausibility Failure

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
106	N	C-Performed accessories kit programing. 17054-3
107	N	Op code: 36574 @ 1.3 (ECU,HMIOM,TECU)
108	N	Op code: 17054 @ 0.1 (Accessory Kit)
109	N	Op code: 17010 @ 0.2 (VCADS Connection)
110	N	Op code: 17012 @ 0.2 (Check Codes)
111	N	Defect: 49
112	N	Casual Part No: 21485928
113	N	Job Ref: 8200545-1
114	N	Auth: 200463221

20/11/2021 **R01090039**

101	11VO	RECTIFY ENGINE DERATE WARNING ON DASH
102	11	ENGINE MECHANICAL LABOUR
103	N	C: Check dash warning light on
104	N	C: P055B64: Piston Cooling Oil Pressure Sensor Range/Performance,
105	N	Signal Plausibility Failure and P007164: Ambient Air Temperature
106	N	Sensor Range/Performance, Signal Plausibility Failure
107	N	C: Connected tech tool, checked and found ambient temperature and
108	N	piston cooling sensor faults. Removed and replaced ambient
109	N	temperature sensor
110	N	Op/code: 38681 @ 0.2
111	N	Op/code: 17906 @ 0.5
112	N	Defect : 44
113	N	Causal : 20912514
114	N	Job ref:
115	STAR	*****
116	N	N.B. Same repair carried out on 18/11/21
401	02CAMP	CAMPAIGN CHECK
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BY EN
405	N	DATE 20.11.21
406	N	*****
701	COVIDSAN	SANITISE TRUCK
702	STAR	*****
703	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
704	N	THE START & COMPLETION OF WORKS

25/11/2021 **R01090197**

101	11VO	CHECK/RECTIFY ENGINE FAN - REDUCED PULLING PWR ON DASH
102	11	CHECK/RECTIFY ENGINE FAN - REDUCED PULLING PWR ON DASH
103	VT21706081	CABLE HARNESS ADBLUE EXHAUST FH-4
104	VT20469544	TAPE ELECTRICAL CLOTH VOLVO
105	N	C: REPLACE ADBLUE HARNESS
106	N	C: OPEN CIRCUIT ADBLUE HARNESS
107	N	C-FOUND OPEN CIRCUIT IN ADBLUE HARNESS.R&R ADBLUE HARNESS, CLEARED CODE
108	N	TESTED OK.
109	N	OP CODE: 25899 @ 2.0
110	N	OP CODE: 25846 @ 0.5
111	N	OP CODE: 17010 @ 0.2
112	N	OP CODE: 17012 @ 0.2
113	N	OP CODE: 17034 @ 0.2
114	N	OP CODE: 37102 @ 0.4
115	N	DEFECT: 43
116	N	CAUSAL: 21706081
117	N	JOB REF: 8200683-1
401	11VO	NON CLAIMABLE CONS
402	AMNARV56707	CONDUIT TUBING SPLIT 7MM X 10METRE
403	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA

02/12/2021 **R01090375**

101	34VO	RECTIFY ABS MALFUNCTION ON DASH
-----	------	---------------------------------

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
102	34	BRAKES LABOUR
103	N	C: Check ABS warning light on dash
104	N	C: C10113A, Wheel Speed Sensor 5 - Signal Has Too Many Pulses
105	N	C: Connected tech tool, checked and found 2dn drive left wheel speed
106	N	sensor fault. Inspected and found the sensor air back was out of
107	N	spec. It had been pushed out. Adjusted sensor air gap, cleared fault
108	N	codes, test drove vehicle and could not replicate fault (N.B.
109	N	Adjustment only covered for up to 120 days/50K).
110	N	Op/code: 59300 @ 0.4 – Checked and adjusted ABS sensor air gap
111	N	Op/code: 17010 @ 0.2
112	N	Op/code: 17012 @ 0.2
113	N	Op/code: 17105 @ 0.3 - Test drive
114	N	Defect : 46
115	N	Causal : 21663558
116	N	Job ref:8201174-1
401	34VO	RECTIFY AIR DRIER SERVICE REQUIRED WARNING ON DASH
402	34	BRAKES LABOUR
403	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
404	N	C: Check air drier warning fault
405	N	C: C101268: Air Filter Cartridge, Event Information
406	N	C: Checked and found air drier usage fault code. Replaced air drier
407	N	filter, rechecked for fault and all okay
408	N	Op/code: 56166 @ 0.3
409	N	Defect : 21
410	N	Causal : 23260134
411	N	Job ref: 8201174-2
701	02CAMP	CAMPAIGN CHECK
702	N	*****
703	N	NO CAMPAIGNS OUTSTANDING
704	N	CHECKED BY EN
705	N	DATE 2.12.21
706	N	*****
1001	COVIDSAN	SANITISE TRUCK
1002	STAR	*****
1003	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
1004	N	THE START & COMPLETION OF WORKS

01/02/2022 **R01092003**

101	11VO	CHECK ENGINE LIGHT ON - ON SITE WORKS
102	11	LABOUR
103	N	C: INSPECT AND RECTIFY ENGINE LIGHT ON DASH
104	N	C: AMBIENT TEMP FAULT P007164: AMBIENT AIR
105	N	TEMPERATURE SENSOR RANGE/PERFORMANCE, SIGNAL PLAUSIBILITY FAILURE
106	N	C: CLEARED CODES.
107	N	OP CODE: 17010 @ 0.2 (VCADS CONNECTION)
108	N	OP CODE: 17012 @ 0.2 (CHECK CODES)
109	N	DEFECT: 49
110	N	CASUAL PART NO: 21485928
111	N	JOB REF: 8204991-1

16/02/2022 **R01092499**

101	11VO	Check dash engine warning light on
102	11	ENGINE MECHANICAL LABOUR
103	N	C: Check dash engine warning light on
104	N	C: P007164: Ambient Air Temperature Sensor Range/Performance, Signal
105	N	Plausibility Failure
106	N	C: Connected tech tool, checked and cleared fault codes
107	N	Op/code: 17026 @ 0.2
108	N	Op/code: 17010 @ 0.2
109	N	Op/code: 17012 @ 0.2
110	N	Defect : 49
111	N	Causal : 23141251

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
112	N	Job ref: 8205648-1
113	N	Auth#: 200464856
15/03/2022 R01093349		
101	11VO	Check dash engine warning light on
102	11	ENGINE ELECTRICAL LABOUR
103	N	C: Check dash engine warning light on
104	N	C: P055B64: Piston Cooling Oil Pressure Sensor Range/Performance,
105	N	Signal Plausibility Failure and P007164: Ambient Air Temperature
106	N	Sensor Range/Performance, Signal Plausibility Failure
107	N	C: Connected tech tool, checked and cleared fault codes
108	N	Op/code: 17026 @ 0.2
109	N	Op/code: 17010 @ 0.2
110	N	Op/code: 17012 @ 0.2
111	N	Defect : 49
112	N	Causal : 23141251
113	N	Job ref: 8207864-1
114	N	Auth#: 200465469
22/03/2022 R01093584		
101	11VO	Check dash engine warning light on
102	11	ENGINE ELECTRICAL LABOUR
103	N	C: Check dash engine warning light on
104	N	C: P007164: Ambient Air Temperature Sensor Range/Performance, Signal
105	N	Plausibility Failure
106	N	C: Connected tech tool, checked and cleared fault codes
107	N	Op/code: 17026 @ 0.2
108	N	Op/code: 17010 @ 0.2
109	N	Op/code: 17012 @ 0.2
110	N	Defect : 49
111	N	Causal : 23141251
112	N	Job ref: 8208312 - 1
113	N	Auth#: 200465601
29/03/2022 R01093787		
101	11VO	Check dash engine warning light on
102	11	CAMPAIGNS LABOUR
103	N	C: Check dash engine warning light on
104	N	C: P007164: Ambient Air Temperature Sensor Range/Performance, Signal
105	N	Plausibility Failure
106	N	C: Connected tech tool, checked and cleared fault codes
107	N	Op/code: 17026 @ 0.2
108	N	Op/code: 17010 @ 0.2
109	N	Op/code: 17012 @ 0.2
110	N	Defect : 49
111	N	Causal : 23141251
112	N	Job ref: 8208672-1
113	N	Auth#: 200465668
06/04/2022 R01094061		
101	12VO	CHECK AND REPAIR ENGINE LIGHT UP ON DASH - ONSITE WORKS
102	12	CHECK AND REPAIR ENGINE LIGHT UP ON DASH - ONSITE WORKS
103	STAR	*****
104	n	C: Check dash engine warning light on
105	n	C: P055B64: Piston Cooling Oil Pressure Sensor Range/Performance,
106	n	Signal Plausibility Failure and P007164: Ambient Air Temperature
107	n	Sensor Range/Performance, Signal Plausibility Failure
108	n	C: Connected tech tool, checked and cleared fault codes
109	n	Op code: 17010 @ 0.2
110	n	OP code: 17012 @ 0.2
111	n	defect: 49
112	n	causaL; 23141251
113	n	job ref: 8209030-1

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
27/04/2022 R01094553		
101	11VO	REPAIR VEHICLE AS REPORTED TO HAVE ENGINE LIGHT ON DASH - ONSITE WORKS
102	11	REPAIR VEHICLE AS REPORTED TO HAVE ENGINE LIGHT ON DASH - ONSITE WORKS
103	N	C: Check dash engine warning light on
104	N	C: P055B64: Piston Cooling Oil Pressure Sensor Range/Performance,
105	N	Signal Plausibility Failure and P007164: Ambient Air Temperature
106	N	Sensor Range/Performance, Signal Plausibility Failure
107	N	C: Connected tech tool, checked and cleared fault codes
108	N	Op/code: 17010 @ 0.2
109	N	Op/code: 17012 @ 0.2
110	N	Defect : 46
111	N	Causal P/no. 21485928
112	N	Job ref: 8210383-1
113	N	CC200466227 100% approved
114	STAR	*****
401	12VO	CARRY OUT VEHICLE SOFTWARE UPDATE AS REQUIRED
402	12	CARRY OUT VEHICLE SOFTWARE UPDATE AS REQUIRED
403	N	C-Check and rectify engine light
404	N	C-Inspected found engine light on due to active fault code regarding
405	N	ambient air temp sensor P055B64: Piston Cooling Oil Pressure
406	N	Sensor Range/Performance, Signal Plausibility Failure
407	N	C-Followed procedure fault became inactive - cleared fault memory,
408	N	all good
409	N	Op/code: 36500 @ 0.5 (install software)
410	N	Defect: 46
411	N	Causal P/no. 21485928
412	N	Job ref: 8210383-2
413	N	CC 200466228 100% approved
414	STAR	*****
21/07/2022 R01097006		
101	24VO	Check and repair gear selector switch on
102	24L	TRANSMISSION LABOUR
103	VT23194828	GEAR SELECTOR I-SHIFT DASH MOUNTED
104	N	C: Check and repair gear selector switch on
105	N	C: Gear selector button sticking
106	N	C: Test drove vehicle and whilst changing gears the selector stopped
107	N	working. Checked operation and the gear lever button was sticking.
108	N	Connected tech tool, checked and could not find related fault codes.
109	N	Replaced gear selector, cleared fault codes, test drove, checked
110	N	operation and all okay.
111	N	Op/code: 43208 @ 0.8
112	N	Op/code: 17010 @ 0.2
113	N	Op/code: 37102 @ 0.4
114	N	Op/code: 19020 @ 0.3
115	N	Defect : 43
116	N	Causal : 23194828
117	N	Job ref:8215680-1
25/07/2022 R01097087		
101	64VO	CHECK AND REPAIR A/C NOT WORKING - no show
102	STAR	*****
401	02CAMP	NO CAMPAIGNS OUTSTANDING
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BY MICHAEL
405	N	DATE 25/07/22
406	N	*****
701	COVIDSAN	SANITISE TRUCK
702	STAR	*****
703	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
704	N	THE START & COMPLETION OF WORKS
05/08/2022	R01097473	
101	64VO	RECTIFY AC NW,
102	64	LABOUR
103	VT85022133	EXC COMPRESSOR AIR COND FM V4
104	VT23592900	DESICCANT
105	VT84164454	HOSE AIRCON TOP FM VER4
106	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
107	STAR	*****
108	N	OLD SERIAL: 001800915070
109	N	NEW SERIAL: 003428314091
110	STAR	*****
111	N	C: RECTIFY AC NW
112	N	C: AC COMPRESSOR OPEN CIRCUIT
113	N	C: -INSPECTED CABIN FILTER, FOUND BLOCKED. REPLACED CABIN FILTER.
114	N	-CONNECTED PRESSURE GAUGES AND FOUND COMPRESSOR NOT WORKING.
115	N	-CHECKED GAS LEVEL, FOUND NO GAS.
116	N	-PRESSURE TESTED AND FOUND LEAKING HIGH-PRESSURE HOSE.
117	N	-CHECKED SIGNALS TO COMPRESSOR. OK.
118	N	-TESTED COMPRESSOR FOUND OPEN CIRCUIT.
119	N	-FITTED NEW COMPRESSOR AND HIGH-PRESSURE HOSE, PRESSURE TESTED AND
120	N	VACUUMED AC SYSTEM.
121	N	-ALSO REPLACED DESSICANT/DRYER AS AC SYSTEM WAS OPEN TO ATMOSPHERE
122	N	AND SATURATED THE DESSICANT.
123	N	-CHARGED WITH GAS.
124	N	-CHECKED AC OPERATION AND FOUND SYSTEM TO BE OPERATING NORMALLY FOR A
125	N	SHORT PERIOD OF TIME THEN PROGRESSIVELY STOPPED WORKING.
126	N	-RECOVERED GAS AND TESTED COMPRESSOR. COMPRESSOR CLUTCH OPERATIONAL.
127	N	REMOVED COMPRESSOR PIPES AND NOTED THAT THE OIL WAS DARK AND
128	N	CONTAMINATED WITH DESSICANT FROM CONDENSER. SUSPECT DESSICANT BAG HAS
129	N	RUPTURED.
130	N	OP CODE: 87433 @ 1.7 A/C COMPRESSOR, REPLACE
131	N	OP CODE: 87405 @ 0.2 DRIER, REPLACE
132	N	OP CODE: 87468 @ 2.4 HIGH PRESSURE HOSE, REPLACE. INCLUDED: DRAINING
133	N	AND FILLING REFRIGERANT
134	N	OP CODE: 87015 @ 0.6 AC SYSTEM LEAKPROOFNESS TEST AND LEAKAGE CHECK
135	N	WITH GAS.
136	N	OP CODE: 87208 @ 0.1 AIR FILTER, AIR CONDITIONING, REPLACE
137	N	DEFECT: 43
138	N	CAUSAL: 85022133
139	N	JOB REF: 8217964-1
1001	12VO	RECTIFY ENGINE LIGHT ON DASH
1002	12	LABOUR
1003	STAR	*****
1004	N	C: ENGINE LIGHT ON DASH
1005	N	C: AMBIENT TEMP SENSOR OPEN CIRCUIT. P007164: AMBIENT AIR TEMPERATURE
1006	N	SENSOR RANGE/PERFORMANCE, SIGNAL PLAUSIBILITY FAILURE.
1007	N	C: CLEARED CODES AND RECHECKED OK
1008	N	OP CODE: 17010 @ 0.2 CONNECT-DISCONNECT DIAGNOSTIC TOOL
1009	N	OP CODE: 17012 @ 0.2 FAULT CODE READING
1010	N	DEFECT: 43
1011	N	CAUSAL: 20912514
1012	N	JOB REF:
1301	64VO	RECTIFY AC NW,
1302	64	LABOUR
1303	VT23592900	DESICCANT, AIR CON
1304	VT85022133	EXC COMPRESSOR AIR COND FM V4
1305	VT21063612	EVAPORATOR AIRCON FH D123488-
1306	VT22768927	CONDENSER AIR CONDITIONING FM VER-4
1307	VT21354759	VALVE TX AIR CONDITIONONG FH13

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
1308	VT84046397	O-RING KIT
1309	STAR	*****
1310	N	REF: R01097473 @ 187014KMS, 31/8/22.
1311	N	TRAVELLED: 1KM, 31/8/22.
1312	STAR	*****
1313	N	OLD SERIAL: 003428314091
1314	N	NEW SERIAL: 004014555012
1315	STAR	*****
1316	N	C: RECTIFY AC NW
1317	N	C: RUPTURED CONDENSER DESSICANT
1318	N	C: -REMOVED CONDENSER AND ASSOCIATED PLUMBING. VERIFIED DESSICANT BAG
1319	N	RUPTURED AND ALLOWED DESSICANT TO CONTAMINATE AND BLOCK THE AC
1320	N	SYSTEM.
1321	N	-INSPECTED TX VALVE AND FOUND CONTAMINATED WITH DESSICANT.
1322	N	-DISCONNECTED AC SYSTEM PLUMBING AND FLUSHED AS REQUIRED. FLUSHED
1323	N	EVAPORATOR.
1324	N	-REPLACED CONTAMINATED AC COMPRESSOR, CONDENSER, DESSICANT AND TX
1325	N	VALVE.
1326	N	-CHARGED WITH GAS AND VERIFIED AC OPERATION AND PERFORMANCE ON ROAD
1327	N	TEST.
1328	N	OP CODE: 87433 @ 1.7 A/C COMPRESSOR, REPLACE
1329	N	OP CODE: 87408 @ 0.5 CONDENSER, REPLACE. EXCLUDING DRAINING AND
1330	N	FILLING REFRIGERANT
1331	N	OP CODE: 87436 @ 0.7 EXPANSION VALVE, REPLACE
1332	N	OP CODE: 87405 @ 0.2 DRIER, REPLACE
1333	N	WITH GAS.
1334	N	OP CODE: 87900 @ 0.5 FLUSH AND CLEAN AC SYSTEM PLUMBING.
1335	N	DEFECT: 31
1336	N	CAUSAL: 23592900
1337	N	JOB REF: 8217965-1

14/09/2022 **R05032887**

101	17VO	REPAIR COOLANT LEAK
102	17	REPAIR COOLANT LEAK
103	85108914C	COOLANT VCS PER LITRE
104	STAR	*****
105	N	DEFECT: 21
106	N	C/P: 21687848
107	N	OP/CODE: 26006 .4
108	N	OP/CODE: 26000 .5
109	N	JOB REF: 8218837
110	N	
111	N	C: Repair coolant loss
112	N	C: Retarder hoses
113	N	C: Travelled onsite. Pressure tested cooling system and inspected for
114	N	leaks. Found retarder hoses to be leaking. Tightened clamps as
115	N	required and topped up coolant. Returned to workshop.
401	01VOBD	ATTEND VOLVO BREAKDOWN - COOLANT LOSS
402	TC	TRAVEL CUSTOMER
403	KT	KM TRAVEL CHARGE
404	N	ADDRESS: BARRO QUARRY, FORDS RD, SEYMOUR VIC
405	N	DRIVER PH # SAM 0404 000 809
406	STAR	*****
407	N	DEFECT: 24
408	N	C/P: 21687848
409	N	OP/CODE: 19400
410	N	JOB REF: 8218837
411	N	
412	N	W/SHOP-B/DOWN: 9.00am - 10.15am
413	N	REPAIR TIME: 10.15am - 11.15am
414	N	RETURN TRIP: 11.15am - 12.20pm

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
16/06/2021 RD0005918		
101	72VO	PD
102	72	PD LABOUR
103	C	CONSUMABLES;CLEANING;EPA
104	STAR	*****
401	72VO	CHROME MOONCAPS (NO N/COVERS OR DRESSRIM)
402	72	CHROME MOONCAPS (NO N/COVERS OR DRESSRIM) LABOUR
403	STAR	*****
404	SP7001480	HUB CAP CROME 7001480 REAR
701	72VO	NEW TYPE CAB BLOWER
702	72	NEW TYPE CAB BLOWER LABOUR
703	STAR	*****
704	PK01VT003A	PK01VT003A CAB BLOWER NEW STYLE FM/FH
705	VT21248577	DUST BLOWER KIT FH4/FM4 FH/FM
706	VT22354897	COMPRESSED AIR OUTLET KIT
1001	72VO	BLK PLASTIC GUARDS ON DRIVE
1002	72	BLK PLASTIC GUARDS ON DRIVE LABOUR
1003	STAR	*****
1004	PK01VT001	PK01VT001 DRIVE AXLE GUARDS (BLACK)
1005	VT60111996	WASHER BOLT TRUCK MOUNT POLE
1006	VT990962	NUT FLANGED 16MM LOCKING NYLOCK STAB BAR & CAB FL C0589
1007	AM9728HB300	KIT MUDGUARD MOUNTING TO POLE TRUCKMATE
1008	AM9728CMBOS	POLE BRACKET MUDGUARD MOUNTING TRUCKMATE
1009	VT984836	BOLT FLANGED 16MM X 70MM LONG 10.9 GRADE
1010	AM9728MG650B	MUDGUARD TRUCKMATE BLACK 650MM WIDE
1011	VT60113330	WASHER FAN ALTERNATOR
1012	VT21052112	LOOP KIT MUDGUARD REAR
1301	72VO	NARVA LED ROTATING ROOF LIGHT
1302	72	NARVA LED ROTATING ROOF LIGHT LABOUR
1303	STAR	*****
1304	PK01VT049	PK01VT049 CARTAGE NARVA ROTATING LIGHT
1305	SPBEACONBRACKET	BRACKET BEACON LIGHT NEW TRUCK FIT-UP
1306	VTWUR0057620	BOLT 6MM X 20MM LONG 8.8
1307	VTWUR03686	NUT NYLOC LOCK NUT 6MM
1308	VTWUR0411620	PENNY WASHER ZN 6.4X20X1.25
1309	MXX70MR2386	TIE, CABLE 'ADHESIVE' SQUARE
1310	AMNARV85064A	LED LIGHT BOX NARVA
1601	72VO	PTO WARNING BUZZER
1602	N	LABOUR FOR PTO WARNING BUZZER CARRIED OUT ON LINE 11
1603	STAR	*****
1604	PK01VT009	PK01VT009 PTO WARNING BUZZER KIT
1605	AMNARV72550BL	BUZZER
1606	VT20382270	DIODE ORANGE BLOCK 3AMP
1607	SPACX3024	TERMINAL SPADE BLUE FEMALE INSULATED
1608	SPACX3007	TERMINAL SPADE BLUE MALE
1609	AMNARV56820BK	TAPE ELECTRICAL INSULATION BLACK
1610	VT21244697	RELAY K5 MINI 24VOLT BOSCH TYCO V23234
1901	72VO	REMOVE BOTH FUEL TANKS (FUEL NECK SWAP)
1902	72	REMOVE BOTH FUEL TANKS (FUEL NECK SWAP) LABOUR
1903	STAR	*****
1904	s	PROGRAM FUEL TANK SIZE
1905	VT20392753	CAP FUEL TANK LOCKABLE X3
2201	72VO	ENGAGE POWER DIVIDER UP TO 18KPH
2202	N	LABOUR WAS CARRIED OUT ON LINE 11
2203	STAR	*****
2204	PK01VT010	PK01VT010 ENGAGE POWER DIVIDER UP TO 18KPH
2205	VT993360	HOUSING
2206	VT21244697	RELAY K5 MINI 24VOLT BOSCH TYCO V23234
2207	VT979002	TERMINAL PLUG FH NH SERIES
2208	VT978304	TERMINAL SUIT PLUG 978310 ECU ECS

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
2209	VT25392050	RELAY HOLDER FM/FH VER.4
2210	VT984724	BOLT FLANGED 6MM X 12MM LONG 8.8 GRADE
2211	VT23439998	VALVE SOLENOID PLASTIC 24V FM/FH(4) 1MPA
2212	VT990060	CABLE TERMINAL
2213	PK01VT230	PK01VT230 CARTAGE WEBBY EXTRA PARTS
2214	VT991971	RAUFOSS NIPPLE PLASTIC 8MMX1.0MM SMALL
2215	VT20578929	CONNECTOR SWITCH HOLDER MOUNT FM-FH VER4
2216	VT983020	CABLE TERMINAL
2217	VT977409	VIPS ELBOW NIPPLE
2218	VT991090	RAUFOSS VIPS MALE THREAD M12-PLASTIC 8MM TUBE
2219	VT3963412	RECEPTACLE HOUSING ELECTRICS 98 7 PIN
2220	VT3963409	CABLE TERMINAL SUIT 3963412
2221	VT20517988	HOUSING DIN ROUND PLUG REAR FOR CONDUIT
2222	VT991185	RAUFOSS T-NIPPLE SMALL
2223	VT980832	AIRLINE PLASTIC PIPE 8MM OD
2224	SPACX0812L	WIRE 3 CORE 3MM BLACK SHEATH
2225	SPACX0816L	WIRE 7CORE 3MM PER METER
2501	72VO	FIT TIPPER SWITCHES
2502	72	FIT TIPPER SWITCHES LABOUR
2503	STAR	*****
2504	PK01VT011	PK01VT011 TIPPER SWITCHES TRUCK AND TRAILER
2505	VT22281821	SWITCH DASH FH-M VER4 TIPPER BODY
2506	VT22281822	SWITCH TIPPER DASH FH-FM-4
2507	VT21850858	SWITCH DASH FH-M VER4 TAILGATE LOCK
2508	VT21850858	SWITCH DASH FH-M VER4 TAILGATE LOCK
2509	VT22328334	CAP SWITCH FHFM (4) TRUCK TILT
2510	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
2511	VT20578929	CONNECTOR SWITCH HOLDER MOUNT FM-FH VER4
2512	VT990060	CABLE TERMINAL
2513	SPACX0702	WIRE 3MM RED SINGLE CORE
2514	VT983020	CABLE TERMINAL
2801	72VO	MOVE HAZARD SWITCH
2802	N	LABOUR WAS CARRIED OUT ON LINE 11
2803	STAR	*****
3101	72VO	CONNECT JACK KNIFE SENSOR
3102	N	LABOUR HAS BEEN CARRIED OUT ON LINE 11
3103	STAR	*****
3401	72VO	CONNECT RINGFEEDER SESNSOR
3402	N	LABOUR WAS CARRIED OUT ON LINE 11
3403	STAR	*****
3404	PK01VT012	PK01VT012 RING FEEDER SENSOR KIT
3405	VT21244697	RELAY K5 MINI 24VOLT BOSCH TYCO V23234
3406	SPACX3024	TERMINAL SPADE BLUE FEMALE INSULATED
3407	VT20382270	DIODE ORANGE BLOCK 3AMP
3408	SPACX3007	TERMINAL SPADE BLUE MALE
3409	VT25392050	RELAY HOLDER FM/FH VER.4
3410	VT978304	TERMINAL SUIT PLUG 978310 ECU ECS
3411	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
3412	VT979002	TERMINAL PLUG FH NH SERIES
3701	72VO	CONNECT TARP
3702	72	CONNECT TARP LABOUR
3703	STAR	*****
3704	SPACX1728	FUSE HOLDER W/PROOF 10A
3705	VT978999	FUSE BLADE 20 AMP YELLOW D123488-
3706	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
4001	72VO	PARK BRAKE ALARM
4002	72	PARK BRAKE ALARM LABOUR
4003	STAR	*****
4004	S	P/BRAKE ALARM CONV KIT - 85142228
4005	S	P/BRAKE ALARM CONV KIT - 85142182

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
4006	STAR	*****
4007	VT978304	TERMINAL BODY BUILDER PLUG ECU ECS
4008	VT9456277	HOUSING
4009	VT978309	INSULATOR
4010	VT978310	SOCKET INSULATOR GREEN 30POLE DASH BUS
4301	72VO	PROGRAM PARAMETER TEMPLATE
4302	72	PROGRAM PARAMETER TEMPLATE
4303	STAR	*****
4601	72VO	3MIN IDLE SHUTDOWN
4602	72	3MIN IDLE SHUTDOWN
4603	STAR	*****
4901	72VO	HARDWIRE REVERSE BUZZER
4902	72	HARDWIRE REVERSE BUZZER LABOUR
4903	STAR	*****
5201	72VO	RELOCATE BACK PRESSURE SENSOR
5202	72	RELOCATE BACK PRESSURE SENSOR LABOUR
5203	STAR	*****
5204	PK01VT205	PK01VT205 BACK PRESSURE RELOCATE NEW TRUCK
5205	VT990950	NUT FLANGED LOCK NUT 8MM 8 GRADE
5206	VT993354	NIPPLE
5207	SPBPSKIT	HOSE BRAIDED BACK PRESSURE SENSOR
5208	VT965556	BRACKET ANGLE 90 DEGREE ONE HOLE
5209	VT984734	BOLT FLANGED 8MM X 20MM LONG 8.8 GRADE
5210	VT980464	CABLE TIES 14" HEAVY DUTY
5211	VT965552	BRACKET
5501	72VO	CB & UHF RADIOS WITH REMOTE
5502	72	CB & UHF RADIOS WITH REMOTE LABOUR
5503	STAR	*****
5504	N	GLUE MIC DOWN - DO NOT SCREW
5505	PK01VT005	PK01VT005 CB & UHF RADIO KIT GME W/ ANTENNA
5506	AM9771TX2720	RADIO CB AM UNIT 27MHZ
5507	AMNARV56272BL	ELECTRICAL PLUG KIT NARVA SUIT UHF
5508	AM9771LEM6P	MICROPHONE EXT LEAD 4 METRE
5509	AM9771AE4005	LEAD ASSEMBLY 4.5DB ARIEL
5510	AM9771MB207	MOUNT CB/UHF MIC MAGNETIC
5511	VT965560	BRACKET 90 DEGREE TWO HOLE
5512	AM9771TX4500S	RADIO UHF 477 MHZ 80 CHANNEL
5801	72VO	REWIRE TRAILER LIGHT CIRCUIT TO 24V
5802	N	NOT REQUIRED - STANDARD FROM FACTORY
5803	STAR	*****
6101	72VO	RETENSION RETARDER HOSE CLAMPS
6102	72	RETENSION RETARDER HOSE CLAMPS LABOUR
6103	STAR	*****
6401	72VO	REPLACE CONVEX SIDE MIRRORS WITH FLAT
6402	72	REPLACE CONVEX SIDE MIRRORS WITH FLAT LABOUR
6403	STAR	*****
6404	N	TYPE MIRROR GLASS
6405	VT82359314	GLASS MIRROR FLAT MAIN LH FH VER 4
6406	VT82359320	GLASS MIRROR FLAT MAIN RH FH VER 4
6701	73VOMTRUCKWASH	CARRY OUT VOLVO NEW TRUCK MAJOR (3.5 HRS) WASH AND DETAIL
6702	73NWD	NEW TRUCK MAJOR WASH AND DETAIL LABOUR
6703	STAR	*****
7001	02VO	FIT MISSING BATTERY BOX STEP ASSEMBLY
7002	STAR	*****
7003	VT21891309	LADDER BATTERY BOX FM(4)
7004	VT990861	BOLT FLANGED 10MM X 30MM LONG 8.8 GRADE

06/08/2021 **RD0006308**

103	VT1078316	VALVE SOLENOID 24VOLT CLOSED CH120726-
105	n	C: check for air leak when lifting trailer body.
106	n	c: Air leaking at bottom exhaust of solenoid valve.

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
107	n	c: checked and located air leak,
108	n	R/ R solenoid valve and reconnect air lines check operation
109	n	Op code: 56300 @ 0.3 (r/r tipper solenoid valve)
110	n	OP code: 56000 @ 0.2 (air leak check)
111	n	defect: 21
112	n	causal: 1078316
113	n	job ref:8193193-1
401	02CAMP	CAMPAIGN CHECK
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BY NICK.A
405	N	DATE 06/08/2021
406	N	*****

10/08/2021 **RE0026977**

101	01VO1ST	1ST WARRANTY SERVICE VOLVO (AWAITING VOSP TO BE SET UP)
102	01	1ST WARRANTY SERVICE VOLVO (AWAITING VOSP TO BE SET UP)
103	N	Job ref: 8192717
104	STAR	*****
401	01VO	17527-3 FINAL DRIVE OIL CHANGE - MINERAL VCM
402	01	1ST WARRANTY SERVICE VOLVO (AWAITING VOSP TO BE SET UP)
403	85121715c	85W140 205L PUMPOU
404	N	Delayed entry awaiting contract set up
405	n	job ref: 8194418
701	01VO	17523-3 GEARBOX OIL & FILTER REPLACE LUBE AREA(MINERAL VCM)
702	01	17523-3 GEARBOX OIL & FILTER REPLACE LUBE AREA(MINERAL VCM)
703	VT20779040	FILTER GEARBOX I-SHIFT AT2512C AT2612D
704	85121714c	SAE50 TRANS OIL 205 PUMP OUT
705	n	Delayed entry awaiting contract set up
706	n	job ref: 8194418
1001	02CAMP	CAMPAIGN CHECK
1002	N	*****
1003	N	NO CAMPAIGNS OUTSTANDING
1004	N	CHECKED BY: NICK.M
1005	N	DATE: 09/08/2021
1006	N	*****
1301	COVIDSAN	SANITISE TRUCK
1302	STAR	*****
1303	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
1304	N	THE START & COMPLETION OF WORKS

23/09/2021 **RE0028272**

101	01VOBSCA	CARRY OUT BASIC SERVICE CARTAGE VEHICLE (NO VOSP).
102	01	CARRY OUT BASIC SERVICE CARTAGE VEHICLE (NO VOSP).
103	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
104	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
105	VDS4	VGA CAL85121795 ENGINE OIL
106	N	17744-2 Basic service
107	N	23306-3 Fuel filter, replace (one)
108	N	17513-2 Engine, oil and filter, replace. Lube area
109	N	23311-3 Filter, water separator, replace
110	N	Job ref: 8196365
111	STAR	*****
112	34OTSBRT3VCM	Carry Out Brake Roller Test 3 Axle
113	N	Copy of report to be included with
114	N	invoice and any issues to be detailed
115	STAR	*****
116	STAR	*****
401	02CAMP	CAMPAIGN CHECK
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BY: NICK.M

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
405	N	DATE: 22/09/2021
406	N	*****
701	COVIDSAN	SANITISE TRUCK
702	STAR	*****
703	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
704	N	THE START & COMPLETION OF WORKS
1001	01VO	replace outer air filter
1002	01	SERVICE LABOUR
1003	VT21337557	FILTER AIR OUTER FM VER-4-B8R BUS
1004	N	C: replace outer air filter
1005	N	C: blocked
1006	N	C: replaced outer air filter
1007	N	Op code 25627
1008	N	Defect 31
1009	n	Job ref: 8196365
1301	01VO	-Replace R/H head light globe
1302	01	SERVICE LABOUR
1303	VT990037	GLOBE H7 24V-70W FL-FE-FM-FH
1304	N	C: Headlight not working
1305	N	C: Blown bulb
1306	N	C: Removed and replaced RH headlight bulb
1307	N	Op code: 35104 @ 0.1
1308	N	Defect: 41
1309	n	Job ref: 8196365
19/10/2021 RE0028920		
101	11VO	INSPECT AND RECTIFY ENGINE LIGHT ON DASH
102	11	INSPECT AND RECTIFY ENGINE LIGHT ON DASH
103	STAR	*****
104	N	VEHICLE HAD NO ENGINE LIGHT ON DASH WAS ALREADY RECTIFIED
18/10/2021 RE0028929		
101	11VO	ENGINE LIGHT ON
102	11	ENGINE LIGHT ON
103	STAR	*****
104	n	C-Inspect and rectify engine light on dash
105	n	C-Ambient temp & piston cooling fault P055B64: Piston Cooling Oil
106	n	Pressure Sensor Range/Performance, Signal Plausibility
107	n	FailureC-Performed accessories kit programing. 17054-3
108	n	Op code: 36574 @ 1.3 (EECU,HMIOM,TECU)
109	n	Op code: 17054 @ 0.1 (Accessory Kit)
110	n	Op code: 17010 @ 0.2 (VCADS Connection)
111	n	Op code: 17012 @ 0.2 (Check Codes)
112	n	Defect: 49
113	n	Casual Part No: 21485928
114	n	Job Ref: 8197884
115	n	auth 200462392
17/11/2021 RE0029716		
101	11VO	RECTIFY ENGINE LIGHT - DERATE IN 36HRS ON DASH
102	11	RECTIFY ENGINE LIGHT - DERATE IN 36HRS ON DASH
103	VT22827993	SENSOR NOX EXHAUST SCR EURO5-6 OUTLET
104	STAR	*****
105	N	C: Engine light on - derating in 36 hrs on dash
106	N	C: P2BAE00: NOx Exceedence - NOx Control Monitoring System
107	N	C: Carried out test to confirm,
108	N	R/r nox sersor
109	N	Op/code: 25837 @ 0.4
110	N	Op code: 17037 @ 0.2
111	N	Op/code 17010 @ 0.2
112	N	Op/code 17012 @ 0.2
113	N	Defect: 41

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
114	N	Causal: 22827993
115	N	Job ref: 8200259
1001	11VO	VIP - RECTIFY ENGINE LIGHT ON DASH
1002	11	VIP - RECTIFY ENGINE LIGHT ON DASH
1003	VT20912514	KIT SENSOR AMBIENT TEMPERATURE FH-M 3-4
1004	STAR	*****
1005	n	C: Engine light on dash
1006	n	C: P007164: Ambient Air Temperature Sensor Range/Performance, Signal
1007	n	Plausibility Failure
1008	n	C: Carried out sensor test,
1009	n	R&r ambient temp sensor & tested ok
1010	n	Op code: 38681 @ 0.2
1011	n	Op code: 17037 @ 0.2
1012	n	Op code: 17010 @ 0.2
1013	n	Op code: 17012 @ 0.2
1014	n	Defect: 41
1015	n	Causal: 20912514
1016	n	Job ref: 8200259
08/01/2022 RE0031017		
101	17VO	DRIVER COMPLAINT COOLANT LEAK,
102	17	DRIVER COMPLAINT COOLANT LEAK,
103	N	C: Check coolant leak underneath
104	N	C: Loss of tension retarder hose clamps, leaking
105	N	C: Carried out pressure test for cooling system, Tightened retarder
106	N	pipe clamps & checked over ok
107	N	Op code: 59000 @ 0.4 (tighten retarder pipe clamps)
108	N	Op code: 26006 @ 0.4
109	N	Defect : 24
110	N	Causal P/no. 995680
111	N	Job ref: 8203095
112	STAR	*****
15/02/2022 RE0031990		
101	01VOBSVCM	FM CLASSIC & FM4 D13C BASIC SERVICE VCM
102	01	LABOUR
103	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
104	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
105	AMP23068346C	VOLVO ENGINE OIL VDS4
106	N	17744-2 Basic service
107	N	23306-3 Fuel filter, replace (one)
108	N	17513-2 Engine, oil and filter, replace. Lube area
109	N	23311-3 Filter, water separator, replace
110	STAR	*****
111	34OTSBRT3VCM	51090 - Carry Out Brake Roller Test 3 Axle
112	N	Copy of report to be included with
113	N	invoice and any issues to be detailed
114	STAR	*****
401	01VO	17846-2 Trailer coupling, safety and function check
402	01	17846-2 Trailer coupling, safety and function check
403	N	GREASE AND INSPECT TRAILER COUPLING.
404	N	CAUSAL 20424368
405	n	claim - 8206105-2
701	01VO	17063-3 6 Month ECU Download & Oil sample
702	01	17063-3 6 Month ECU Download & Oil sample
703	VT23448457	KIT OIL TEST SAMPLE SINGLE UNITS
704	N	CLAIM - 8206108- 1
705	STAR	*****
1001	01VO	87208-3 Air conditioning air filter, replace
1002	01	87208-3 Air conditioning air filter, replace
1003	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
1004	N	CLAIM -8206105-3

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
1301	01VO	56166-3 Air drier cassett, replace
1302	01	56166-3 Replace , Air drier cassett
1303	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
1304	N	CLAIM - 8206105 - 4
1601	01VO	21413-2 ADJUST, Valves and unit injectors
1602	01	21413-2 ADJUST, Valves and unit injectors
1603	N	Causal 21921757
1604	n	auth 200464999
1605	N	Job ref: 8206108
1606	STAR	*****
1901	01VO	17528-3 Retarder, oil change. Lube area
1902	01	17528-3 Retarder, oil change. Lube area
1903	85136278C	RETARDER OIL
1904	VT21157755	PLUG RETARDER
1905	VT21156871	PLUG BRAKE RETARDER
1906	VT21157139	PLUG RETARDER HYDRAULIC 123488-
1907	N	CLAIM - 8206105-5
2201	02CAMP	CAMPAIGN CHECK
2202	N	*****
2203	N	NO CAMPAIGNS OUTSTANDING
2204	N	CHECKED BYAMEE.....
2205	N	DATE ..14../..02../..22..
2206	N	*****
2501	COVIDSAN	SANITISE TRUCK
2502	STAR	*****
2503	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
2504	N	THE START & COMPLETION OF WORKS
2801	12VO	REPLACE WIPER BLADES
2802	12	LABOUR
2803	VT84035947	WIPER BLADE ASSEMBLY FM-FH
2804	STAR	*****
2805	N	C: REPLACE WIPER BLADES
2806	N	C: WORN
2807	N	C: REPLACED WIPER BLADES AS REQUIRED
2808	N	OP/CODE: 36304 @ 0.1 X 2
2809	N	DEFECT: 61
2810	N	CAUSAL: 84035947
2811	N	JOB REF: 8206105-6

06/06/2022 RE0034889

101	Z17746	17746-2 Annual Service
102	01	17746-2 Annual Service
103	amp23068346c	VOLVO ENGINE OIL VDS4
104	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
105	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
106	gr	GREASE
107	STAR	*****
108	N	17746-2 Annual Service (Do not claim, is wty)
109	n	23306-3 Fuel filter replace (one)
110	n	17513-2 Engine, oil & filter, replace
111	n	23311-3 Fuel, water seperator, replace
112	n	17589-2 Lubrication of trailer hitch
113	n	Job Ref : 823150
114	STAR	*****
115	340TSBRT3VCM	Carry Out Brake Roller Test 3 Axle
116	N	Copy of report to be included with
117	N	invoice and any issues to be detailed
118	STAR	*****
401	11VO	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
402	11	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
403	VT21337557	FILTER AIR OUTER FM VER-4-B8R BUS

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
404	n	Job Ref : 823150
405	STAR	*****
701	Z17528	Z17528-3 Retarder, oil change, lube area
702	01	17528-3 Retarder, oil change. Lube area
703	85136278C	RETARDER OIL
704	VT21157139	PLUG RETARDER HYDRAULIC 123488-
705	VT21156871	PLUG BRAKE RETARDER
706	VT21157755	PLUG RETARDER
707	n	Job Ref : 823150
1001	11VO	56166-3 Air drier cassett, replace
1002	11	56166-3 Air drier cassett, replace
1003	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
1004	N	Job Ref : 823150
1005	STAR	*****
1301	Z87208	87208-3 Air conditioning Air filter ,replace
1302	01	87208-3 Air conditioning Air filter ,rep
1303	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
1304	n	Job Ref : 823150
1601	Z17064	17064-3 12 Month ECU Download & Oil Sample
1602	01	17064-3 12 Month ECU Download & Oil Samp
1603	VT23448457	KIT OIL TEST SAMPLE SINGLE UNITS
1604	n	Job Ref: 8213527
1901	11VO	81003-2 12 Month Cab inspection
1902	11	81003-2 12 Month Cab inspection
1903	N	Job Ref: 8213527
1904	STAR	*****
2201	74VO	CARRY OUT NHVR INSPECTION ON VEHICLE AS REQUIRED
2202	74	CARRY OUT NHVR INSPECTION ON VEHICLE AS REQUIRED
2203	STAR	*****
2801	02CAMP	NO CAMPAIGNS OUTSTANDING
2802	N	*****
2803	N	NO CAMPAIGNS OUTSTANDING
2804	N	CHECKED BY MICHAEL
2805	N	DATE 06/06/22
2806	N	*****
3101	COVIDSAN	SANITISE TRUCK
3102	STAR	*****
3103	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
3104	N	THE START & COMPLETION OF WORKS
3401	01VO	RECTIFY WORN WIPER BLADES
3402	01	LABOUR
3403	VT84035947	WIPER BLADE ASSEMBLY FM-FH
3404	STAR	*****
3405	N	C: RECTIFY WORN WIPER BLADES
3406	N	C: WORN
3407	N	C: REPLACED WIPER BLADES AS REQUIRED
3408	N	OP CODE: 36304 @ 0.2 (0.1 X 2) REPLACE WIPER BLADES
3409	N	DEFECT: 61
3410	N	CAUSAL: 84035947
3411	N	JOB REF: 8213150
3701	01VO	17846-2 Trailer coupling, safety and function check
3702	01	17846-2 Trailer coupling, safety and function check
3703	n	causal 20424368
3704	N	Job Ref : 823150
4001	01VO	17746-2 Annual Service
4002	01	SERVICE LABOUR
4003	N	Job Ref: 8213527

15/09/2022 **RE0037807**

101	17VO	CHECK OVER VEHICLE FOR LEAKING RETARDER PIPES.
102	N	SHEPPARTON ATTEND BREAKDOWN YESTERDAY FOR LEAK COOLANT. FOUND

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
103	N	RETARDER CLAMPS LEAKING. CLAMPS WERENT REPLACED AS HAD NONE ONBOARD
104	N	TO REPLACE
105	17	LABOUR
106	VT23653293	RADIATOR TRANSCOOLER BEHIND GRILLE FM(4)
107	VT984993	HOSE CLAMP 12-22MM
108	STAR	*****
109	N	C: Coolant leak check
110	N	C: Leaking/crack in transmission radiator
111	N	C: Pressure system & confirmed leak,
112	N	R&r transmission radiator & check leaks ok.
113	N	Op code: 49116 @ 1.7
114	N	OP code: 26006 @ 0.4
115	N	Defect: 82
116	N	Causal: 22630453
117	N	Job ref: 8219354
20/09/2022 RE0037863		
101	Z17744	Carry out "BASIC SERVICE" Cartage truck
102	01	SERVICE LABOUR
103	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
104	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
105	AMP23068346C	VOLVO ENGINE OIL VDS4.5
106	N	17744-2 Basic service
107	N	23306-3 Fuel filter, replace (one)
108	N	17513-2 Engine, oil and filter, replace. Lube area
109	N	23311-3 Filter, water separator, replace
110	N	51090 Brake roller test x3
111	n	Job Ref: 8219496-1
112	star	*****
113	n	Carry Out Brake Roller Test 3 Axle
114	n	Copy of report to be included with
115	n	invoice and any issues to be detailed
116	star	*****
401	11VO	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
402	11	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
403	N	c- check air filter still clean
404	STAR	*****
701	Z17528	Z17528-3 Retarder, oil change, lube area
702	01	17528-3 Retarder, oil change. Lube area
703	85136278C	RETARDER OIL
704	VT21157755	PLUG RETARDER
705	VT21157139	PLUG RETARDER HYDRAULIC 123488-
706	VT21156871	PLUG BRAKE RETARDER
707	n	Job Ref: 8219496-2
1001	11VO	56166-3 Air drier cassett, replace
1002	11	56166-3 Air drier cassett, replace
1003	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
1004	N	CLAIM - 8219496-3
1005	STAR	*****
1301	Z25822	25822-2 Filter, AdBlue, replace
1302	01	25822-2 Filter, AdBlue, replace
1303	VT23381562	FILTER ADBLUE PUMP UNIT FH-M VER-4
1304	n	Job Ref: 8219496-4
1602	Z87208	87208-3 Air conditioning Air filter ,replace
1603	01	87208-3 Air conditioning Air filter ,rep
1604	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
1605	n	Job Ref: 8219496-5
1901	11VO	17846-2 Trailer coupling, safety and function check
1902	11	17846-2 Trailer coupling, safety and function check
1903	N	CLAIM - 8219496-6
1904	STAR	*****

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
2201	340TSBRT3	replace wiper blades
2202	34	replace wiper blades
2203	VT84035947	WIPER BLADE ASSEMBLY FM-FH
2204	n	C: Replace wiper blades
2205	n	C: Worn
2206	n	C: Replaced wiper blades & tested operation ok
2207	n	OP CODE: 36304 @ 0.1 X2
2208	n	DEFECT: 61
2209	n	job ref: 8219496-7
2210	STAR	*****
2501	02CAMP	NO CAMPAIGNS OUTSTANDING
2502	N	*****
2503	N	NO CAMPAIGNS OUTSTANDING
2504	N	CHECKED BY MICHAEL
2505	N	DATE 19/09/22
2506	N	*****
2801	COVIDSAN	SANITISE TRUCK
2802	STAR	*****
2803	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
2804	N	THE START & COMPLETION OF WORKS
3101	34VO	REPLACE BRAKE PADS ON STEER & REAR DRIVE AXLE TO LOW
3102	34	REPLACE BRAKE PADS ON STEER & REAR DRIVE AXLE TO LOW
3103	STAR	*****
3104	VT23149532	KIT BRAKE PAD FH-M D128250-FE(3)-MACK DISC NB
3105	N	C: REPLACE BRAKE PADS ON STEER & REAR DRIVE AXLE
3106	N	C: LOW
3107	N	C: REPLACED BRAKE PADS ON STEER & REAR DRIVE AXLE
3108	N	OP CODE 51106
3109	N	OP CODE 51207
3110	N	DEFECT 61
3111	N	JOB REF: 8219496-8

11/10/2022 RE0038531

101	61VO	REPAIR BEACON ON VEHICLE NOT WORKING - ONSITE REPAIRS
102	61	LABOUR
103	AMNARV85064A	LED LIGHT BOX NARVA
104	C	CONSUMABLES;CLEANING;EPA
105	STAR	*****
106	N	C: Repair beacon light on roof of vehicle not working
107	N	C: Failed LED light unit
108	N	C: Replaced faulty beacon light on roof with a new one & tested ok.

23/11/2022 RE0039802

101	11VO	REPAIR ENGINE LIGHT UP ON DASH - ONSITE REPAIR
102	11	REPAIR ENGINE LIGHT UP ON DASH - ONSITE REPAIR
103	n	C: Repair engine light up on dash - Onsite repairs
104	n	C: Ambient air ghost code P007164
105	n	C: Connect tech tool. Found ambient air fault. Checked for updates
106	n	- 1 x updates due
107	n	EMS, Cleared DTC's. Engine light went out.
108	n	Op/code: 17010 @ 0.2
109	n	OP code: 17012 @ 0.2
110	n	Defect: 49
111	n	Causal: 23141251
112	n	Job ref: 8224112
113	STAR	*****

02/12/2022 RE0040098

101	61VO	REPAIR PARK BRAKE LEVER IN VEHICLE - ONSITE REPAIR
102	61	LABOUR
103	VT23126245	SWITCH PARK BRAKE FM FH VER-4
104	STAR	*****

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
105	N	C: PARK BRAKE LEVER BROKEN
106	N	C: MATERIAL CRACK
107	N	C: REPLACE PARK BRAKE LEVER
108	N	OP CODE: 56324 @ 1.0 PARKING BRAKE HAND CONTROL, REPLACE
109	N	DEFECT: 82
110	N	CAUSAL: 23126245
111	N	JOB REF: 8225336-1
19/12/2022 RE0040574		
101	11VO	REPAIR WINDSCREEN WASHER BOTTLE LEAKING ON VEHICLE - PTS PRICE VAR
102	11	LABOUR
103	VT84468335	LEVEL SENSOR WASHER WIPER BOTTLE VER4
104	STAR	*****
105	N	C: Windscreen washer bottle leaking
106	N	C: Windscreen washer bottle sensor leaking
107	N	C: R/r Windscreen washer bottle sensor
108	n	Op code: 38691 @ 0.3
109	n	Defect: 24
110	n	Causal: 84468335
111	n	Job ref: 8226296-1
06/01/2023 RE0040958		
101	Z17744	17744-2 Basic service
102	01	17744-2 Basic service
103	amp23068346c	VOLVO ENGINE OIL VDS4.5
104	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
105	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
106	GR	GREASE
107	STAR	*****
108	N	17744-2 Basic service
109	n	17513-2 Engine, oil & filte, replace.lub
110	n	23306-3 Fuel filter, replace (one)
111	n	23311-3 Filter, water seperator, replace
112	n	17589-2 Lubrication of trailer hitch
113	n	Job Ref: 8226775-1
114	star	*****
115	n	Carry Out Brake Roller Test 3 Axle
116	n	Copy of report to be included with
117	n	invoice and any issues to be detailed
118	star	*****
401	11VO	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
402	11	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
403	VT21693755	FILTER AIR INNER & OUTER KIT FM V4
404	N	25627-3 Filter insert, air cleaner, replace. Only valid for primary f
405	N	25625-3 Secondary air filter, replace. Air filter insert removed
406	N	JOB REF: 8226775-2
407	STAR	*****
1001	Z17523	17523-3 Gearbox oil and filter, replace. Lube area
1002	01	17523-3 Gearbox oil and filter, replace
1003	85121714c	SAE50 TRANS OIL 205 PUMP OUT
1004	VT20779040	FILTER GEARBOX I-SHIFT AT2512C AT2612D
1005	n	Job Ref: 8226775-3
1301	Z17527	17527-3 Final drive oil, change
1302	01	17527-3 Final drive oil, change
1303	85121715c	85W140 205L PUMPOU
1304	n	Job Ref: 8226775-4
1601	Z17528	Z17528-3 Retarder, oil change, lube area
1602	01	17528-3 Retarder, oil change. Lube area
1603	85136278C	RETARDER OIL
1604	VT21156871	PLUG BRAKE RETARDER
1605	VT21157139	PLUG RETARDER HYDRAULIC 123488-
1606	n	Job Ref: 8226775-5

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
1901	Z21413	21413-2 Valves and unit injectors, adjust
1902	01	21413-2 Valves and unit injectors, adjus
1903	n	Casual: 21921757
1904	n	Job Ref: 8226775-6
2201	11VO	56166-3 Air drier cassett, replace
2202	11	56166-3 Air drier cassett, replace
2203	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
2204	N	JOB REF: 8226775-7
2205	STAR	*****
2501	Z87208	87208-3 Air conditioning Air filter ,replace
2502	01	87208-3 Air conditioning Air filter ,rep
2503	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
2504	n	Job Ref: 8226775-8
2801	11VO	17846-2 Trailer coupling, safety and function check
2802	11	17846-2 Trailer coupling, safety and function check
2803	N	CAUSAL: 20824368
2804	N	JOB REF: 8226775-9
2805	STAR	*****
3101	Z17065	17065-3 18 Month ECU download and Oil sample
3102	01	17065-3 18 Month Download and Oil Sample
3103	VT23448457	KIT OIL TEST SAMPLE SINGLE UNITS
3104	n	Job Ref: 8226782-1
3401	74VO	INSPECT AND REPLACE CABIN FIRE EXTINGUISHER IF OUT OF DATE
3402	74	**NOT REQUIRED**
3403	STAR	*****
4601	34VO	REPLACE WORN BRAKE PADS ON 1ST DRIVE
4602	34	REPLACE BRAKE PADS ON 1ST DRIVE TO LOW
4603	VT23149532	KIT BRAKE PAD FH-M D128250-FE(3)-MACK DISC NB
4604	STAR	*****
4605	N	C: RECTIFY WORN BRAKE PADS DRIVE AXLE
4606	N	C: BRAKE PADS WORN
4607	N	C: REPLACE DRIVE AXLE BRAKE PADS.
4608	N	OP CODE: 51207 @ 1.8 BRAKE PADS, REPLACE
4609	N	OP CODE: 17010 @ 0.2 VCADS CONNECT
4610	N	OP CODE: 50006 @ 0.2 BRAKE PADS, TEST
4611	N	DEFECT: 61
4612	N	CAUSAL: 23149532
4613	N	JOB REF: 8226775-10
4901	01VO	REPLACE WIPER BLADE WORN
4902	01	LABOUR
4903	VT84035947	WIPER BLADE ASSEMBLY FM-FH
4904	STAR	*****
4905	N	C: RECTIFY WORN WIPER BLADES
4906	N	C: WORN
4907	N	C: REPLACED WIPER BLADES AS REQUIRED
4908	N	OP CODE: 36304 @ 0.2 (0.1 X 2) REPLACE WIPER BLADES
4909	N	DEFECT: 61
4910	N	CAUSAL: 84035947
4911	N	JOB REF: 8226775-11
5201	01VO	REPLACE LEAKING OIL SUMP PLUG
5202	01	SERVICE LABOUR
5203	VT20571854	PLUG SUMP MAGNETIC D12-3-16-MP8-10
5204	STAR	*****
5205	N	C: REPLACE LEAKING ENGINE OIL SUMP PLUG
5206	N	C: WORN THREADS
5207	N	C: REMOVED SUMP PLUG AND IDENTIFIED WORN THREADS ON PLUG,
5208	N	-REPLACED PLUG AND VERIFIED NO LEAKS.
5209	N	OP CODE: 21700 @ 0.2 REPLACE LEAKING SUMP PLUG
5210	N	DEFECT: 23
5211	N	CAUSAL: 20571854

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
5212	N	JOB REF: 8226775-12
5501	24VO	REPLACE LEAKING GEARBOX FILL PLUG
5502	24L	LABOUR
5503	VT20366642	PLUG GEARBOX VT SERIES BRASS HEX
5504	STAR	*****
5505	N	C: RECTIFY GEARBOX FILL PLUG OIL LEAK
5506	N	C: WORN THREADS ON FILLER PLUG
5507	N	C: WASHED LOCALISED AREA AND INSPECTED LEAK. IDENTIFIED WORN THREADS
5508	N	ON FILLER PLUG.
5509	N	-REPLACED FILLER PLUG. VERIFIED REPAIR.
5510	N	OP CODE: 43000 @ 0.1 GEARBOX FILLER PLUG, REPLACE
5511	N	DEFECT: 23
5512	N	CAUSAL: 20366642
5513	N	JOB REF:8226775-13
14/02/2023 RE0041963		
101	34VO	REPAIR AIR LEAKS FROM VEHICLE - ONSITE REPAIR
102	34	Labour
103	VT991970	RAUFOSS NIPPLE PLASTIC 6MMX1.0MM SMALL
104	VT992248	RAUFOSS ELBOW 45DEG NIPPLE PLASTIC SMALL
105	N	C: Check air leaks
106	N	C: Leaking fittings
107	N	C: Checked air leaks
108	N	found loose air compressor governor fittings.
109	N	removed and fitted new air compressor governor fittings.
110	N	Op/code: 56000 @ 0.1 x 2 (replace leaking air fittings on air
111	N	compressor)
112	N	Op/code: 56001 @ 0.5
113	N	Defect: 21
114	N	Causal p/no. 991970
115	N	Job ref: 8229298-1
116	STAR	*****
01/03/2023 RE0042373		
101	11VO	REPAIR LOW ENGINE OIL IN VEHICLE - ONSITE REPAIR
102	11	REPAIR LOW ENGINE OIL IN VEHICLE - ONSITE REPAIR
103	STAR	*****
104	VTAMP23068343	OIL ENGINE VDS-4.5 VOLVO 15W-40 5LTR CONTAINER
105	n	C: REPAIR LOW ENGINE OIL IN VEHICLE
106	n	C: LEVEL LOW
107	n	C: CHECKED OIL LERAKS AND TOP-UP 5L ENGINE OIL, CHECKED LEVEL ALL OK
108	n	op code 17586 .3 top up engine oil
109	n	defect 05
110	n	job ref: 8230999
15/03/2023 RE0042829		
101	33VO	FIT JACK KNIFE SENSOR
102	33	LABOUR
103	n	C – Fit supplied jack knife sensor
104	n	C – Updated type
105	n	C – Fitted supplied sensor and bracket as required
106	STAR	*****
107	VT990949	NUT FLANGED 6MM LOCKING 8 GRADE
108	VT984731	BOLT FLANGED 6MM X 60MM LONG 8.8 GRADE
30/03/2023 RE0043273		
101	61VO	REPAIR LHS HEADLIGHT NOT WORKNG - ONSITE REPAIR
102	61	REPAIR LHS HEADLIGHT NOT WORKNG - ONSITE REPAIR
103	VT990037	GLOBE H7 24V-70W FL-FE-FM-FH
104	N	C: Check & repair left head light n/w
105	N	C: Blown head light globe
106	N	C: R&R left head light globe & tested ok
107	N	Op/code: 35104 @ 0.1

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
108	N	Defect: 44
109	N	Causal: 990037
110	N	Job ref: 8232431
111	STAR	*****
401	61VO	REPAIR BEACON LIGHT NOT WORKING - Fleet # 266
402	61	LABOUR
403	AMNARV85064A	LED LIGHT BOX NARVA
404	N	C: REPAIR BEACON LIGHT NOT WORKING - ONSITE REPAIR
405	N	C: NOT WORKING
406	N	C: REMOVED ALL WIRING AND TESTED ALL OK
407	N	TESTED POWER AND ALL OTHER OK
408	N	FITTED NEW BEACON LIGHT AND TESTED ALL OK
409	STAR	*****

19/04/2023 RE0043709

101	Z17746	17746-2 Annual Service
102	01	SERVICE LABOUR
103	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
104	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
105	AMP23068346C	VOLVO ENGINE OIL VDS4.5
106	GR	GREASE
107	n	(Do not claim is wty)
108	n	23306-3 Fuel filter replace (one)
109	n	17513-2 Engine, oil & filter, replace
110	n	23311-3 Fuel, water seperator, replace
111	N	51090-2 brake roller test @ 0.2 x 3
112	n	Job ref: 8233452-1
113	star	*****
401	Z32123	32123-3 Alternator drive belt, replace
402	01	32123-3 Alternator drive belt, replace
403	VT22275091	BELT ALTERNATOR-A/C FH-M D13
404	n	Job Ref: 8233452-2
701	Z26307	26307-3 Drive Belt Fan, Replace
702	01	26307-3 Drive Belt Fan, Replace
703	VT20484545	V-RIBBED BELT FAN 16 LIT
704	n	Job Ref: 8233452-4
1001	Z17528	Z17528-3 Retarder, oil change, lube area
1002	01	17528-3 Retarder, oil change. Lube area
1003	85136278C	RETARDER OIL
1004	VT21157139	PLUG RETARDER HYDRAULIC 123488-
1005	VT21156871	PLUG BRAKE RETARDER
1006	VT21157755	PLUG RETARDER
1007	n	Job Ref: 8233452-5
1301	11VO	23414-3 Filter for fuel tank ventilation, replace
1302	11	23414-3 Filter for fuel tank ventilation, replace
1303	VT21743197	FILTER SENDER FUEL TANK BREATHER FH-M V4 B7R
1304	N	Job ref:8233452-6
1305	STAR	*****
1901	01	32130-2 Belt tensioner, Alternator , Rep
1902	VT21819687	BELT TENSIONER ALTERNATOR & FAN FH-M V4 D11-13
1903	Z32130	32130-2 Belt tensioner, Alternator , Replace
1904	n	Job Ref: 8233452-7
2201	Z87208	87208-3 Air conditioning Air filter ,replace
2202	01	87208-3 Air conditioning Air filter ,rep
2204	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
2205	n	Job Ref: 8233452-8
2501	Z26308	26308-3 Fan belt, tensioer, replace
2502	01	26308-3 Fan belt, tensioer, replace
2503	VT22674901	BELT TENSIONER
2504	VT22696301	PULLEY IDLER FAN BELT FM-FH D13A-C
2505	n	Job Ref: 8233452-9

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
2801	11VO	17846-2 Trailer coupling, safety and function check
2802	11	17846-2 Trailer coupling, safety and function check
2803	N	Causal P/no. 20424368
2804	N	Job ref: 8233452-10
2805	STAR	*****
3101	74VO	INSPECT AND REPLACE CABIN FIRE EXTINGUISHER IF OUT OF DATE
3102	74	INSPECT AND REPLACE CABIN FIRE EXTINGUISHER IF OUT OF DATE
3103	VT22556828	FIRE EXTINGUISHER 2.3KG & BRACKET FIRX925A
3104	STAR	*****
3701	02CAMP	NO CAMPAIGNS OUTSTANDING
3702	N	*****
3703	N	NO CAMPAIGNS OUTSTANDING
3704	N	CHECKED BY MICHAEL
3705	N	DATE 16/04/23
3706	N	*****
4001	COVIDSAN	SANITISE TRUCK
4002	STAR	*****
4003	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
4004	N	THE START & COMPLETION OF WORKS
4301	74VO	CARRY OUT NHVR INSPECTION ON VEHICLE AS REQUIRED
4302	74	CARRY OUT NHVR INSPECTION ON VEHICLE AS REQUIRED
4303	STAR	*****
4601	01VO	REPLACE WIPER BLADES WORN
4602	01	REPLACE WIPER BLADES WORN
4603	VT84035947	WIPER BLADE ASSEMBLY FM-FH
4604	N	C: Replace wiper blades noted during service
4605	N	C: Worn
4606	N	C: Replaced wiper blades as required
4607	N	Op/code: 36304 @ 0.1 X 2
4608	N	Defect: 61
4609	N	Causal: 84035947
4610	N	Job ref: 8233452-11
4901	01VO	Replace Air filter outer blocked
4902	01	Replace Air filter outer blocked
4903	VT21337557	FILTER AIR OUTER FM VER-4-B8R BUS
4904	N	C: Replace outer air filter noted during service
4905	N	C: Blocked
4906	N	C: R&R outer air filter
4907	N	Op/code: 25627 @ 0.1
4908	N	Defect: 31
4909	N	Causal P/no. 21337557
4910	N	Job ref: 8233452-12
5201	01VO	17746-2 Annual Service
5202	01	SERVICE LABOUR
5203	n	causal 24122024
5204	n	defect 05
5205	n	job ref: 8233457-1

10/05/2023 **RE0044444**

101	18VO	EXHAUST MANIFOLD GASKETS LEAKING
102	18	EXHAUST MANIFOLD GASKETS LEAKING
103	VT20855371	GASKET EXHAUST MANIFOLD D13A-C-MP8
104	VT20784537	GASKET TURBO BASE SQUARE METAL
105	VT22206133	GASKET TURBO FEED&FILTER HOUSING D12A-C
106	VT420643	GASKET TURBO RETURN MACK-VOLVO
108	VT993811	BOLT FLANGED 10MM X 50MM LONG 8.8 GRADE
109	VT20573472	SLEEVE SPACER TURBO BASE MOUNTING 13&16LTR ENGINES
110	VT21433769	MANIFOLD SEALING RING METAL D9-11-13 MP8
111	VT20938963	KIT EXHAUST MANIFOLD SEAL D13
113	STAR	*****
114	N	C: EXHAUST MANIFOLD LEAKING

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
115	N	C: WORN GASKETS
116	N	C: R&R MANIFOLD & ASSOCIATED GASKETS & TESTED OK
117	N	OP CODE: 25104 @ 1.6 GASKETS, EXHAUST MANIFOLD, REPLACE
118	N	OP CODE: 25006 @ 0.2 INLET AND EXHAUST SYSTEMS, CHECK
119	N	OP CODE: 18204 @ 0.5 WASH OF ENGINE
120	N	DEFECT: 21
121	N	CAUSAL: 20855371
122	N	JOB REF: 8234295-1
401	11VO	NON CLAIMABLE CONS
402	VTWUR0890200	WURTH ROST OFF " PLUS "
403	VTWUR0673205010	BUFF PAD 2" COARSE NYLON POWER LOC

26/05/2023 **RE0044934**

101	17VO	REPAIR COOLANT LEAK
102	17	LABOUR
103	VTAMP24078863	COOLANT VCS-2 PREMIX VOLVO 5LTR CONTAINER
104	N	Top up coolant
105	N	Op/code: 17586 @ 0.3
106	N	Defect : 05
107	N	Causal P/no. 24118108
108	N	Job ref: 8235409-1
109	STAR	*****

26/05/2023 **RE0044966**

101	11VO	CHECK AND RECTIFY GEARBOX OIL LEAK
102	11	CHECK AND RECTIFY GEARBOX OIL LEAK
103	STAR	*****
401	11VO	CHECK AND RECTIFY LOSS OF COOLANT
402	11	CHECK AND RECTIFY LOSS OF COOLANT
403	VT995680	CLAMP HOSE 56-74MM
404	N	C: Check coolant leak underneath
405	N	C: Loss of tension retarder hose clamps, leaking
406	N	C: Carried out pressure test for cooling system, replaced retarder
407	N	pipe clamps & checked over ok
408	N	Op code: 59000 @ 0.4 (replace retarder pipe clamps)
409	N	Op code: 26006 @ 0.4
410	N	Defect : 24
411	N	Causal P/no. 995680
412	N	Job ref: 8235239-1
413	STAR	*****
701	11VO	CHECK AND RRECTIFY SEAT BELT ISSUES
702	11	CHECK AND RRECTIFY SEAT BELT ISSUES
703	STAR	*****

29/05/2023 **RE0044983**

101	11VO	INTERNAL DRIVER DOOR LEVER COVERS CRACKED AND SPLIT
102	11	LABOUR
103	VT84569441	KNOB DOOR LATCH RH FM VER-4
104	VT84569439	PLUG RH DOOR LATCH FM4
105	STAR	*****
106	N	C: INTERNAL DRIVER SIDE DOOR LEVER COVERS CRACKED
107	N	C: LEVER COVERS WORN, NO LONGER STAYING INTACT
108	N	C: INSPECTED AND FOUND DRIVER DOOR LEVER COVERS CRACKED.
109	N	-FITTED DOOR LEVER COVERS/KNOBS.
110	N	-ALSO TIGHTENED LOOSE DOOR LOCK MOUNT FASTENERS.
111	N	OP CODE: 83400 @ 0.1 REPLACE INTERNAL DRIVER DOOR LEVER COVERS/KNOB.
112	N	DEFECT: 53
113	N	CAUSAL: 84569441
114	N	JOB REF: 8235582-1
401	51VO	DRIVER SEAT BELT NOT WORKING
402	51	LABOUR
403	VT84161777	SEAT BELT KIT RHS FH VER4 FM

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
404	STAR	*****
405	N	C: SEAT BELT NOT RETRACTING/RETURNING
406	N	C: REEL MECHANISM FAULTY, SEIZED
407	N	C: REPLACED SEAT BELT.
408	N	OP CODE: 88408 @ 0.8 SEAT BELT, REPLACE (ONE)
409	N	DEFECT: 32
410	N	CAUSAL: 84161777
411	N	JOB REF: 8235582-2
701	51VO	DRIVER SEAT COVER TORN/WORN @ 50% P/L
702	n	50% parts and labour cost toward CMV goodwill.
703	STAR	*****
704	51	BODY TRIM LABOUR
705	VT21873207	UPHOLSTERY SEAT BASE RH VER4
706	N	REMOVED AND REPLACED TORN DRIVER SEAT TRIM UPHOLSTERY.
1001	51VO	DRIVER SEAT CUSHION COLLAPSED
1002	51	BODY TRIM LABOUR
1003	VT21432027	SEAT CUSHION RH FH(4) FM
1004	STAR	*****
1005	N	C: RECTIFY SEAT CUSHION COLLAPSED
1006	N	C: RH SEAT CUSHION COLLAPSED
1007	N	C: REPLACE SEAT CUSHION
1008	N	OP CODE: 85251 @ 0.3 DRIVER SEAT CUSHION, REPLACE
1009	N	DEFECT: 34
1010	N	CAUSAL: 21432027
1011	N	JOB REF:
1301	51VO	DRIVER SEAT COVER TORN @ 50% P/L NEW TRUCK GW
1302	51	BODY TRIM LABOUR
1303	VT21873207	UPHOLSTERY SEAT BASE RH VER4
1304	STAR	*****
1305	N	AS PER AGREEMENT WITH CBS
09/06/2023 RE0045346		
101	17VO	DRIVER COMPLAINT COOLANT LEAK,
102	17	DRIVER COMPLAINT COOLANT LEAK, REF- RE0047499
103	STAR	*****
401	11VO	DRIVER COMPLAINT OIL SMELL, - RE0047499
402	11	DRIVER COMPLAINT OIL SMELL,
403	STAR	*****
404	VT944126	O RING SUMP & INJECTOR LOOM FM-FH
405	VT983472	CABLE TIES GREY INJECTOR LOOM D12-13 X70MR
13/06/2023 RE0045389		
101	51VO	REPAIR SEAT BELT WARNING LIGHT ON - PARTS WARRANTY
102	51	REPAIR SEAT BELT WARNING LIGHT ON
103	VT84161777	SEAT BELT KIT RHS FH VER4 FM
104	STAR	*****
105	N	REF: RE0044983, 9/5/23 @ 4388 KMS TRAVELLED
106	STAR	*****
107	N	C: SEAT BELT NOT RETRACTING/RETURNING RHF
108	N	C: REEL MECHANISM FAULTY, SEIZED
109	N	C: REPLACED SEAT BELT.
110	N	OP CODE: 88408 @ 0.8 SEAT BELT, REPLACE (ONE)
111	N	DEFECT: 32
112	N	CAUSAL: 84161777
113	N	JOB REF: 8236812-1
07/07/2023 RE0046208		
101	34VO	RECTIFY APM FAULT ON DASH
102	34	BRAKES LABOUR
103	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
104	STAR	*****
105	N	C: CONSUMED AIR DRYER CARTRIDGE

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
106	N	C: APM CARTRIDGE CONSUMED
107	N	C: REPLACE AND CALIBRATE APM CARTRIDGE
108	N	OP CODE: 56166 @ 0.4 AIR DRYER, DRYER INSERT, REPLACE
109	N	OP CODE: 56021 @ 0.3 APM, STATUS
110	N	OP CODE: 17010 @ 0.2 CONNECT-DISCONNECT DIAGNOSTIC TOOL
111	N	OP CODE: 56198 @ 0.2 AIR DRYER, CALIBRATION
112	N	DEFECT: 21
113	N	CAUSAL: 23690622
114	N	JOB REF: 8238313

31/07/2023 **RE0046911**

101	11VO	REPAIR AIR LEAK AT 1ST AXLE
102	11	REPAIR AIR LEAK AT 1ST AXLE
103	STAR	*****
104	N	C: RECTIFY AIR LEAK AT 1ST DRIVE AXLE
105	N	C: DIFF LOCK COVER FASTENERS LOOSE
106	N	C: INSPECTED DIFF LOCK HOUSING, ACTIVATED DIFF LOCK AND IDENTIFIED
107	N	LOOSE FASTENERS AT DIFF LOCK COVER.
108	N	-TIGHTENED FASTENERS AND CHECKED FOR AIR PRESSURE DROP. VERIFIED
109	N	REPAIR
110	N	OP CODE: 46800 @ 0.2 INSPECTED DIFF LOCK HOUSING, ACTIVATED DIFF LOCK
111	N	AND IDENTIFIED LOOSE FASTENERS AT DIFF LOCK COVER. TIGHTENED
112	N	FASTENERS
113	N	OP CODE: 56001 @ 0.5 PRESSURE DROP IN COMPRESSED AIR SYSTEM, CHECK
114	N	DEFECT: 21
115	N	CAUSAL: 984726
116	N	JOB REF: 8239962-1

01/08/2023 **RE0046965**

101	11VO	REPAIR WIPER WASHER N/W
102	11	REPAIR WIPER WASHER N/W
103	N	C: Repair wiper washer N/W
104	N	C: Wiper washer hose blocked
105	N	C: Checked and tested wiper washers not working
106	N	checked water level, tested power and wiring
107	N	removed all wiper washer hose and cleaned with air pressure
108	N	found wiper washer hose blocked
109	N	fitted all back to truck and tested all working
110	N	Op/code: 36300 @ 0.2 (clean out washer hoses)
111	N	Op/code: 36385 @ 0.2
112	N	Op/code: 37102 @ 0.4
113	N	Defect: 24
114	N	Causal p/no. 82171137
115	N	Job ref: 8239752-1
116	STAR	*****

10/08/2023 **RE0047214**

101	Z17744	17744-2 Basic Service
102	01	Basic Service
103	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
104	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
105	AMP23068346C	VOLVO ENGINE OIL VDS4.5
106	N	17744-2 Basic service
107	N	23306-3 Fuel filter, replace (one)
108	N	17513-2 Engine, oil and filter, replace. Lube area
109	N	23311-3 Filter, water separator, replace
110	N	51090 brake roller test x3
111	N	job ref: 8239092
112	340TSBRT3	Carry Out Brake Roller Test 3 Axle
113	star	*****
401	Z32204	32204-3 Charging regulator, replace
402	01	32204-3 Charging regulator, replace

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
403	VT21579977	REGULATOR ALTERNATOR FM-H V4
404	n	Job Ref: 8239092
701	Z17523	17523-3 Gearbox oil and filter, replace.
702	01	17523-3 Gearbox oil and filter, replace
703	VT24074626	FILTER GEARBOX I-SHIFT AT2512C AT2612D
704	85121714c	SAE50 TRANS OIL 205 PUMP OUT
705	n	Job Ref: 8239092
1001	Z17527	17527-3 Final drive oil, change
1002	01	17527-3 Final drive oil, change
1003	85121715c	85W140 205L PUMPOU
1004	n	Job Ref: 8239092
1301	Z17528	17528-3 Retarder, oil change, lube area
1302	01	17528-3 Retarder, oil change. Lube area
1303	85136278C	RETARDER OIL
1304	VT21157139	PLUG RETARDER HYDRAULIC 123488-
1305	VT21157755	PLUG RETARDER
1306	VT21156871	PLUG BRAKE RETARDER
1307	n	Job Ref: 8239092-4
1308	PK01VT229	RETARDER OIL PLUG KIT CARTAGE
1601	11VO	56166-3 Air drier cassett, replace
1602	STAR	*****
1901	Z17846	17846-2 Trailer coupling, safety and function check
1902	01	Trailer coupling, safety and fun
1903	n	causal 20424368
1904	n	job ref: 82390902
2201	74OT	CARRY OUT NHVR INSPECTION ON VEHICLE AS REQUIRED
2202	STAR	*****
2501	74OT	INSPECT AND REPLACE CABIN FIRE EXTINGUISHER IF OUT OF DATE
2502	STAR	*****
2801	12VO	CHECK JACKKNIFE SENSOR FUNCTION
2802	STAR	*****

18/08/2023 RE0047499

101	11VO	RECTIFY OIL LEAK AT INJECTOR LOOM PASS THROUGH
102	11	RECTIFY OIL LEAK AT INJECTOR LOOM PASS THROUGH
103	VT944126	O RING SUMP & INJECTOR LOOM FM-FH
104	VT983472	CABLE TIES GREY INJECTOR LOOM D12-13 X70MR
105	STAR	*****
106	N	C: RECTIFY OIL LEAK AT INJECTOR LOOM PASS THROUGH
107	N	C: LEAKING INJECTOR LOOM 'O' RING
108	N	C: REPLACED LEAKING INJECTOR LOOM 'O' RING.
109	N	OP CODE: 28600 @ 0.3 REPLACE INJECTOR PASS-THROUGH O-RING
110	N	OP CODE: 21153 @ 0.2 VALVE COVER REMOVE
111	N	OP CODE: 21154 @ 0.4 VALVE COVER INSTALL
112	N	OP CODE: 18202 @ 0.3 LOCALISED WASH FOR FAULT TRACING
113	N	DEFECT: 23
114	N	CAUSAL: 944126
115	N	JOB REF: 8241114-1
401	17VO	DRIVER COMPLAINT COOLANT LEAK,
402	17	ENGINE COOLING LABOUR
403	VT20840154	CLAMP HOSE 60-80MM
404	STAR	*****
405	N	C: COOLANT LEAK, LOW COOLANT
406	N	C: LOSS OF TENSION RETARDER HOSE CLAMPS.
407	N	C: WASHED AREA FOR INSPECTION. CARRIED OUT PRESSURE TEST FOR COOLING
408	N	SYSTEM, IDENTIFIED LEAK AT RETARDER HOSE CLAMPS. INSPECTED CLAMPS AND
409	N	FOUND NO LONGER HOLDING TENSION. DRAINED COOLANT. REMOVED HOSE AND
410	N	REPLACED CLAMPS. REFILLED WITH COOLANT, WASHED DOWN & CHECKED OVER
411	N	OK.
412	N	OP CODE: 59200 @ 0.2 REPLACE CLAMPS
413	N	OP CODE: 26006 @ 0.4 COOLING SYSTEM PRESSURE TEST

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
414	N	OP CODE: 26027 @ 0.2 COOLANT, DRAINING
415	N	OP CODE: 26028 @ 0.6 COOLANT, FILLING
416	N	OP CODE: 18202 @ 0.3 WASH & INSPECT
417	N	DEFECT: 24
418	N	CAUSAL: 20840154
419	N	JOB REF: 8241114-2
30/08/2023 RE0047848		
101	17VO	DRIVER COMPLAINT COOLANT LEAK,
102	17	Labour
103	VT85023583	EXC WATER PUMP FH-M D9A D13A FH16 D16C
104	VTAMP24078863	COOLANT VCS-2 PREMIX VOLVO 5LTR CONTAINER
105	VT21103569	SEALING RING WATER PUMP D9-11-13-16 FH-M MP8-10 MACK
106	N	C: Check coolant leak
107	N	C: Leaking water pump
108	N	C:Pressure tested the cooling system and then found that the water
109	N	pump leaking, replaced water pump then tested
110	N	Op/code: 26202 @ 1.3
111	N	Op/code: 26006 @ 0.4
112	N	Op/code: 18202 @ 0.3
113	N	Defect: 24
114	N	Causal P/no. 22902404
115	N	Job ref: 8242569-1
116	STAR	*****
12/09/2023 RE0048205		
101	32VO	DRIVER COMPLAINT OIL LEAK UNDER TRUCK,
102	32L	DRIVER COMPLAINT OIL LEAK UNDER TRUCK,
103	VT23478738	PIPE POWER STEERING PUMP SERVO FH-M V4 D206740-ON WARDS
104	VT1161995	OIL TRANSMISSION AUTO TQ-D II 4LTR
105	STAR	*****
106	N	C: POWER STEERING LEAK/NOISY, PUMP SUPPLY PIPE
107	N	C: STEERING PIPE LEAKING
108	N	C: WASHED FOR INSPECTION. IDENTIFIED LEAK AT PUMP SUPPLY PIPE.
109	N	REPLACED PIPE, HOSE AND FITTING. PURGED SYSTEM AND VERFIED FUNCTION.
110	N	OP CODE: 64552 @ 1.1 POWER STEERING PIPE, REPLACE
111	N	OP CODE: 64500 @ 0.1 DRAIN STEERING FLUID FROM SYSTEM
112	N	OP CODE: 64534 @ 0.6 HYDRAULIC OIL, FILLING. INCLUDING BLEEDING THE
113	N	SYSTEM.
114	N	OP CODE: 18202 @ 0.3 LOCALISED WASH FOR FAULT TRACING
115	N	DEFECT: 23
116	N	CAUSAL: 23478738
117	N	JOB REF: 8243703-1
401	17VO	DRIVER COMPLAINT COOLANT LEAK,
402	17	DRIVER COMPLAINT COOLANT LEAK,
403	VT20840154	CLAMP HOSE 60-80MM
404	STAR	*****
405	N	C: LOW COOLANT FAULT ON DASH
406	N	C: LOSS OF TENSION RETARDER HOSE CLAMPS, LEAKING
407	N	C: CARRIED OUT PRESSURE TEST FOR COOLING SYSTEM, IDENTIFIED LEAK AT
408	N	RETARDER HOSE CLAMPS. REMOVED AIR CLEANER HOUSING TO GAIN ACCESS.
409	N	TIGHTENED RETARDER PIPE CLAMPS AND PRESSURE TESTED. WASHED DOWN &
410	N	VERIFIED REPAIR.
411	N	OP CODE: 59200 @ 0.3 (TIGHTEN RETARDER PIPE CLAMPS, REPLACE 2 X
412	N	CLAMP)
413	N	OP CODE: 26006 @ 0.4 COOLING SYSTEM PRESSURE TEST
414	N	OP CODE: 26012 @ 0.8 COOLING SYSTEM, DRAIN AND REFILL
415	N	OP CODE: 18202 @ 0.3 WASH & INSPECT
416	N	OP CODE: 25630 @ 0.1 AIR FILTER HOUSING, REMOVE
417	N	OP CODE: 25631 @ 0.2 AIR FILTER HOUSING, INSTALL
418	N	DEFECT: 24
419	N	CAUSAL: 995680

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
420	N	JOB REF: 8243703-2
23/09/2023 RE0048623		
101	12VO	DRIVER COMPLAINT ENGINE FAN STAYING ON,
102	12	Labour
103	VT984945	CABLE TERMINAL
104	VT20734499	SEAL CABLE TERMINAL BLUE
105	N	C:Driver complaint fan stuck on,
106	N	C:Engine thermo fan wiring connector pin corroded
107	N	C:Remove the failed pins and then clean out the fan loom plug and
108	N	the housing, supply and fit new pins and then reconnect, all okay.
109	N	Op/code: 37001 @ 0.1
110	N	Op/code: 37102 @ 0.4
111	N	Defect: 43
112	N	Causal p/no. 984945
113	N	Job ref: 8244257-1
114	STAR	*****
04/10/2023 RE0048886		
101	18VO	ENGINE BRAKE NOT WORKING
102	18	ENGINE BRAKE NOT WORKING
103	STAR	*****
104	N	C: EXHAUST BRAKE NOT WORKING
105	N	C: EPG ACTUATOR HOSE ADRIFT
106	N	C: INSPECTED AND IDENTIFIED AIR LEAKING FROM
107	N	EPG ACTUATOR LINE. CHECKED AND FOUND CONNECTION ADRIFT.
108	N	-REMOVED, CLEANED, INSPECTED AND REFIT EPG LINE TO CYLINDER.
109	N	OP CODE: 25585 @ 0.4 ACTUATOR BY-PASS VALVE, TEST.
110	N	OP CODE: 19020 @ 0.3 ROAD TESTED
111	N	DEFECT:21
112	N	CAUSAL: 23532368
113	N	JOB REF: 8244621-1
26/10/2023 RE0049078		
101	11VO	AIR LEAK BEHIND TRUCK
102	11	AIR LEAK BEHIND TRUCK
103	STAR	*****
401	61VO	DAMAGE TO INTERIOR SWITCHS
402	61	Labour
403	VT23194828	GEAR SELECTOR I-SHIFT DASH MOUNTED
404	VT22372592	SWITCH STEERING WHEEL FH-M V4
405	VT22629276	SWITCH STEERING WHEEL VOLUME CONTROL FH4 FM
406	VT22281821	SWITCH DASH FH-M VER4 TIPPER BODY
407	VT22585191	SWITCH
408	VT22996866	SWITCH
409	VT21211203	SWITCH DASH FH-M VER4 PTO GEARBOX
410	VT21211195	SWITCH DASH FH-M VER4 BACK UP ALARM
411	VT21211191	SWITCH HILL STAR AID
412	VT21211214	SWITCH DASH FH-M VER4 BEACON LIGHT
413	VT21211226	SWITCH DASH FH-M VER4 LANE KEEPING
414	VT21211227	SWITCH LANE-KEEPING VER.4
415	VT21211228	SWITCH DASH COLLISION WARNING FM-H-4
416	VT21211229	SWITCH
417	VT22026373	MODULE SWITCH FLEXIBLE BOX VER4
418	VT22281822	SWITCH TIPPER DASH FH-FM-4
419	VT21850858	SWITCH DASH FH-M VER4 TAILGATE LOCK
420	VT22328334	CAP SWITCH FHFM (4) TRUCK TILT
421	VT21727618	SWITCH ROCKER DASH FH 4 ON-OFF AUXILIARY HARDWIRED
422	VT84193673	PLATE FRAME DASH SWITCHES
423	N	C: Dashboard switches surface worn off
424	N	C: Switch emblem worn off
425	N	C: Removed whole dashboard and switch panel

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
426	N	Replaced flex switches one at a time
427	N	Connected tech tool and check codes and cleared codes
428	N	Calibrated all flex switches
429	N	Tested all switches and refitted dashboard
430	N	Op/code: 43208 @ 0.8
431	N	Op/code: 36495 @ 0.5
432	N	Op/code: 36412 @ 0.2 x 8
433	N	Op/code: 36012 @ 0.3 x 9
434	N	Op/code: 36018 @ 0.3
435	N	Op/code: 17010 @ 0.2
436	N	Defect: 61
437	N	Causal P/no. 23194828
438	N	Job ref: 8247862-1
439	STAR	*****
30/10/2023 RE0049563		
101	01MIS	JOB CARD RAISED BY MISTAKE
102	STAR	*****
13/11/2023 RE0049954		
101	66VO	BLUETOOTH NOT WORKING
102	N	Cant claim vcm or wrty
103	STAR	*****
104	66	BLUETOOTH NOT WORKING
105	N	C: BLUETOOTH NOT WORKING
106	N	C: RESET
107	N	C: CHECKED AND TESTED TOO MANY DEVICES CONNECTED
108	N	REMOVED ALL AND RESET
109	N	TESTED ALL WORKING
24/11/2023 RE0050331		
101	51VO	OVER HEAD STORAGE LOCK ADRIFT - Customer charge
102	51	LABOUR
103	VT21647001	GLOVEBOX COMPARTMENT LHS FM V4
104	c	CONSUMABLES;CLEANING;EPA
105	STAR	*****
106	n	C: Overhead storage lock adrift -
107	n	C: Driver broken
108	n	C: Removed all internal panels and replaced overhead storage box.
401	11VO	ENGINE OIL LEVEL LOW
402	11	ENGINE OIL LEVEL LOW
403	AMP23068346C	VOLVO ENGINE OIL VDS4.5
404	n	C: ENGINE OIL LEVEL LOW
405	n	C: ENGINE OIL LEVEL LOW
406	n	C: Topped up oil
407	n	op code 17586 0.3 topped up oil
408	n	defect 05
409	n	job ref: 8247286-1
410	STAR	*****
04/12/2023 RE0050593		
101	11VO	OIL LEAK UNDER TRUCK - ENGINE OIL LEVEL LOW
102	11	Labour
103	AMP23068346C	VOLVO ENGINE OIL VDS4.5
104	n	ENGINE OIL LEVEL LOW
105	n	ENGINE OIL LEVEL LOW
106	N	Top up engine oil
107	N	Op/code: 17586 @ 0.3
108	N	Defect : 05
109	N	Causal P/no. 24118108
110	N	Job ref: 8249195-1
111	STAR	*****
11/12/2023 RE0050777		

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
101	Z17744	17744-2 Basic Service
102	01	Basic Service
103	STAR	*****
104	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
105	AMP23068346C	VOLVO ENGINE OIL VDS4.5
106	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
107	n	17744-2 Basic service
108	n	23306-3 Fuel filter, replace (one)
109	n	17513-2 Engine, oil and filter, replace. Lube area
110	n	23311-3 Filter, water separator, replace
111	n	51090 brake roller test x3
112	n	Job Ref: 8249462-1
401	Z17528	17528-3 Retarder, oil change, lube area
402	01	17528-3 Retarder, oil change. Lube area
403	85136278C	RETARDER OIL
404	VT21157139	PLUG RETARDER HYDRAULIC 123488-
405	VT21157755	PLUG RETARDER
406	VT21156871	PLUG BRAKE RETARDER
407	n	Job Ref: 8249462-2
701	Z56166	56166-3 Air drier cassette, replace
702	01	56166-3 Air drier cassette, replace
703	VT23690622	FILTER APM CARTRIDGE TYPE FH-M VER 4
704	n	Job Ref: 8249462-3
1001	Z17067	17067-3 30 Month ECU Download & Oil Sample
1002	01	17067-3 30 Month ECU Download & Oil Samp
1003	VT23448457	KIT OIL TEST SAMPLE SINGLE UNITS
1004	n	Job Ref: 8249462-4
1301	74OT	CARRY OUT NHVR INSPECTION ON VEHICLE AS REQUIRED
1302	STAR	*****
1601	74VO	CHECK JACKKNIFE SENSOR FUNCTION
1602	STAR	*****
1901	74VO	INSPECT & REPLACE CABIN FIRE EXTINGUISHER IF OUT OF DATE.
1902	STAR	*****
2201	Z25627	25627-3 Filter insert, air cleaner, replace. Only valid for primary fi
2202	01	25627- 3 Filter insert, air cleaner, rep
2203	VT21337557	FILTER AIR OUTER FM VER-4-B8R BUS
2204	N	Job Ref: 8249462-5
2501	Z21413	21413-2 Valves and unit injectors, adjust
2502	01	21413-2 Valves and unit injectors, adjus
2503	n	Casual: 21921757
2504	n	Job Ref: 8249462-6
2801	Z25822	25822-2 Filter, AdBlue, replace
2802	01	25822-2 Filter, AdBlue, replace
2803	VT23381562	FILTER ADBLUE PUMP UNIT FH-M VER-4
2804	n	Job Ref: 8249462-7
3101	Z25518	25518-2 Engine turbocharger, replace
3102	01	25518-2 Engine turbocharger, replace
3103	VT85020372	EXC TURBO HD D13A480-EU4 D13C380-540 EU5-6 SCR
3104	n	old serial W2009249367
3105	n	new serial W2205177883
3106	VT469601	O RING TURBO RETURN LINE MACK-VOLVO
3107	VT21940615	SEALING RING TURBO RETURN PIPE D12A-C-D13-MP8
3109	VT993811	BOLT FLANGED 10MM X 50MM LONG 8.8 GRADE
3110	VT20573472	SLEEVE SPACER TURBO BASE MOUNTING 13&16LTR ENGINES
3111	VT20784537	GASKET TURBO BASE SQUARE METAL
3112	VT22206133	GASKET TURBO FEED&FILTER HOUSING D12A-C
3113	VT20707685	GASKET OIL RETURN D11C-D9 LATE V2-D16E-D8K
3114	n	causal 20763166
3115	n	job ref: 8249462-8
3401	Z56111	56111-2 Compressor, replace

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
3402	01	56111-2 Compressor, replace
3403	VT85013941	EXC AIR COMPRESSOR FH-M D13-D16
3404	VT992247	RAUFOSS FITTING BRASS SWIVEL M16X1.5
3405	VT992065	O RING COMPRESSOR MOUNTING V3-4-MP8
3406	VT471708	O RING OIL COOLER AND COMPRESSOR HEAD
3407	n	old serial no 4420
3408	n	new serial no 3023
3409	n	causal 22040497
3410	n	job ref:8249462-9
3701	12VO	ADAPTIVE CRUISE N /W
3702	12	Labour
3703	SPACX3064	TERMINAL JOINER RED STD & HEAT SHRINKABL
3704	SPACX3065	TERMINAL JOINER BLUE STD & HEAT SHRINK
3705	SPACX0817L	WIRE 7 CORE 4MM CABLE SOLD PER METRE
3706	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
3707	AMNARV56713	CONDUIT TUBING SPLIT 13MM X 10 METRE
3708	VTWUR0893090030	WURTH SUPERGLUE HANDLE
3709	STAR	*****
3710	n	C: Adaptive cruise n /w
3711	n	C: damaged 7core wire - pic's attached
3712	n	C: Inspected Abs 1 codes on trailer and reverse light wont work,
3713	n	Checked and tested found abs 1 codes in system,
3714	n	Checked codes with trailer diagnostic computer,
3715	n	Found lost power trailer diagnostic power 24v,
3716	n	Checked plug and all wiring,
3717	n	Found 2 x damaged place,
3718	n	Repaired / fitted new modifications type & tested all ok.

21/12/2023 **RE0051136**

101	12VO	ENGINE ELECTRICAL VOLVO
102	12	LABOUR
103	c	CONSUMABLES;CLEANING;EPA
104	STAR	*****
105	n	C: DACU codes on dash
106	n	C: FLS mount bracket bent (impact damage effect)
107	n	C: Removed front grill and all steps,
108	n	Was able repair by re-bend the bracket, no replacement req,
109	n	Calibrated sensor and road tested ok.

05/01/2024 **RE0051413**

101	17VO	DRIVER COMPLAINT COOLANT LEAK,
102	17	DRIVER COMPLAINT COOLANT LEAK,
103	VT20840154	CLAMP HOSE 60-80MM
104	STAR	*****
105	N	C:Driver complaint coolant leak,
106	N	C:Failed retarder clamps,
107	N	C:Checked over the truck and found that the coolant level was low,
108	N	pressure
109	N	tested the cooling system and found that the lower retarder clamps
110	N	had failed.
111	N	Drain coolant and then remove and fit new clamps, tension clamps to
112	N	spec and
113	N	then refill and bleed coolant. Take truck to the wash bay and then
114	N	clean down
115	N	all okay, park up truck all okay.
116	N	Op/code: 59000 @ 0.3 (R&R RETARDER CLAMPS)
117	N	Op/code: 26012 @ 0.8
118	N	Op/code: 18202 @ 0.3
119	N	Defect: 21
120	N	Causal: 20840154
121	N	Job ref: 8249606-1

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
08/01/2024 RE0051470		
101	18VO	ENGINE DERATE,
102	18	DRIVER COMPLAINT ENGINE DERATE,
103	VT24444704	PIPE SET EPG FH-M VER-4
104	VT23532368	VALVE SOLENOID EPG D9-D11-13-16 GH11
105	VT992065	O RING COMPRESSOR MOUNTING V3-4-MP8
106	VT471708	O RING OIL COOLER AND COMPRESSOR HEAD
107	STAR	*****
108	N	C: LOW POWER/DERATED
109	N	C: RUPTURED EPG/WASTEGATE AIR PIPES
110	N	IDENTIFIED LEAK AT EPG PIPE. AIR PIPE RUBBED THROUGH.
111	N	C: CONNECTED VCADS AND CARRIED OUT EPG AND WASTEGATE TESTS.
112	N	IDENTIFIED AVU VALVE BYPASSING INTERNALLY TO EXHAUST PORT. ALSO FOUND
113	N	WASTEGATE AND EPG VALVE PIPES LEAKING.
114	N	-REPLACED EPG PIPE SET.
115	N	-REPLACED AVU SOLENOID
116	N	OP CODE: 25300 @ 0.5 REPLACE EPG/WASTEGATE PIPE SET
117	N	OP CODE: 25006 @ 0.2 INLET AND EXHAUST SYSTEMS, CHECK
118	N	OP CODE: 25062 @ 0.2 ACTUATOR, CHECK (WASTEGATE)
119	N	OP CODE: 25630 @ 0.1 AIR FILTER HOUSING REMOVE,
120	N	OP CODE: 26012 @ 0.8 COOLING SYSTEM DRAIN. REFILL
121	N	OP CODE: 56170 @ 0.7 COMPRESSOR REMOVE
122	N	OP CODE: 59214 @ 0.6 RETARDER PIPE REMOVE/REFIT, COOLANT DRAINED
123	N	OP CODE: 28420 @ 0.6 ENGINE ECU REMOVE/REFIT
124	N	OP CODE: 25631 @ 0.2 AIR FILTER HOUSING INSTALL
125	N	OP CODE: 56172 @ 0.7 COMPRESSOR INSTALL
126	N	DEFECT: 21
127	N	CAUSAL: 22142825
128	N	JOB REF: 8250520-1
401	18VO	EXHAUST LEAK,
402	18	DRIVER COMPLAINT EXHAUST LEAK,
403	VT20508112	EXHAUST MANIFOLD CENTRE-D13C-MP8-SCR
404	VT20855371	GASKET EXHAUST MANIFOLD D13A-C-MP8
405	VT20938963	KIT EXHAUST MANIFOLD SEAL D13
406	VT20784537	GASKET TURBO BASE SQUARE METAL
407	VT21433769	MANIFOLD SEALING RING METAL D9-11-13 MP8
408	VT22206133	GASKET TURBO FEED&FILTER HOUSING D12-13A-C
409	VT420643	GASKET TURBO RETURN MACK-VOLVO
410	VT469601	O RING TURBO RETURN LINE MACK-VOLVO
411	VT21940615	SEALING RING TURBO RETURN PIPE D12A-C-D13-MP8
412	STAR	*****
413	N	C: CRACKED EXHAUST MANIFOLD
414	N	C: MANIFOLD CRACKED
415	N	C: INSPECTED INTAKE AND EXHAUST SYSTEMS. FOUND EXHAUST LEAKS AT
416	N	MANIFOLD GASKETS AND CRACKED EXHAUST MANIFOLD. REPLACED CRACKED
417	N	EXHAUST MANIFOLD. ALSO FOUND MULTIPLE BOLTS SEIZED AND SOME BOLT
418	N	HOLES CROSS-THREADED. MULTIPLE BOLTS STRETCHED. REPLACED MANIFOLD
419	N	BOLTS AND RE-TAPPED/CLEANED BOLT HOLE THREADS. RE-SEALED NEW MANIFOLD
420	N	WITH NEW GASKETS AND ORINGS AS REQUIRED.
421	N	OP CODE: 25900 @ 1.0 ASSEMBLE NEW MANIFOLD WITH NEW SEALING RINGS.
422	N	EXTRACTED SEIZED BOLTS. TAPPED AND CLEANED BOLT HOLES.
423	N	OP CODE: 25104 @ 2.2 GASKETS, EXHAUST MANIFOLD, REPLACE
424	N	OP CODE: 25116 @ 0.3 GASKET KIT, REPLACE
425	N	OP CODE: 18204 @ 0.5 WASH OF ENGINE
426	N	OP CODE: 25006 @ 0.2 INLET AND EXHAUST SYSTEMS, CHECK
427	N	DEFECT: 21
428	N	CAUSAL: 20508112
429	N	JOB REF: 8250520-2
701	51VO	DRIVER COMPLAINT DOOR NOT HOLDING,
702	51	DRIVER COMPLAINT DOOR NOT HOLDING,

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
703	VT84167953	DOOR CHECK STRAP LH RH FH-M V4
704	STAR	*****
705	N	C: DRIVER DOOR NOT HOLDING OPEN
706	N	C: WORN DOOR STRAP
707	N	C: INSPECTED DOOR HARDWARE. IDENTIFIED DOOR STRAP BUSHING FAILED.
708	N	OP CODE: 83131 @ 0.2 REPLACED DOOR STRAP AND VERIFIED FUNCTION.
709	N	DEFECT: 61
710	N	CAUSAL: 84167953
711	N	JOB REF: 8250522-1
1001	11VO	ENGINE ECU ISOLATORS WORN
1002	11	ENGINE MECHANICAL LABOUR
1003	VT22008175	KIT RUBBERS ECU MOUNTING X4
1004	STAR	*****
1005	N	C: ENGINE ECU/EMS RATTTLING
1006	N	C: RUBBER MOUNTS/ISOLATORS PERISHED
1007	N	C: IDENTIFIED PERISHED MOUNT RUBBERS CAUSING RATTTLING.
1008	N	-REPLACED ENGINE ECU ISOLATOR RUBBERS.
1009	N	OP CODE: 28400 @ 0.4 REMOVED ENGINE ECU, REPLACED RUBBER MOUNTS AND
1010	N	REFITTED ECU.
1011	N	DEFECT: 61
1012	N	CAUSAL: 22008175
1013	N	JOB REF: 8250522-2
30/01/2024 RE0052099		
101	11VO	REDUCE PULLING POWER ON DASH
102	11	REDUCE PULLING POWER ON DASH
103	VT22827993	SENSOR NOX EXHAUST SCR EURO5-6 OUTLET
104	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
105	n	C: Reduced pulling power on dash
106	n	C: P220E93: NOx Sensor Heater Control Circuit Range/Performance (Bank
107	n	1 Sensor 1), No Operationc C: Investigated the fault using Tech Tool
108	n	and found fault code P220E93: NOx sensor heater control circuit
109	n	range/performance (bank 1 sensor 1), no operation. Tested wiring to
110	n	the sensor, which was all okay. Suspected a faulty NOx sensor.
111	n	Replaced the NOx sensor, cleared faults, and road tested the truck –
112	n	all okay.
113	n	Op code: 25837 @ 0.4
114	n	Op code: 17906 @ 0.5
115	n	Op code: 28407 @ 0.2
116	n	Op code: 17071 @ 0.2
117	n	Op code: 37102 @ 0.4
118	n	Defect code: 46
119	n	Causal part no: 22827993
120	n	Job ref: 8251792-1
121	STAR	*****
401	11VO	ENGINE LIGHT ON
402	11	ENGINE LIGHT ON
403	VT20920705	MUFFLER SCR FH540 EURO5 FM VER-4
404	n	C: Engine light on dash
405	n	C: P029900: Turbocharger/Supercharger Underboost
406	n	C: Connected the Tech Tool and identified active fault code P029900:
407	n	Turbocharger/Supercharger under boost. Conducted tests and observed a
408	n	back pressure reading of 60 kPa during the road test, suspecting a
409	n	blocked muffler. Replaced the muffler, cleared faults, and road
410	n	tested the truck. Confirmed that the vehicle is now receiving full
411	n	boost with no engine light on.
412	n	Op code: 25222 @ 1.9
413	n	Op code: 25846 @ 0.5
414	n	Op code: 19020 @ 0.3
415	n	Defect code: 31
416	n	Causal part no:20920705

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
417	n	Job ref: 8251691-1
418	n	Serial no – Old: 20029A60501085
419	n	Serial no – New: 23253A60501049
420	n	GRT#8224
421	STAR	*****
14/02/2024 RE0052582		
101	34VO	ENGINE BRAKES N /W
102	34	ENGINE BRAKES N /W - Rebook
103	STAR	*****
12/03/2024 RE0053472		
101	52VO	LH MIRROR IMPACT DAMAGED
102	52	LABOUR
103	VT82356824	GLASS MIRROR SPOTTER LH-RH FH V4-5 FM V4 FMX V4-5
104	N	C: Replace LH side mirror glass.
105	STAR	*****
401	63VO	HEAD LIGHT LH N /W
402	63	HEAD LIGHT LH N /W
403	VT990037	GLOBE H7 24V-70W FL-FE-FM-FH
404	N	C: Check & repair left head light n/w
405	N	C: Blown head light globe
406	N	C: R&R left head light globe & tested ok
407	N	Op/code: 35104 @ 0.1
408	N	Defect: 44
409	N	Causal: 990037
410	N	Job ref: 8253847-1
411	STAR	*****
27/03/2024 RE0053981		
101	52VO	Rectify driver's seat belt stuck and won't retract
102	52	INTERIOR SEAT LABOUR
103	VT84161777	SEAT BELT KIT RHS FH VER4 FM
104	N	C: Rectify driver's seat belt not retracting
105	N	C: Internal mechanical fault
106	N	C: Checked operation and driver's side seat belt not retracting.
107	N	Replaced seat belt, checked operation and fault rectified.
108	N	Op/code: 88408 @ 0.4
109	N	Defect : 32
110	N	Causal : 84161777
111	N	Job ref: 8254884-1
112	N	Old RO#: RE0044983 @ 316 984km, 31/05/23. Travelled 98 032km
401	02CAMP	NO CAMPAIGNS OUTSTANDING
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BY MICHAEL
405	N	DATE 2703/24
406	N	*****
407	N	ARE ALL LOOSE ITEMS SECURE INSIDE CABIN
408	N	DRIVER NAME
409	N	DATE / /
410	N	*****
16/04/2024 RE0054566		
101	34VO	DRIVER COMPLAINT LOUD AIR GUSHING NOISE INTERMITENTLY,
102	N	TRUCK TRADED IN
103	STAR	*****
104	34	DRIVER COMPLAINT LOUD AIR GUSHING NOISE INTERMITENTLY,
22/04/2024 RE0054791		
101	61VO	JACK KNIFE SENSOR N /W
102	61	LABOUR
103	SPACX3064	TERMINAL JOINER RED STD & HEAT SHRINKABL
104	C	CONSUMABLES;CLEANING;EPA

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
105	STAR	*****
106	n	C: Jack knife sensor n /w
107	n	C: Jack knife sensor 1 x wire joiner with water damaged
108	n	C: Removed and refitted all new joiners and tested
109	n	all power and ground ok, but sensor didn't not work,
110	n	Checked and replaced jack knife sensor,
111	n	Tested all working ok.
26/05/2024 RE0055808		
101	01	17746-2 Annual Service
102	VT24122024	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
103	AMP23068346C	VDS4.5 ENGINE OIL
104	Z17746	17746-2 Annual Service
105	VT85129545	FLUID WASHER WINDSCREEN 1LTR CONCENTRATE
106	STAR	*****
107	n	17746-2 Annual Service
108	n	23306-3 Fuel filter replace (one)
109	n	17513-2 Engine, oil & filter, replace
110	n	23311-3 Fuel, water seperator, replace
111	n	51090 brake roller test x3
112	n	Job ref: 8259122-1
113	star	*****
114	34OTSBRT3VCM	Carry Out Brake Roller Test 3 Axle
115	N	Copy of report to be included with
116	N	invoice and any issues to be detailed
117	STAR	*****
401	Z17528	17528-3 Retarder, oil change, lube area
402	01	17528-3 Retarder, oil change. Lube area
403	VT21157139	PLUG RETARDER HYDRAULIC 123488-
404	85136278C	RETARDER OIL
405	VT21157755	PLUG RETARDER
406	VT21156871	PLUG BRAKE RETARDER
407	n	Job Ref: 8259122-2
701	Z87208	87208-3 Air conditioning Air filter ,replace
702	01	87208-3 Air conditioning Air filter ,rep
703	VT21758906	FILTER CABIN FH-M V123 NH FM VER-4 ONLY
704	n	Job Ref: 8259122-3
1001	Z26375	26375-2 Fan belt idler pulley, replace
1002	01	26375-2 Fan belt idler pulley, replace
1003	VT22696301	PULLEY IDLER FAN BELT FM-FH D13A-C
1004	n	Job Ref: 8259122-4
1301	Z17915	17915-2 Cable terminals and connections, corrosion prevention
1302	01	17915-2 Cable terminals and connections
1303	N	CAUSAL: 9510226
1304	N	JOB REF: 8259122-5
1601	Z17846	17846-2 Trailer coupling, safety and function check
1602	01	Trailer coupling, safety and fun
1603	N	CAUSAL: 20424368
1604	N	JOB REF: 8259122-6
1901	Z17527M	17527-3 Final drive oil, change (Mineral Oil)
1902	01	17527-3 Final drive oil, change
1903	85121715C	85W140 205L PUMPOU
1904	n	Job Ref: 8259122-7
2201	Z17523M	17523-3 Gearbox oil and filter, replace. (Mineral Oil)
2202	01	17523-3 Gearbox oil and filter, replace
2203	VT24283117	FILTER GEARBOX I-SHIFT AT2512C AT2612D
2204	85121714C	SAE50 TRANS OIL 205 PUMP OUT
2205	n	Job Ref: 8259122-8
2501	ZKMS	NEXT SERVICE INTERVAL
2502	N	SERVICE INTERVALS KMS
2503	N	479900 km - 482000 km

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
2504	n	Next Service Date 30-Sep-2024 - 06-Oct-2024, BASIC
2801	02CAMP	CAMPAIGN CHECK
2802	N	*****
2803	N	NO CAMPAIGNS OUTSTANDING
2804	N	CHECKED BY EBONY
2805	N	DATE 22/5/24
2806	N	*****
2807	N	ARE ALL LOOSE ITEMS SECURE INSIDE CABIN
2808	N	DRIVER NAME
2809	N	DATE / /
2810	N	*****
3101	Z17068	17068-3 36 Month ECU Download & Oil Sample
3102	01	17068-3 36 Month ECU Download & Oil Samp
3103	VT23448457	KIT OIL TEST SAMPLE SINGLE UNITS
3104	n	Job Ref: 8259129-1
3401	74VO	CARRY OUT NHVR INSPECTION ON TRUCK AS REQUIRED
3402	STAR	*****
3701	74VO	INSPECT AND REPLACE CABIN FIRE EXTINGUISHER IF OUT OF DATE
3702	STAR	*****
4001	74VO	INSPECT AND REPORT ON ALL FRONT SUSPENSION SHACKLE PINS & BUSHES
4002	STAR	*****
4301	34VO	REAR DRIVE BRAKE PADS WORN
4302	34	REPLACE BRAKE PADS ON REAR DRIVE
4303	VT23149532	KIT BRAKE PAD FH-M D128250-FE(3)-MACK DISC NB
4304	STAR	*****
4305	N	C: DRIVE AXLE BRAKE PADS WORN
4306	N	C: BRAKE PADS WORN UNEVENLY
4307	N	C: REPLACE BRAKE PADS
4308	N	OP CODE: 51207 @ 1.6 BRAKE PADS, REPLACE (TWO DRIVEN WHEEL)
4309	N	OP CODE: 51012 @ 0.2 BRAKE ROLLER, TEST (3 AXLE).
4310	N	OP CODE: 50006 @ 0.2 BRAKE PADS, TEST
4311	N	DEFECT: 61
4312	N	CAUSAL: 23149532
4313	N	JOB REF: 8259122-9
23/05/2024 RE0055835		
101	34VO	EMERGENCY BRAKES N /W ON DASH
102	34	EMERGENCY BRAKES N /W ON DASH
103	STAR	*****
104	N	C: ABS1 FAULT ON DASH
105	N	C: BLOWN ABS POWER SUPPLY FUSE
106	N	C: INSPECTED WIRING AND CONNECTORS FOR ABS SYSTEM. CHECKED SIGNALS TO
107	N	CONNECTOR, FOUND NO POWER SUPPLY. TRACED BACK WIRING INTO CAB.
108	N	CHECKED FUSES AND RELAYS. IDENTIFIED BLOWN ABS FUSE.
109	N	-CHECKED FOR SHORT CIRCUIT IN LOOM. FOUND SHORT TO GROUND.
110	N	-REPAIRED WIRING, REPLACED FUSE AND VERIFIED POWER TO CONNECTOR.
111	N	-Cleared codes and verified repair on road est.
112	N	OP CODE: 17010 @ 0.2 VACDS CONNECT
113	N	OP CODE: 37102 @ 0.4 ELECTRIC WIRES AND CONNECTIONS, CHECK
114	N	OP CODE: 57000 @ 0.5 CHECK TRAILER BRAKE CONTROL CONNECTOR SIGNALS
115	N	OP CODE: 19020 @ 0.3 ROAD TEST
116	N	DEFECT: 41
117	N	CAUSAL: 22701778
118	N	JOB REF: 8259177
29/05/2024 RE0056061		
101	63VO	ROOFTOP R/H LIGHTS NOT WORKING
102	63	ROOFTOP R/H LIGHTS NOT WORKING
103	VT84208821	LAMP ROOF CLEARANCE LED CLEAR
104	STAR	*****
105	N	C: RECTIFY ROOF MARKER/CLEARANCE LIGHT N/W
106	N	C: FAULTY LED LIGHT

Repair Order History

Stock#: 212416 **Rego:** XV68UO **VIN:** YV5XG30D7MD212416
Model: #266 FMX500 **Body:** RIGID **Color:** Color

RO Date **RO#**

Line#	Product	Description
107	N	C: CHECKED WIRING AND CONNECTOR. VERIFIED SIGNALS TO LIGHT. TESTED
108	N	AND IDENTIFIED LAMP OPEN CIRCUIT.
109	N	-REPLACE LAMP AND VERIFIED FUNCTION.
110	N	OP CODE: 35504 @ 0.2 ROOF POSITION LIGHT, REPLACE
111	N	OP CODE: 37102 @ 0.4 ELECTRICAL WIRES AND CONNECTIONS CHECK
112	N	DEFECT: 43
113	N	CAUSAL: 84208821
114	N	JOB REF: 8259425-1