

## COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

### Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.11. Parking Brake & Emergency Application	✓						

**NOTES:**

REPLACED BOTH AXLE # 2 SLACKS & BRAKE POTS, REPLACED BOTH AXLE # 3 DRUMS

### Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control and Linkage	✓			4.4. Kingpin	✓		
4.2. Power Steering System (Hydraulic and Electric)	✓			4.5. Self-Steer and Controlled-Steer Axle			✓
4.3. Steering Operation (Active Steer Axle)	✓						

**NOTES:**

REPLACED AXLE # 1 RH DRAG LINK

### Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher	✓			5.8. Heater & Windshield Defroster	✓		
5.2. Hazard Warning Kit	✓			5.9. Fuel-Burning Auxiliary Heater			✓
5.3. Horn	✓			5.10. Chain/"Headache" Rack	✓		
5.5. Speedometer	✓			5.11. Auxiliary Controls and Devices	✓		
5.6. Odometer	✓			5.12. Auxiliary Drive Controls	✓		
5.7. Windshield Wiper/Washer	✓						

**NOTES:**

REPAIRED WASHER SYSTEM

### Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.4. Instrument Panel Lamps	✓		
6.2. Reflex Reflector	✓			6.5. Headlamp Aim	✓		
6.3. Retro-Reflective Marking	✓						

**NOTES:**

REPLACED LH HEADLAMPS, REPAIRED REAR LIGHTS, REPAIRED LICENSE PLATE LIGHT

### Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery	✓						

**NOTES:**

### Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.1. Hood or Engine Enclosure	✓			8.12. Bumper	✓		
8.2. Tilt Cab			✓	8.13. Windshield	✓		
8.3. Air-Suspended Cab			✓	8.14. Side Windows	✓		
8.4. Cab and Passenger-Vehicle Body	✓			8.15. Rear Window	✓		
8.5. Cargo Body	✓			8.16. Interior Sun Visor	✓		
8.6. Frame, Rails & Mounts	✓			8.17. Exterior Windshield Sun Visor	✓		
8.7. Unitized Body Elements	✓			8.18. Rear-View Mirror	✓		
8.8. Cab or Cargo Door	✓			8.19. Seat	✓		
8.9. Cargo Tank or Vessel			✓	8.20. Seat Belt/Occupant Restraint	✓		
8.10. Body, Device or Equipment Attached or Mounted to the	✓			8.21. Fender/Mud Flap	✓		



## COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

<b>Type of Vehicle</b> Truck										<b>Gross Vehicle Weight registered</b> 24500 kg									
<b>Vehicle Information</b>																			
VIN		2	F	Z	X	K	M	C	B	X	Y	A	B	3	4	0	6	4	
Unit Number 104			Year 2000			Make Sterling			Model Sterling			Odometer 399,374							
Registered Owner's Name HADNHILLS FARMING CO															Plate Number CCT6265				
Address RR 3										Postal Code T0J 1P0					Phone Number (403) 854-4323				

Drum Brakes:    A-Full Inspection with Drum Removed                      Disc Brakes:

		LEFT		FRONT		RIGHT			
100 psi 5 mm		420.36 mm	15 mm	Drums/Rotors	420.40 mm	16 mm	38 mm	100 psi 6 mm	
		420.60 mm	15 mm	Linings/Pads	420.90 mm	16 mm	40 mm	100 psi    100 psi 7 mm       2 mm	
		419.10 mm	13 mm	Drums/Rotors	419.10 mm	13 mm	40 mm	100 psi    100 psi 9 mm       13 mm	
				Linings/Pads				psi       psi mm       mm	
				Push Rod Travel				psi       psi mm       mm	
								psi       psi mm       mm	
								psi       psi mm       mm	
								psi       psi mm       mm	

Park Brake Lining    Left    NA    mm    Right    NA    mm    Trans    NA    mm  
 Wheel Torque Checked     Inner    NA    ft lbs    Outer    475    ft lbs



**Commercial Vehicle Inspection Certificate  
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE  
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	24500 kg	Brake Type:	Air
Owner Name:	HADNHILLS FARMING CO		
Address:	RR 3		
City:	HANNA	Province:	AB
		Postal Code:	T0J 1P0
Telephone Number:	(403) 854-4323		
Vehicle Identification Number:	2FZXKMCBXYAB34064		
Make:	Sterling	Model:	Sterling
Year:	2000	Unit Number:	104
Odometer:	399374 KM	Licence Plate Number:	CCT6265
		Province:	AB

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Glover International Trucks Ltd.	Facility Number:	13266
Inspection Technician Name:	Brady Bagley	Technician Number:	D1540
Inspection Technician Signature:			
Inspection Date:	2026/04/28		