



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340511

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

### Customer Details:

Name: Simplot Grower Solutions

Address: Highway 26 North-West, Meota, Saskatchewan, S0M 1X0

Inspection Completed Date: 22May2026

Inspection Expiry Date: 31May2027

### Vehicle Details:

VIN: 2AEABRBFXKR000140

Hubometer Reading:

Year: 1989

Vehicle Make/Model: ADVANCE TRAILER/TRAILER

Plate: 560 IVI

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

## Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

**Customer Details:**

Name: Simplot Grower Solutions

Address: Highway 26 North-West, Meota, Saskatchewan, S0M 1X0

**Vehicle Details:**

VIN: 2AEABRBFXKR000140

Hubometer Reading:

Year: 1989

Vehicle Make/Model: ADVANCE TRAILER TRAILER

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	-installed new light holder for right outside clearance lamp -changed left side tail light assembly and got lights working
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-installed snap ring on 1st axle left slack adjuster -installed new glad hand rubber
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	-pumped up 2nd axle inside tire -pumped up 3rd axle right outside tire
x				Self-Steering Axle (2&4)	
		x		Frame/Crossmembers/Mounts (8)	-welded in new crossmember just below air tank at 3rd axle -welded in crossmember just above 2nd axle -welded left side second support bracket
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

#### Brake/Tire Measurements

##### Axle 1-Pass

---

Wheel1 : Tire Tread Depth: 7 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 52.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 40.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

##### Axle 2-Pass

---

Wheel1 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 37.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 74.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

##### Axle 3-Pass

---

Wheel1 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 74.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 65.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A340511

Inspection Completed Date: 22May2026