



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340512

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

Customer Details:

Name: Simplot Grower Solutions

Address: Highway 26 North-West, Meota, Saskatchewan, S0M 1X0

Inspection Completed Date: 22May2026

Inspection Expiry Date: 31May2027

Vehicle Details:

VIN: 2AEARPAC7LR000167

Hubometer Reading:

Year: 1990

Vehicle Make/Model: ADVANCE TRAILER/TRAILER

Plate: 561 IVI

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340512

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

Customer Details:

Name: Simplot Grower Solutions

Address: Highway 26 North-West, Meota, Saskatchewan, S0M 1X0

Inspection Completed Date: 22May2026

Inspection Expiry Date: 31May2027

Vehicle Details:

VIN: 2AEARPAC7LR000167

Hubometer Reading:

Year: 1990

Vehicle Make/Model: ADVANCE TRAILER/TRAILER

Plate: 561 IVI

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71682	Station Name: Garry's Heavy Equipment Repair
Technician #: 88237	Technician Name: Darcy Poole
Signing Officer #: 88238	Signing Officer Name: Jodie Poole

Customer Details:	
Name: Simplot Grower Solutions	Address: Highway 26 North-West, Meota, Saskatchewan, S0M 1X0

Vehicle Details:	
VIN: 2AEARPAC7LR000167	Hubometer Reading:
Year: 1990	Vehicle Make/Model: ADVANCE TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
		x		Landing Gear (8)	-freed up landing gear
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-installed cam spacer on 2nd axle right side -tightened nut on 2nd axle left brake pot -installed new brake shoes and brake drum on 1st axle right side -changed 2nd axle left cam spacer
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	-changed out 2nd axle right wheel seal -changed out 2nd axle left wheel seal
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
		x		Frame/Crossmembers/Mounts (8)	-welded left tank support between duels -welded crack on right side above fifth wheel bolts
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 86.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Brake Drum/Rotor: 16.538 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 16.566 in • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Brake Drum/Rotor: 16.569 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A340512

Inspection Completed Date: 22May2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.