04082723

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba 704-3

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL NUMBER
Manitoba
C072578

	DAY	MO.	YR.
Date Inspection Started	05	11	16
Date Inspection Completed	06	11	16
Inspection Expiry Date	30	11	17

Station Number: A01061 — Station Name: FORT TRANSPORT — City: ST-A

Mechanic Number: M59913 — Mechanic Signature: [signature] — Station Phone Number: 204-285-9357

Vehicle Owner: STRADA RECYCLING INC

Address — City — Province — Postal Code — Phone

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: CJX10916 — Prov.: MB — NSC #: MB1508393 — Odometer Reading: 150541 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 1FT8W3DT7DEB38716 — Make: FORD — Model: F350 — Year: 2013 — Unit #:

[ ] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

[X] Truck — GVWR: 63501 — KGS — [ ] Truck Tractor — [ ] Trailer — [ ] Semi-Trailer — [ ] Bus — [ ] School Bus — [ ] Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	**Section 1 - Power Train:** Defects (if any) 4-5 - HANGER BEARING WORN
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** (3H) 3A — Defects (if any) — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A B C D (E) Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	.355	.340	1.523	1.505		
2	.348	.314	1.435	1.424		
3						
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		11	11							60	60					
2	11	11	11	11					60	60	60	60				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE