

Prepared By: Joe Chavez

Model	D6NLGP	Job Site	coors Shop		Inspection Date	27Jul26
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	PBA01596	Track Sag (1.80 in - 2.60 in)	1.90 in	2.00 in	Next Inspection Hours	--
Reference Number	430499	Frame Ext (max 4.30 in)	1.50 in	1.71 in	<u>Underfoot Conditions</u>	
Hour Meter Reading	3330	Frame Ext %	35%	40%	Impact	High
Hours Per Week	2.3	Dry Joints	--	--	Abrasion	Moderate
Total Odometer Reading	--	Track Shoe Width	23.60 in	23.60 in	Moisture	Moderate
Forward Odometer	1680 miles	Link Roller System	9%	9%	Packing	Moderate
Reverse Odometer	770 miles				Bushing Allowable Wear	Greater
Distance Per Week	--				Link Allowable Wear	Greater

[illegible]

8	Good	7% (1.72 in)	10% (1.70 in)	--	--	--	--	--	--	--
SPROCKET	Good	18% (8.30 in)	18% (8.30 in)	--	--	--	--	--	--	--

CONDITION: Good

Recommendations

--

Photos
Pre-Inspect



Pre-Inspect



Pre-Inspect





Pre-Inspect



Pre-Inspect
