

REPORT OF THOROUGH EXAMINATION

REPORT NUMBER: JIC- 892078
JOB NUMBER: 11542
EXAMINATION DATE: 11/09/2023

COMPANY DETAILS


COMPANY	Metcalf Cranes	LOCATION	Unit 119 78-82 Freight Drive Somerton Vic 3062
ACCOUNT NUMBER	191		

EQUIPMENT DETAILS

ITEM DESCRIPTION	30t Franna Swivel Hook		
SERIAL NUMBER	499461	LOAD TEST TO	N/A
CATEGORY	Lifting Fittings	WORKING LOAD LIMIT	30 Tonne
CLIENT ASSET NUMBER	N/A	DECOMMISSIONED	NO
AUSTRALIAN STANDARD	AS3776 Lifting Fittings		

INSPECTION RESULTS

Is the equipment safe for use?	YES
Was the examination carried out after the occurrences of exceptional circumstances/follow up?	NO
OTHER DETAILS	

INSPECTOR NAME:	Hadiq Ali	INSPECTION RESULT:  COMPLIES - PASSED
INSPECTOR SIGNATURE:		
NEXT INSPECTION DUE:	11/09/2024	

REPORT OF THOROUGH EXAMINATION

REPORT NUMBER: JIC- 892077
JOB NUMBER: 11542
EXAMINATION DATE: 11/09/2023

COMPANY DETAILS


COMPANY	Metcalf Cranes	LOCATION	Unit 119 78-82 Freight Drive Somerton Vic 3062
ACCOUNT NUMBER	191		

EQUIPMENT DETAILS

ITEM DESCRIPTION	16t Franna Swivel Hook		
SERIAL NUMBER	08.2020.1034	LOAD TEST TO	N/A
CATEGORY	Lifting Fittings	WORKING LOAD LIMIT	16 Tonne
CLIENT ASSET NUMBER	N/A	DECOMMISSIONED	NO
AUSTRALIAN STANDARD	AS3776 Lifting Fittings		

INSPECTION RESULTS

Is the equipment safe for use?	YES
Was the examination carried out after the occurrences of exceptional circumstances/follow up?	NO
OTHER DETAILS	

INSPECTOR NAME:	Hadiq Ali	INSPECTION RESULT:  COMPLIES - PASSED
INSPECTOR SIGNATURE:		
NEXT INSPECTION DUE:	11/09/2024	