




Franna
AT 22
22078
VIC214724
AC A 214724-17
UNIT U84

Note: Anyone can access
the full report when this
QR code is scanned

CraneSafe®
Certificate No. **VIC214724**



Make	Franna	Model	AT 22		
S/N	22078	Insp.	25 May 2026	Next Insp.	25/05/2027
Plant Reg.	NOT AVAILABLE	Plant No.	UNIT U84		
Inspected For	Metcalf Crane Services Pty Ltd				
Assessor	John Carroll	No.		VIC1017	



Supported by



CraneSafe Australia
PO Box 136
MOUNT WAVERLY VIC 3149
p: (03) 9501 0078
e: assessments@cranesafe.com.au

Herewith please find your CraneSafe 'Green Sticker'. Please affix this in a highly visible location on the inside of the Crane Cabin Window to be read from the outside. Make sure the window glass is clean.