

03986359

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920



C057740

Date Inspection Started: DAY 17, MO. 06, YR. 26
 Date Inspection Completed: DAY 17, MO. 06, YR. 26
 Inspection Expiry Date: DAY 30, MO. 06, YR. 27

Station Number: A611610 Station Name: Rolling Hills Repair Aus
 City: _____
 Mechanic Number: M100416 Mechanic Signature: [Signature] Station Phone Number: 204-871-6025
 Vehicle Owner: Norfolk Farms Ltd
 Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

Pass/Safe Vehicle Fail/Unsafe Vehicle Fail/Hazardous
 Licence Number: _____ Prov.: _____ NSC #: _____ Odometer Reading: _____ Odom. Type: km mi
 Vehicle Identification Number: 1W1MCFYA91B2330110 Make: Wilson Model: Hopper Year: 2000 Unit #: _____
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ^{GVWR} 291454 KGS Truck Tractor _____ Trailer _____ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus _____

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
✓		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0.540</td> <td>0.500</td> <td>16.585</td> <td>16.565</td> <td>1.50</td> <td>1.50</td> </tr> <tr> <td>2</td> <td>0.540</td> <td>0.530</td> <td>16.575</td> <td>16.530</td> <td>1.50</td> <td>1.50</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7" style="text-align: center;">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	0.540	0.500	16.585	16.565	1.50	1.50	2	0.540	0.530	16.575	16.530	1.50	1.50	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	0.540	0.500	16.585	16.565	1.50	1.50																																																																			
2	0.540	0.530	16.575	16.530	1.50	1.50																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
✓		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">MM Initial</th> <th colspan="2">Corrected</th> <th colspan="2">PSI Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <td></td> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>10</td> <td>10</td> <td>10</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>10</td> <td>10</td> <td>10</td> <td>10</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				MM Initial		Corrected		PSI Initial		Corrected			L	R	L	R	L	R	L	R	1	10	10	10	10	100	100	100	100	2	10	10	10	10	100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	MM Initial		Corrected		PSI Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	10	10	10	10	100	100	100	100																																																																	
2	10	10	10	10	100	100	100	100																																																																	
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE