

03994023 PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE


 Vehicle Standards and Inspections
 Box 45064 Regent Postal Outlet
 Winnipeg, MB, R2C 5C7
 1-204-985-0920

 DECAL
 VOID WITHOUT DECAL

A970862

 Date Inspection Started: 13 06 25
 Day Mo. YR.
 Date Inspection Completed: 13 06 25
 Day Mo. YR.
 Inspection Expiry Date: 10 06 26
 Day Mo. YR.

 Station Number: A5829 Station Name: 6675760 MB Ltd. Man
 City: Manitoba
 Mechanic Number: M4410 Mechanic Signature: 204 381 4172
 Station Phone Number: 204 381 4172
 Vehicle Owner: TERRIAN TRANSPORT INC.
 Address: 100 1st Street
 City: Brandon
 Province: MB
 Postal Code: N2Z 0A2
 Phone: 204 727 1234

 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

 Licence Number: T002993 Prov. MB NSC #: 1
 Odometer Reading: 1234567890
 Odom. Type: km mi
 Vehicle Identification Number: 1J1JV532R6JL051145 Make: Kubota Model: 180 Year: 18 Unit #: R126
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																										
X		Section 1 - Power Train: Defects (if any)																																																																										
X		Section 2 Suspension: Defects (if any)																																																																										
X		Section 3 - Brake Systems: 3H 3A																																																																										
		Defects (if any) Circle Brake Type																																																																										
		Brake Inspection Type: A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <small>Circle appropriate Letter for Internal Brake Component Inspection</small>																																																																										
		Axle	Lining	Drum/Rotor	Stroke																																																																							
		1	3/4	16,500	16,500																																																																							
		2	3/4	16,500	16,500																																																																							
		3																																																																										
		4																																																																										
		5																																																																										
		Final Measurement																																																																										
		Section 4 - Steering: Defects (if any)																																																																										
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																										
		Section 6 - Lamps: Defects (if any)																																																																										
		Section 7 - Electrical System: Defects (if any)																																																																										
		Section 8 - Body: Defects (if any)																																																																										
		Section 9 - Tire & Wheel: Defects (if any)																																																																										
		<table border="1"> <thead> <tr> <th rowspan="2">Axe</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>12</td> <td>12</td> <td>12</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>2</td> <td>12</td> <td>12</td> <td>12</td> <td>12</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				Axe	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	12	12	12	12	90	90	90	90	2	12	12	12	12	90	90	90	90	3									4									5								
Axe	Tread Depth				Air Pressure																																																																							
	Initial		Corrected		Initial		Corrected																																																																					
	L	R	L	R	L	R	L	R																																																																				
1	12	12	12	12	90	90	90	90																																																																				
2	12	12	12	12	90	90	90	90																																																																				
3																																																																												
4																																																																												
5																																																																												
		Section 10 - Coupling Devices: Defects (if any)																																																																										

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature: _____ Date: _____