

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba



705-1

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0929

DECAL
VOID WITHOUT DECAL

Date Inspection Started DAY: 07 MO: 07 YR: 2013	Station Number A511315	Station Name Wolverine Trd 2007 LTD	City WK
Date Inspection Completed DAY: MO: YR:	Mechanic Number [] [] [] []	Mechanic Signature [Signature]	Station Phone Number 204 325 4966
Inspection Expiry Date DAY: MO: YR:	Vehicle Owner S Line Trucking LTD	Address 1765 Pembina Ave WK/MB R2W1T4	
		City Winnipeg	Province MB
		Postal Code R2W1T4	Phone 204 325 8993

☒ Pass/Safe Vehicle	Licence Number M9ALAT9	Prov. []	NSC # []	Odometer Reading 321568	Odom. Type ☒ km ☐ mi
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 1HTMMAAMX1DH436486	Make I.N.	Model 4300	Year 2013	Unit # 201
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
	☒	Section 1 - Power Train: Defects (if any) <u>3-B Emissions Have Been Deleted</u>																																																																						
☒		Section 2 Suspension: Defects (if any)																																																																						
☒		Section 3 - Brake Systems: <u>3H 3A</u> Defects (if any) <u>Circle Brake Type</u>																																																																						
		Brake Inspection Type: A B C <u>D</u> E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3/4</td> <td>3/4</td> <td>1.517</td> <td>1.500</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>3/4</td> <td>3/4</td> <td>1.495</td> <td>1.498</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/4	3/4	1.517	1.500			2	3/4	3/4	1.495	1.498			3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	3/4	3/4	1.517	1.500																																																																				
2	3/4	3/4	1.495	1.498																																																																				
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
☒		Section 4 - Steering: Defects (if any)																																																																						
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
☒	☒	Section 6 - Lamps: Defects (if any) <u>1-K Backup Lights Not Working</u> <u>1-I 2 clean lights on Cab roof</u>																																																																						
☒		Section 7 - Electrical System: Defects (if any)																																																																						
☒		Section 8 - Body: Defects (if any)																																																																						
☒		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td>12 11</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>13 14</td> <td>14 14</td> <td></td> <td></td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1		12 11			100	100			2	13 14	14 14			100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1		12 11			100	100																																																																		
2	13 14	14 14			100	100	100	100																																																																
3																																																																								
4																																																																								
5																																																																								
☒		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -