

04104853

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 45064 Regent Postal Outlet Winnipeg, MB, R2C 5G7 1-204-985-0920



C030958

Date Inspection Started: 20 01 26
Date Inspection Completed: 26 01 26
Inspection Expiry Date: 31 01 27

Station Number: A2019
Station Name: R Lewandoski Farms
Mechanic Number: M9415
Mechanic Signature: [Signature]
Station Phone Number: 204-585-2120
Vehicle Owner: Peter Higgott

Pass/Safe Vehicle [X]
Licence Number: TIF8426
Prov: MB
NSC #:
Odometer Reading:
Odom. Type: km [] mi []
Vehicle Identification Number: 2L1DAH3023CLV0541166
Make: LODE KING
Model: Crown
Year: 12'
Unit #:
Confirmed legible Vehicle Identification Number on vehicle [X]

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck [] GVWR [] KGS []
Truck Tractor [] Trailer [] Semi-Trailer [X] Bus [] School Bus [] Coach Bus []

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Table with 2 columns: P, R. Rows for Section 1-10. Section 3 includes Brake Inspection Type table and Brake Inspection table. Section 10 includes Tread Depth and Air Pressure tables.

Brake Inspection Type: A B C D E
mm Lining Drum/Rotor Stroke
Axle L R L R L R
1 18 18 16.510 16.540 1.5 1.5
2 15 12 16.550 16.545 1.5 1.5

mm Tread Depth Air Pressure
Initial Corrected Initial Corrected
Axle L R L R L R L R
1 11 10 13 13 105 105 105 105
2 13 12 9 11 105 105 105 105

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: Original decal number # A976582 replacement certificate

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
Vehicle received without repairs by: Signature Date:

Station (Lat/Long): A 2011 P
 Metering Number: M P 4112
 Vehicle Number: Peter Higdon
 Inspection Started: 30 01 22
 Inspection Completed: 26 01 26
 Inspection Expiry: 31 01 27

Vehicle Make: KIA
 Model: K5
 Year: 2012
 Registration: 2-DAH3023C-V054186
 License: TB 28426
 Insured: Yes
 Taxed: Yes

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORISED FOR CLASS OF VEHICLE INSPECTED
 Truck Tractor School Bus Coach Bus

Section	Inspected	Defects
Section 1 - Power Train (Defects in any)	<input checked="" type="checkbox"/>	
Section 2 - Brakes (Defects in any)	<input checked="" type="checkbox"/>	
Section 3 - Brake System (Defects in any)	<input checked="" type="checkbox"/>	
Section 4 - Steering (Defects in any)	<input checked="" type="checkbox"/>	
Section 5 - Instruments & Auxiliary Equipment (Defects in any)	<input checked="" type="checkbox"/>	
Section 6 - Lamps (Defects in any)	<input checked="" type="checkbox"/>	
Section 7 - Electrical System (Defects in any)	<input checked="" type="checkbox"/>	
Section 8 - Body (Defects in any)	<input checked="" type="checkbox"/>	
Section 9 - Tyre & Wheel (Defects in any)	<input checked="" type="checkbox"/>	
Section 10 - Coupling Device (Defects in any)	<input checked="" type="checkbox"/>	

THIS INSPECTION IS NOT A WARRANTY
 The inspector, alongside of safety and repair, will inspect the vehicle and issue a certificate of fitness if the vehicle is found to be fit for use.
 The inspector will not be responsible for any damage to the vehicle or its contents during the inspection.
 Original decal number: # 9170582
 Replacement certificate