03986426 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C057826

Date Inspection Started	25 DAY	03 MO.	26 YR.	Station Number A5819	Station Name ASSINIBOINE INJECTIONS City
Date Inspection Completed	01 DAY	04 MO.	26 YR.	Mechanic Number M9459	Mechanic Signature Station Phone Number 749-2123.
Inspection Expiry Date	30 DAY	04 MO.	27 YR.	Vehicle Owner ASSINIBOINE INJECTIONS LTD.	
				Address Box 160	City NOTRE DAME Province MB Postal Code ROG 1N0 Phone 248-2559.

[X] Pass/Safe Vehicle
[X] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number CIH0468 19 Prov. MB. NSC # MB9880350 Odometer Reading 1.040.649 Odom. Type [X] km [ ] mi

Vehicle Identification Number 1XKDAP9X2FJ972768 Make KW. Model T800 Year 15 Unit # T8.

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR 23587 KGS __X__Truck Tractor ____Trailer ____Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	**Section 1 - Power Train:** Defects (if any) X-2D EXHAUST BOTTOM FLEX PIPE LEAKING
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) X-3C 4H MUD FLAP REFLECTIVE TAPE PEELING
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) X-13B BOTH WINDSHIELD CRACK NONE THAN 50MM. X-18D R/H CONVEX MINNOR CONDITION ON GLASS
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	3/4	3/4			1 1/4	1 1/4
2	9/16	13/16		16.5/10	1 1/2	1 1/2
3	13/16	13/16	16.5/10	16.5/10	1 1/2	1 1/2
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		15/32	15/32							100	100					
2	21/32	21/32	21/32	21/32					100	100	100	100				
3	21/32	21/32	21/32	21/32					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE

20372138 MCC ©2023. All rights reserved. — 9355