

104038670

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



V06-4

Vehicle Standards and Inspections
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
VOID WITHOUT DECAL

Manitoba



C041703

Date Inspection Started: DAY 29, MO. 05, YR. 2006
Date Inspection Completed: DAY 03, MO. 06, YR. 2006
Inspection Expiry Date: DAY 31, MO. 06, YR. 2007

Station Number: A6224, Station Name: Wildwood Transport Inc., City: [blank]
Mechanic Number: M8687, Mechanic Signature: [blank], Station Phone Number: 204-957-8877
Vehicle Owner: Brauning Trucking Inc., Address: Box 393, City: Virda, Province: MB, Postal Code: R0A 2H0, Phone: 204-301-4726

Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☒ Fail/Hazardous ☐
Licence Number: C92224, Prov.: MB, NSC #: M0987994, Odometer Reading: 705431, Odom. Type: km ☒ mi ☐
Vehicle Identification Number: 1XAB0P920L0689080, Make: P.D., Model: 579, Year: 20, Unit #: 630
Confirmed legible Vehicle Identification Number on vehicle ☒

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☒ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus ☐

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
		Section 1 - Power Train: Defects (if any)																																																																							
X	X	Section 2 Suspension: Defects (if any) 5-B - RRD air spring cut 7-C - RRD shock leaking																																																																							
X	X	Section 3 - Brake Systems: 3H 3A 14-6 Defects (if any) Circle Brake Type - RRD brake pot brake spring																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>17</td><td>17</td><td>43.01</td><td>43.28</td><td></td><td></td></tr><tr><td>2</td><td>16</td><td>16</td><td>42.94</td><td>42.91</td><td></td><td></td></tr><tr><td>3</td><td>16</td><td>16</td><td>42.68</td><td>42.70</td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	17	17	43.01	43.28			2	16	16	42.94	42.91			3	16	16	42.68	42.70			4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	17	17	43.01	43.28																																																																					
2	16	16	42.94	42.91																																																																					
3	16	16	42.68	42.70																																																																					
4																																																																									
5																																																																									
Final Measurement																																																																									
		Section 4 - Steering: Defects (if any)																																																																							
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
		Section 6 - Lamps: Defects (if any)																																																																							
		Section 7 - Electrical System: Defects (if any)																																																																							
		Section 8 - Body: Defects (if any)																																																																							
		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="4">Tread Depth mm</th><th colspan="4">Air Pressure PSI</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th></th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>13</td><td>12</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>2</td><td>19</td><td>20</td><td>5</td><td>6</td><td>90</td><td>90</td><td>90</td><td>90</td></tr><tr><td>3</td><td>7</td><td>7</td><td>8</td><td>8</td><td>90</td><td>90</td><td>90</td><td>90</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth mm				Air Pressure PSI				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	13	12			100	100			2	19	20	5	6	90	90	90	90	3	7	7	8	8	90	90	90	90	4									5								
Axle	Tread Depth mm				Air Pressure PSI																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	13	12			100	100																																																																			
2	19	20	5	6	90	90	90	90																																																																	
3	7	7	8	8	90	90	90	90																																																																	
4																																																																									
5																																																																									
		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: - all repairs - performed

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature _____ Date: _____