

04058929

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



W01-4

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



04058929

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



W01-4

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C090631

Date Inspection Started DAY: 24 MO: 04 YR: 26	Station Number A11138	Station Name Red River College	City Winnipeg
Date Inspection Completed DAY: 30 MO: 04 YR: 26	Mechanic Number M72105	Mechanic Signature 	Station Phone Number 204-697-5930
Inspection Expiry Date DAY: 30 MO: 04 YR: 27	Vehicle Owner 4885814 Manitoba Ltd		
Address _____ City _____ Province _____ Postal Code _____ Phone _____			
☒ Pass/Safe Vehicle	Licence Number TD2525	Prov. MB	NSC # _____
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 5V8NVC5322HM700398	Make Vanguard	Model Van
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle	Year 17	Unit # FF5330
Odometer Reading _____		Odom. Type km ☐ mi ☐	

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
☒		Section 1 - Power Train: Defects (if any)																																																																							
☒	☒	Section 2 Suspension: Defects (if any) <u>7C- All shocks leaking</u>																																																																							
☒		Section 3 - Brake Systems: 3H <u>3A</u> Defects (if any) _____ Circle Brake Type _____ Brake Inspection Type: A <u>B</u> C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>9/16</td> <td>6520</td> <td>6528</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>2</td> <td>11/16</td> <td>9/16</td> <td>6547</td> <td>6535</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	9/16	6520	6528	1"	1"	2	11/16	9/16	6547	6535	1"	1"	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	11/16	9/16	6520	6528	1"	1"																																																																			
2	11/16	9/16	6547	6535	1"	1"																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
☒		Section 4 - Steering: Defects (if any)																																																																							
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
☒	☒	Section 6 - Lamps: Defects (if any) <u>1C- Rt. tail light out</u>																																																																							
☒		Section 7 - Electrical System: Defects (if any)																																																																							
☒	☒	Section 8 - Body: Defects (if any) <u>5J - Corrosion on front panels</u>																																																																							
☒		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7</td> <td>6</td> <td>8</td> <td>7</td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>6</td> <td>6</td> <td>19</td> <td>19</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	7	6	8	7	100	100			2	6	6	19	19					3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	7	6	8	7	100	100																																																																			
2	6	6	19	19																																																																					
3																																																																									
4																																																																									
5																																																																									
☒		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Date: