

03975443

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



W04-1.

Vehicle Standards and Ins
Box 45064 Regent Postal O
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



A861537

Date Inspection Started 24 DAY 04 MO. 25 YR.

Date Inspection Completed 26 DAY 04 MO. 25 YR.

Inspection Expiry Date 30 DAY 04 MO. 26 YR.

Station Number A5101 Station Name Valley Farm & Lumber City 842

Mechanic Number M10567 Mechanic Signature Ken Taylor Station Phone Number 5173

Vehicle Owner 5769371 Manitoba Ltd. Address SE 4-17-26 City Birtle Province MB Postal Code R0M 0C0 Phone 723 6870

☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous

Licence Number PAM059 Prov. MB NSC # 1204037 Odometer Reading 1034045 Odom. Type ☒ km ☐ mi

Vehicle Identification Number 1M1AW07459N006617 Make MAZDA Model CRUEL Year 2009 Unit #

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck 42500 KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
☒		Section 1 - Power Train: Defects (if any)
☒	☒	Section 2 Suspension: Defects (if any) <u>2.4h suspension wear pads worn.</u>
☒	☒	Section 3 - Brake Systems: <u>3H</u> <u>3A</u> Defects (if any) <u>3A8c ABS relay valve leaking.</u>
☒		Section 4 - Steering: Defects (if any)
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
☒	☒	Section 6 - Lamps: Defects (if any) <u>6.1h license plate light not working</u>
☒		Section 7 - Electrical System: Defects (if any)
☒		Section 8 - Body: Defects (if any)
☒	☒	Section 9 - Tire & Wheel: Defects (if any) <u>9.4h low tire pressures</u> <u>9.6a wheel bearing loose left side.</u>
☒		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure				
	Initial mm		Corrected		Initial		Corrected		
	L	R	L	R	L	R	L	R	
1					85	85		100	100
2	9	10	10	9	90	85	90	100	100
3	11	12	12	10	95	85	90	100	100
4									
5									

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not