04144568

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outle
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba C100209

	DAY	MO.	YR.
Date Inspection Started	27	10	26
Date Inspection Completed	28	10	26
Inspection Expiry Date	31	10	27

Station Number: A3017 Station Name: Lucky Star Wash & Son City:

Mechanic Number: M10196 Mechanic Signature: Station Phone Number: 204-571-1531

Vehicle Owner: Renaissance Transport LTD

Address: S.E 15 Box 46 RR1 City: Brandon Province: MB Postal Code: R7A 5Y1 Phone:

- [x] Pass/Safe Vehicle
- [x] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: 43704H Prov.: MB NSC #: N/A Odometer Reading: N/A Odom. Type: km mi

Vehicle Identification Number: 7PWRT199 Make: Wes Tann Model: Tanker Year: 1979 Unit #: 0004P

- [x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer _X_Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Circle Brake Type. Defects (if any)
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) X-1H-Side marker light inoperative X-1L-RHS Rear Signal light inoperative
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) X-SC-3 hub cap has been pried on.
V		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	9	8	16.513	16.571	1½	1½
2	11	12	16.537	16.556	1½	1½
3		16"				
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	10	8	10	8					100	100	100	100				
2	13	12	11	10					100	100	100	100				
3																
4		32"														
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION