04144562

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba C100203

Date Inspection Started: DAY 22 MO. 10 YR. 26

Date Inspection Completed: DAY 23 MO. 10 YR. 26

Inspection Expiry Date: DAY 31 MO. 10 YR. 27

Station Number: A30117 Station Name: Luckystar Wash & Service City:

Mechanic Number: M10220 Mechanic Signature: [signature] Station Phone Number: 204-571-1531

Vehicle Owner: Renaissance transport LTD

Address: Site 145 Box 46 RR1 City: Brandon Province: MB Postal Code: R7A 5Y1 Phone:

- [x] Pass/Safe Vehicle
- [x] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: N/A Prov.: N/A NSC #: N/A Odometer Reading: N/A Odom. Type: km mi

Vehicle Identification Number: 7HDWR1110 Make: Wes tank Model: Tanker Year: 1970 Unit #: A008

[x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS ____Truck Tractor ____Trailer ✓ Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P = Pass, R = Rejected. Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
✓		**Section 1 - Power Train:** Defects (if any)
✓		**Section 2 Suspension:** Defects (if any)
✓		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
✓		**Section 4 - Steering:** Defects (if any)
✓		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
✓	✓	**Section 6 - Lamps:** Defects (if any) X-1C-LHS outter tail lamp inoperative X-13-rear identification lamps inoperative
✓		**Section 7 - Electrical System:** Defects (if any)
✓		**Section 8 - Body:** Defects (if any)
✓		**Section 9 - Tire & Wheel:** Defects (if any)
✓		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	8	9	16.549	16.581	1½	1½
2	8	11	16.545	16.534	1½	1½
3		16"				
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
1	6	6	7	7					100	100	100	100				
2	7	7	15	16					100	100	100	100				
3		32"														
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION