



Vehicle Standards and Inspection

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

U005-12

Decal # A341057

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:	
Name: Stoney Lake Transport	Address: Box 818, Big River, Saskatchewan, S0J 0E0

Inspection Completed Date: 12May2026	Inspection Expiry Date: 31May2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2PLB02823DBC16202	Hubometer Reading:
Year: 2013	Vehicle Make/Model: PEERLESS TRAILER/TRAILER
Plate: 437 NBJ	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.
-------------------------------------

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:

Name: Stoney Lake Transport	Address: Box 818, Big River, Saskatchewan, S0J 0E0
-----------------------------	--

Vehicle Details:

VIN: 2PLB02823DBC16202	Hubometer Reading:
Year: 2013	Vehicle Make/Model: PEERLESS TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 90.0 degrees • Brake Stroke: 28 mm

Wheel2-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 90.0 degrees • Brake Stroke: 28 mm

Wheel3-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 10 mm • Cam Rotation: 125.0 degrees • Brake Stroke: 28 mm

Wheel4-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 10 mm • Cam Rotation: 125.0 degrees • Brake Stroke: 28 mm

**Axle 2-Pass**

Wheel1-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 12.5 mm • Cam Rotation: 105.0 degrees • Brake Stroke: 28 mm

Wheel2-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 12.5 mm • Cam Rotation: 105.0 degrees • Brake Stroke: 28 mm

Wheel3-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 10 mm • Cam Rotation: 125.0 degrees • Brake Stroke: 28 mm

Wheel4-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 10 mm • Cam Rotation: 125.0 degrees • Brake Stroke: 28 mm

PASS - vehicle passes inspection

Decal # A341057

Inspection Completed Date: 12May2026