



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A341062

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:	
Name: DC North Contracting Ltd.	Address: Box 818, Big River, Saskatchewan, S0J 0E0

Inspection Completed Date: 20May2026	Inspection Expiry Date: 30Nov2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1NKZX4EX9KJ958405	Odometer Reading: 369471 km
Year: 2019	Vehicle Make/Model: KENWORTH/HEAVY VEHICLE
Plate: DCN 9	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.
--

0-000



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71928	Station Name: Clarence Reimer's Garage Ltd.
Technician #: 85631	Technician Name: Clarence Reimer
Signing Officer #: 82605	Signing Officer Name: Pamela Bogner

Customer Details:	
Name: DC North Contracting Ltd.	Address: Box 818, Big River, Saskatchewan, S0J 0E0

Vehicle Details:	
VIN: 1NKZX4EX9KJ958405	Odometer Reading: 369471 km
Year: 2019	Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
		x		Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 32.0 degrees • Brake Stroke: 22 mm

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Cam Rotation: 32.0 degrees • Brake Stroke: 22 mm

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15.5 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 21 mm

Wheel2-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15.5 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 21 mm

Wheel3-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15.5 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 21 mm

Wheel4-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15.5 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 21 mm

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 78.0 degrees • Brake Stroke: 21 mm

Wheel2-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 78.0 degrees • Brake Stroke: 21 mm

Wheel3-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 21 mm

Wheel4-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 21 mm

Axle 4-Pass

Wheel1-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 21 mm

Wheel2-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 21 mm

Wheel3-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 21 mm

Wheel4-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 80.0 degrees • Brake Stroke: 21 mm

PASS - vehicle passes inspection

Decal # A341062

Inspection Completed Date: 20May2026